DroneCore.Pilot peripherals block diagram Connectors CSI F **GPIOS** ADC BAT_SENS I2C MIPI CSI MIPI CSÍ PWM1 FAN1+FAN2 (Jetson) PWM2 **Nvidia Jetson** Flight controller unit **ETHERNET** GPS1 HDMI USB 2.0 SDMMC GPS2 IMU + BARO USB 3.0 **HDMI** USB 2.0 I2C PCIE SERIAL5 USB 2.0 USB 3.0 HUB MICRO SD airvolute DEV 80-pin B2B