
Waiting
LIN=0
Counter:=0
LIN=0 AND Counter=N/2
Counter:=0;
Counter<13N AND
LIN=1
Synchro_0
Reception
Counter++;
InternalState.ErrorSynchro:=1
LIN=1 AND Counter >=13N
Counter:=0;
Counter<N AND
LIN=0
Synchro_1
Reception
Counter++;
InternalState.ErrorSynchro:=1
Counter >=N AND
LIN=1
Waiting
Synchro Field