

TTS PRO REPORT

Basic Electrical Equipment Test Report

Source	PADFX tester export
Description	
Generated	05/06/2026

Total	224	Passed	223	Failed	1
-------	-----	--------	-----	--------	---

PRO REPORT - TEST REGISTER

RESULTS SUMMARY

Appliance ID	Type	Location	Test Date	Retest Date	Status	Test Summary
AT2005	TOASTER	CAL ROOM	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.17 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
0003	Red IEC Lead	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
AT2010-PH3	3 Phase RCD	CAL Room	20/07/2023	19/07/2024	Pass	RCD: (+) ,t IΔN x1 : 25.6 ms (-) ,t IΔN x1 : 35.9 ms
AT2011	RCD	CAL Room	25/07/2023	24/07/2024	Pass	RCD: (+) ,t IΔN x1 : 40.0 ms (-) ,t IΔN x1 : 29.5 ms
RCD002	RCD 15 A	CAL Room	25/07/2023	24/07/2024	Pass	RCD: (+) ,t IΔN x1 : 9.3 ms (-) ,t IΔN x1 : 18.9 ms
TTS00018	Power Board	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00022	IEC Lead	CAL Room	18/07/2022	18/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00023	Oscilloscope	CAL Room	18/07/2022	18/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.20 mA Limit : 5.00 mA S : 0.04...
TTS00028	Power Board	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Polarity: Fault : 1; Differential Leakage: Idiff : 0.06 mA Limit...
TTS00037	DESK POWERBOARD	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00040	Transformer	CAL Room	18/07/2022	18/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.12 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00072	IEC Lead	CAL Room	29/01/2025	29/01/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00099	C6 IEC Lead	CAL Room	21/07/2023	20/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00101	Seaward lead	CAL Room	10/02/2025	10/02/2026	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.02 mA Limit : 5.00 mA S : 0.00 kVA
TTS00112	Kyoritsu Lead	CAL Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.02 mA Limit : 5.00 mA S : 0.00 kVA
TTS00116	Var Tx	CAL Room	18/07/2022	18/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.15 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00117	Figure 8 Lead	CAL Room	22/07/2022	22/07/2023	Pass	Visual Inspection: Result : 0
TTS00126	CT Test Box	CAL Room	22/07/2022	22/07/2023	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00127	IEC Lead	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00128	Service PC	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.08 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00129	IEC Lead	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00130	Monitor PSU	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.07 mA Limit : 5.00 mA S : 0.01 kVA

Appliance ID	Type	Location	Test Date	Retest Date	Status	Test Summary
TTS00164	Fig 8 Lead	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0
TTS00165	Metrel Charger	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.14 mA Limit : 1.00 mA S : 0.00 kVA
TTS00197	Red IEC Lead	CAL Room	05/02/2025	05/02/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00199	Cal Box Lead	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00232	IEC lead	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00233	DMM 6500	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.07 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.04 mA Limit : 5.00 mA S : 0.05...
TTS00253	IEC Lead RH	CAL Room	29/01/2025	29/01/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00253	Kyoritsu Lead	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.01 mA Limit : 1.00 mA S : 0.00 kVA
TTS00254	Cal Box	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.03 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.12 mA Limit : 5.00 mA S : 0.02...
TTS00255	RCD Portable	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.04 mA Limit : 1.00 mA S : 0.00...
TTS00305	IEC Lead	CAL Room	29/01/2025	31/07/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS0285	Extension lead	CAL Room	05/02/2025	07/08/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS169	RCD	CAL Room	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.03 mA Limit : 1.00 mA S : 0.00...
TTS8003	Red IEC Lead	CAL Room	05/02/2025	05/02/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00065	Microwave	Kitchen	21/07/2023	20/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.06 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.27 mA Limit : 5.00 mA S : 1.27...
TTS00067	Sandwich toast	Kitchen	21/07/2023	20/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.11 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00070	RCD	Kitchen	25/07/2023	24/07/2024	Pass	RCD: (+) ,t IΔN x1 : 8.3 ms (-) ,t IΔN x1 : 17.3 ms
TTS00178	Fridge	Kitchen	21/07/2023	20/01/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.07 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.06 mA Limit : 5.00 mA S : 0.11...
TTS00271	Urn	Kitchen	20/07/2023	19/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.16 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS0044	Fridge	Kitchen	19/01/2021	19/01/2022	Fail	Visual Inspection: Result : 0; Earth Continuity: R : >1999 Ohm Limit : 1.00 Ohm Riso : --- MOhm Limit : 1 MOhm
TTS0091	Urn	Kitchen	18/07/2022	18/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.82 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS1008	Coffee Machine	Kitchen	20/07/2023	19/07/2024	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.03 mA Limit : 5.00 mA S : 0.01 kVA

Appliance ID	Type	Location	Test Date	Retest Date	Status	Test Summary
rcd2	IEC lead	Kitchen	19/04/2024	19/04/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.14 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00140	EFTPOS Charger	Reception	18/07/2022	18/07/2023	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00202	IEC Lead	Reception	21/07/2023	20/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00203	Dell PC	Reception	21/07/2023	20/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.11 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00204	Power board	Reception	21/07/2023	20/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS0220	HP Printer	Reception	21/07/2023	20/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.14 mA Limit : 5.00 mA S : 0.01...
TTS2020	IEC Lead	Reception	21/07/2023	20/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
RCD003	RCD	Show Room	25/07/2023	24/07/2024	Pass	RCD: (+) ,t IΔN x1 : 5.7 ms (-) ,t IΔN x1 : 15.6 ms
TTS001	Scan Charger	Show Room	23/06/2021	23/12/2021	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.14 mA Limit : 1.00 mA S : 0.00 kVA
TTS00110	Lead figure 8	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0
TTS00118	IEC lead	Show Room	29/01/2025	29/01/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00123	IEC Lead	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00124	RCD Portable	Show Room	20/07/2023	19/01/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.03 mA Limit : 1.00 mA S : 0.00...
TTS00141	IEC Lead	Show Room	18/07/2022	17/01/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00142	Printer Charger	Show Room	18/07/2022	17/01/2023	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.19 mA Limit : 5.00 mA S : 0.01 kVA
TTS00143	Seaward Lead	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00145	IEC Lead	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00146	Printer Charger	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.04 mA Limit : 5.00 mA S : 0.00 kVA
TTS00149	Blue IEC Lead	Show Room	21/07/2023	20/01/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00150	Orange IEC Lead	Show Room	21/07/2023	20/01/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00152	Battery Charger	Show Room	15/02/2023	15/02/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.01 mA Limit : 1.00 mA S : 0.00 kVA
TTS00153	Fig 8 Lead	Show Room	15/02/2023	15/02/2024	Pass	Visual Inspection: Result : 0
TTS00154	Power Supply	Show Room	15/02/2023	15/02/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.14 mA Limit : 1.00 mA S : 0.00 kVA
TTS00167	Battery Charger	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.05 mA Limit : 1.00 mA S : 0.00 kVA

Appliance ID	Type	Location	Test Date	Retest Date	Status	Test Summary
TTS00179	Iso Tx	Show Room	20/07/2023	19/01/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.13 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00182	Iso Tx	Show Room	21/07/2023	20/07/2024	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.04 mA Limit : 5.00 mA S : 0.01 kVA
TTS00185	Red IEC Lead	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00188	Figure 8 Lead	Show Room	23/06/2021	23/12/2021	Pass	Visual Inspection: Result : 0
TTS00218	Power Supply	Show Room	15/02/2023	15/02/2024	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.14 mA Limit : 1.00 mA S : 0.01 kVA
TTS00219	RCD	Show Room	25/07/2023	24/07/2024	Pass	RCD: (+) ,t IΔN x1 : 8.4 ms (-) ,t IΔN x1 : 17.1 ms
TTS00220	C6 IEC Lead	Show Room	10/02/2025	12/08/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00221	Kyoritsu Lead	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00222	Scan Charger	Show Room	21/07/2023	20/07/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.03 mA Limit : 1.00 mA S : 0.00 kVA
TTS00223	Phone Charger	Show Room	15/02/2023	15/02/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00223	Phone Charger	Show Room	18/07/2022	17/01/2023	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00224	Kyoritsu Lead	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.06 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00225	Phone Charger	Show Room	20/07/2022	19/01/2023	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00226	Phone Charger	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00227	Power Board	Show Room	21/07/2021	20/01/2022	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Polarity: Fault : 1; Differential Leakage: Idiff : 0.03 mA Limit...
TTS00228	Power Board	Show Room	04/02/2025	06/08/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Polarity: Fault : 1; Differential Leakage: Idiff : 0.02 mA Limit...
TTS00229	Power Supply	Show Room	10/02/2025	10/02/2026	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.05 mA Limit : 1.00 mA S : 0.00 kVA
TTS00230	Television	Show Room	10/02/2025	10/02/2026	Pass	Visual Inspection: Result : 0; Insulation-P: Riso-S : >200 MOhm Limit : 1 MOhm
TTS00235	Phone Charger	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00244	IEC Lead	Show Room	15/02/2023	15/02/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00247	Charger	Show Room	15/02/2023	15/02/2024	Pass	Visual Inspection: Result : 0; Insulation: Riso : 73.7 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.05 mA Limit : 1.00 mA S : 0.01 kVA
TTS00250	IEC Lead LH	Show Room	05/02/2025	05/02/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00251	IEC Lead RH	Show Room	20/07/2023	19/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00267	Power Board	Show Room	10/02/2025	10/02/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Polarity: Fault : 1; Differential Leakage: Idiff : 0.05 mA Limit...

Appliance ID	Type	Location	Test Date	Retest Date	Status	Test Summary
TTS00268	Power Board	Show Room	10/02/2025	10/02/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00269	Phone Charger	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00272	Charger	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00273	Tx	Show Room	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.03 kVA
TTS00274	Charger	Show Room	21/07/2023	20/07/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.01 mA Limit : 1.00 mA S : 0.01 kVA
TTS003	Printer Charger	Show Room	23/06/2021	23/12/2021	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.14 mA Limit : 1.00 mA S : 0.01 kVA
TTS00307	Toaster	Show Room	04/02/2025	06/08/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.11 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00308	Iron	Show Room	04/02/2025	06/08/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS0074	Red IEC Lead	Show Room	05/02/2025	05/02/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS0088	IEC Lead	Show Room	21/07/2023	20/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS0089	IEC Lead	Show Room	29/01/2025	29/01/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS1003	SEW Lead	Show Room	05/02/2025	05/02/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.08 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS2011	Instaltest Lead	Show Room	05/02/2025	05/02/2026	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.02 mA Limit : 5.00 mA S : 0.00 kVA
TTS8014	Red IEC Lead	Show Room	20/07/2023	19/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS8015	RCD Portable	Show Room	04/02/2025	06/08/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.01 mA Limit : 1.00 mA S : 0.00...
TTS00171	C6 IEC Lead	Showroom	15/02/2023	15/02/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
AT2010-PH1	3 Phase RCD	WAREHOUSE	25/07/2023	24/07/2024	Pass	RCD: (+) ,t IΔN x1 : 25.7 ms (-) ,t IΔN x1 : 35.8 ms
RCD001	RCD Cal bench	WAREHOUSE	25/07/2023	24/07/2024	Pass	RCD: (+) ,t IΔN x1 : 26.3 ms (-) ,t IΔN x1 : 35.0 ms
TTS00047	IEC lead	WAREHOUSE	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.05 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00071	METREL 2121	WAREHOUSE	23/09/2022	23/09/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00100	Zebra PSU	WAREHOUSE	21/07/2023	20/07/2024	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.19 mA Limit : 5.00 mA S : 0.00 kVA
TTS00109	Fume Extractor	WAREHOUSE	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.07 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm

Appliance ID	Type	Location	Test Date	Retest Date	Status	Test Summary
TTS00190	15A IEC	WAREHOUSE	06/01/2021	05/01/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00192	PSU	WAREHOUSE	06/01/2021	05/01/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.08 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.18 mA Limit : 5.00 mA S : 0.00...
TTS00193	IEC lead	WAREHOUSE	06/01/2021	05/01/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00194	Modem PSU	WAREHOUSE	06/01/2021	05/01/2026	Pass	Visual Inspection: Result : 0; Insulation-P: Riso-S : >200 MOhm Limit : 1 MOhm
TTS00195	IEC lead	WAREHOUSE	06/01/2021	05/01/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00248	IEC Lead	WAREHOUSE	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00264	Figure 8 Lead	WAREHOUSE	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0
TTS00265	Printer PSU	WAREHOUSE	11/01/2024	11/07/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.06 mA Limit : 1.00 mA S : 0.01 kVA
TTS00278	Mini PC PSU	WAREHOUSE	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.06 mA Limit : 1.00 mA S : 0.00 kVA
TTS01001	IEC Lead	WAREHOUSE	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.05 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS01003	POWER BOARD	WAREHOUSE	29/01/2025	31/07/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.03 mA Limit : 5.00 mA S : 0.00...
TTS01003	AA BATT CHARGER	WAREHOUSE	29/01/2025	31/07/2025	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.07 mA Limit : 1.00 mA S : 0.00 kVA
TTS168	Programme PSU	WAREHOUSE	19/07/2022	19/07/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.19 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.63 mA Limit : 5.00 mA S : 0.16...
TTS170	Laminator	WAREHOUSE	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Insulation-P: Riso-S : >200 MOhm Limit : 1 MOhm
0001	Charger	Warehouse	20/07/2022	19/01/2023	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.15 mA Limit : 1.00 mA S : 0.01 kVA
0002	Charger	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.01 mA Limit : 1.00 mA S : 0.00 kVA
00370	IEC Lead	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.03 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
8001	Drill	Warehouse	15/05/2024	15/05/2025	Pass	Visual Inspection: Result : 0; Insulation-P: Riso-S : >200 MOhm Limit : 1 MOhm
AT2000	Battery Charger	Warehouse	04/02/2025	06/08/2025	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.05 mA Limit : 1.00 mA S : 0.00 kVA
AT2002	SEW Lead	Warehouse	05/02/2025	07/08/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
AT2004	Heat Gun	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Insulation-P: Riso-S : >200 MOhm Limit : 1 MOhm
AT2009	IEC Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TT012350	IEC Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.04 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TT012353	SEW Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.04 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1

Appliance ID	Type	Location	Test Date	Retest Date	Status	Test Summary
TTS00003	Scales	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.02 mA Limit : 1.00 mA S : 0.00 kVA
TTS00008	Electric Knife	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Insulation-P: Riso-S : >200 MOhm Limit : 1 MOhm
TTS00010	Extension lead	Warehouse	04/02/2025	06/08/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00011	IEC Lead	Warehouse	17/01/2022	19/07/2022	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00012	Solder Station	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.03 mA Limit : 5.00 mA S : 0.10...
TTS00013	Flouro Lamp	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00014	Lamp	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.01 mA Limit : 1.00 mA S : 0.01 kVA
TTS00015	Solder Station	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.27 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.26 mA Limit : 5.00 mA S : 0.32...
TTS00026	IEC Lead	Warehouse	20/07/2022	19/01/2023	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00027	Computer PSU	Warehouse	20/07/2022	19/01/2023	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.02 mA Limit : 5.00 mA S : 0.00 kVA
TTS00033	IEC lead	Warehouse	04/02/2025	06/08/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00038	Desk Powerboard	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.03 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00039	Extension Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00041	Drill Press	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.19 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00046	IEC Lead	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.06 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00048	IEC Lead	Warehouse	12/01/2024	11/01/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00050	IEC lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00051	Label Printer	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.12 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00051	Label Printer	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.11 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00053	Label Printer	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.30 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00054	Monitor	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.28 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00059	Charger	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.01 kVA

Appliance ID	Type	Location	Test Date	Retest Date	Status	Test Summary
TTS00064	Vacuum Cleaner	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Insulation-P: Riso-S : >200 MOhm Limit : 1 MOhm
TTS00104	Extension Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00105	IEC Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.04 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00106	IEC Lead	Warehouse	17/01/2022	19/07/2022	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00115	Phone Charger	Warehouse	29/01/2025	31/07/2025	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00125	Fig 8 Lead	Warehouse	29/01/2025	31/07/2025	Pass	Visual Inspection: Result : 0
TTS00131	Laminator	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Insulation-P: Riso-S : >200 MOhm Limit : 1 MOhm
TTS00132	Phone Charger	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00133	IEC Lead	Warehouse	12/01/2024	11/01/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.07 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00134	Fig 8 Lead	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0
TTS00139	Phone Charger	Warehouse	15/02/2023	15/02/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00147	Battery Charger	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.12 mA Limit : 1.00 mA S : 0.01 kVA
TTS00148	Fig 8 Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0
TTS00151	Power Supply	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.06 mA Limit : 1.00 mA S : 0.00 kVA
TTS00155	C6 IEC Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.12 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00156	Power Board	Warehouse	11/01/2024	11/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00157	IEC Lead	Warehouse	04/02/2025	06/08/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00158	Scales	Warehouse	19/07/2023	18/01/2024	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.02 mA Limit : 5.00 mA S : 0.00 kVA
TTS00159	C6 IEC Lead	Warehouse	13/01/2022	15/07/2022	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00160	Battery Charger	Warehouse	13/01/2022	15/07/2022	Pass	Visual Inspection: Result : 0; Insulation: Riso : 48.9 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.05 mA Limit : 5.00 mA S : 0.00 kVA
TTS00161	Phone Charger	Warehouse	04/02/2025	04/02/2026	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00172	Power Supply	Warehouse	11/01/2024	11/07/2024	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.11 mA Limit : 1.00 mA S : 0.01 kVA
TTS00174	Label Winder	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00183	Printer	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.14 mA Limit : 5.00 mA S : 0.88...
TTS00191	IEC Lead	Warehouse	06/01/2021	05/01/2026	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1

Appliance ID	Type	Location	Test Date	Retest Date	Status	Test Summary
TTS00205	Instaltest Lead	Warehouse	04/02/2025	06/08/2025	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.02 mA Limit : 1.00 mA S : 0.00 kVA
TTS00206	Extension Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00217	Power Supply	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.22 Ohm Limit : 1.00 Ohm; Differential Leakage: Idiff : 0.34 mA Limit : 5.00 mA S : 0.01...
TTS00237	Charger	Warehouse	29/01/2025	31/07/2025	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA
TTS00238	Kyoritsu lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.02 mA Limit : 1.00 mA S : 0.00 kVA
TTS00239	Seaward Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.02 mA Limit : 1.00 mA S : 0.00 kVA
TTS00241	Power Board	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.08 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00242	PC	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.11 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS00243	Dyson vac	Warehouse	20/07/2022	19/01/2023	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.06 mA Limit : 1.00 mA S : 0.00 kVA
TTS00256	C6 IEC Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00257	Power Supply	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.05 mA Limit : 1.00 mA S : 0.01 kVA
TTS00258	Power Board	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Polarity: Fault : 1; Differential Leakage: Idiff : 0.07 mA Limit...
TTS00259	IEC Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.04 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00260	Power Board	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.05 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00262	IEC Lead	Warehouse	11/01/2024	11/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00263	Monitor	Warehouse	11/01/2024	11/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.10 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm
TTS0027	Power Board	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.06 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00275	Monitor PSU	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.07 mA Limit : 1.00 mA S : 0.00 kVA
TTS00276	MRL	Warehouse	29/01/2025	31/07/2025	Pass	Visual Inspection: Result : 0
TTS00277	IEC Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.03 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00289	C6 IEC Lead	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.08 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00291	Charger	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.04 mA Limit : 1.00 mA S : 0.00 kVA

Appliance ID	Type	Location	Test Date	Retest Date	Status	Test Summary
TTS00294	Truecon Lead	Warehouse	12/01/2024	13/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.03 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00296	RCD Portable	Warehouse	18/01/2024	19/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.03 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1.00 mA S : 0.00...
TTS00306	Power Board	Warehouse	04/02/2025	06/08/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00310	Power Supply	Warehouse	10/02/2025	12/08/2025	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.06 mA Limit : 1.00 mA S : 0.00 kVA
TTS00311	IEC Cable	Warehouse	17/02/2025	19/08/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.06 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS00312	Seaward Lead	Warehouse	17/02/2025	19/08/2025	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.02 mA Limit : 1.00 mA S : 0.00 kVA
TTS00313	Power Supply	Warehouse	17/02/2025	19/08/2025	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.13 mA Limit : 1.00 mA S : 0.01 kVA
TTS0059	Power Board	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.03 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS0075	Extension Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS0076	Drill	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Insulation-P: Riso-S : >200 MOhm Limit : 1 MOhm
TTS0077	Glue Gun	Warehouse	29/01/2025	31/07/2025	Pass	Visual Inspection: Result : 0; Insulation-P: Riso-S : >200 MOhm Limit : 1 MOhm
TTS0081	Fig 8 Lead	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0
TTS0084	Charger	Warehouse	11/01/2024	12/07/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.11 mA Limit : 1.00 mA S : 0.00 kVA
TTS01004	Power board	Warehouse	11/01/2024	25/01/2024	Pass	Visual Inspection: Result : 0; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Differential Leakage: Idiff : 0.13 mA Limit : 1.00 mA S : 0.00 kVA
TTS1306	IEC Lead	Warehouse	29/01/2025	31/07/2025	Pass	Visual Inspection: Result : 0; Earth Continuity: R : 0.09 Ohm Limit : 1.00 Ohm; Insulation: Riso : >200 MOhm Limit : 1 MOhm; Polarity: Fault : 1
TTS171	PSU	Warehouse	24/07/2023	23/01/2024	Pass	Visual Inspection: Result : 0; Touch Leakage: Itou : 0.04 mA Limit : 1.00 mA S : 0.00 kVA
rcd3	Drill	Warehouse	15/05/2024	15/05/2025	Pass	Visual Inspection: Result : 0; Insulation-P: Riso-S : >200 MOhm Limit : 1 MOhm