


D1-D4 = 1N4148
R1-R10 = METAL-FILM RESISTORS
M1 = MOTOR FOR VERTICAL ROTATION
M2 = MOTOR FOR HORIZONTAL ROTATION
L1 = UPPER VERTICAL LIMIT SENSOR
L2 = LOWER VERTICAL LIMIT SENSOR
L3 = LEFT* HORIZONTAL LIMIT SENSOR
L4 = RIGHT* HORIZONTAL LIMIT SENSOR

***WHEN THE VIEWER IS DIRECTLY FACING THE LIMIT SENSORS' CONNECTION PINS.**

CIRCUIT DIAGRAM

Dual Axis Solar Tracker

REV NO.	DESIGNED BY:	DATE:
2	Luke Jiang	07/05/2026