Making SodiumFATP SW

Communications via CP2102 USB to UART Apple USB Ethernet Adapter set to 169.254.51.34 Found in rc.groundhog.postprocess USB Ethernet = 169.254.1.10

Disconnecting makes postsnap error out trying to connect to 169.254.90.103

Found in TM.app bundle uiStartUp.lua ping -c 1 169.254.1.32 sc:connect("169.254.1.32", 7600) sc:send("[123]eeprom read(translation,cat08,20,32)\r\n")

Sniffed on wireshark: ping request src 17.114.120.32 dst 169.254.1.32

Successfully pinged 169.254.1.32 from USB interface 169.254.1.1

telnet 169.254.1.32 (return key)

[(null)]ACK(ERR_-3: id=-1: message need ID number, ID format is error; or ID too long;ERROR;1560,338,1560,338,0)

[123]eeprom read(translation,cat08,20,32) $\r\$

[123]ACK(ERR_-194 param error;ERROR;1587,721,1587,722,1)

[123]help

[123]ACK(ERR_-5: message format is error; ERROR; 1641, 62, 1641, 62, 0)

Set up MacBook as imiddle router

Yangs-MacBook-Pro-3:~ yang_gu\$ sudo ifconfig bridge1 create

Yangs-MacBook-Pro-3:~ yang_gu\$ sudo ifconfig bridge1 addm en39 addm en40

Yangs-MacBook-Pro-3:~ yang_gu\$ sudo ifconfig bridge1 up

=====

Temp/Humidity sensor apparently causing noise to FATPSodium Fixture (??) Sunny unplugged at some point and that