



Stepper Motor Controller



Spare Gates



Mounting Holes

- H1
- H2
- H3
- H4

Power Input Section

