					Comr	nerciali	izati	on Me	etina	Ren	ort						
Model na	ame					···o··o··a··		<u> </u>	<u> </u>	,	<u> </u>						
Country		RUN THE WORLD VIETNAM - INDONESIA				Fac	Factory			HWA - HWI							
Season		SS22					Las	Lasting type			STROBEL						
PB Type		TN/NM					Bot	Bottom type				EVA					
Gender / Size run Buy month		W: 3.5-9.5 09-11						Article number			LEA NA						
Last #		22030					Arti				SYN NA						
Tooling #		57776							TEX GZ0570/GW6254								
Model Picture						ME automation											
Stage		Date	Result	Fittest	Fit result	Stage	Date	Result	Fittest	Fit Res	sult Stage	Date		Result		Remarks	
CS1		8-Mar	Pending	8-Mar	Pass												
Process	Stage	Illu	ıstration	Is	sues and Co	mments		Action Plan		Issued by	LO Comment	Result	PIC	Apply Stage	Cost Impact		
Material	CS1			- The gap of 3 Stripes is inconsistent.			1. 3stripes 2. Base: F 3stripes: F 3. 3stripes	ake option on 3stripes: stripes: Printing 2D (not base) -> Reject ase: Printing 3D full 3stripes on Vamp/Q'tr, ipes: Printing 2D -> Waiting CMFD stripes printing 3D (not base) on Dancess -> recut b-sew (same CS1)			Pro		Undertesting	Tech	CS2		
		disigned spec	eficially for E N		bbing Logo: Prin easy delaminati	gting 3D on logo ion.	- Change 0.3mm to	thickness printing 0.5mm.	3D "small lette	ers" from	Dev		Done	Tech	CS2		
				- Wear test iss delamination.	sue: When wear	ring Tongue lining	- Incease Tongue.	Tongue lining patt	tern and add c	clock stitch or	Dev		Undertesting	Tech	CS2		
	CS2																
	CS3																
	CS1																
Pattern	CS2																
	CS3																
	CS1															 	
Cutting	CS2																
	CS3																

Stitching	CS1		- The surface of Top Eyestay Nosew is broken at embroidery.	- Make option: 1. Reduce 40% needle stitching line. 2. Reduce 20% needle stitching line.	Pro		Undertesting	Tech	CS2	
		15 IVAD	- Difficult stitch and turn Heel Vamp/Quarter, because it tough at nosew part and visible the thread stitching at Heel.	- Change material Heel Cap part: • Old (cū): DANACESS PLUSRECYCLED AQUAVEGAN EPM 5/TFLAT 1.0mm • New (mới): DANACESS PLUSRECYCLED AQUAVEGAN EPM 5/TFLAT 0.5mm	Pro		Undertesting	Tech	CS2	
	CS2									
	CS3									
Assembly	CS1									
	CS2									
	CS3									
Bottom	CS1									
	CS2									
	CS3									
Option	CS1									
	CS2									
	CS3									
1	* Agreement (after CS3 meeting)						1			
		, , , , , , , , , , , , , , , , , , , ,	J.							

RUN THE W	/ORLD								
Process	Stage	Illustration	Issues and Comments	d Comments Action Plan			Result	Apply Stage	Cost Impact
			Forefoot. * 1/6 tester felt slight tight at fore foot.	No changed pattern or process. Done					
	OFTENSET .	>	Midfoot. * No critical issues.	-					
Comment F	FIT Tos		Heel. * 1/6 tester felt slight tight at heel.	No changed pattern or process. Done					
	FILLES	slight wrintle manufact fore foot	General * slight wrinkle material at fore foot. Refer to pic 1.	CS2 use correct Toe shape molding					