# FIRST PRODUCTION REVIEW

# FLUIDFLOW 2.0 M Art. FZ1985

PT. Hwaseung Indonesia Jepara, November 17<sup>th</sup>, 2021



# First Production Policy - Implementation

This first production quality check is conducted as the implementation of the adidas First Production Policy Manual.

#### **Procedure:**

- 1. Pick Up @5 prs / Size Pairs (Min 20 Max 50) New Model Shoe from Warehouse
- 2. Put the shoe on the AQL Inspection Table (Lighting: 650-800 Lux)
- 3. Shoe inspected by LO Representative (LO Production Manager)
- 4. Review all issue finding and Conclusion from LO to Factory (Production, QIP, Development, CE,ME)
- 5. Take defect picture, calculate the defect rate, and report FPS Review by QIP Procedure.

# First Production Shoe Review - Activity





Date : November, 17<sup>th</sup> 2021

Cell/Building : Cell A17 / Building A

Model Name : Fluidflow 2.0 M

Article Number : FZ1985

PO : 128928321

Participant : Production, CE, QIP, Dev, ME

Result : Pass rate : 64% (32 from 50 pairs OK)

LO Comment : Go Ahead Production

( with note : the first production must

be repacked 100% issue dirty outsole)

Defect:

1. Dirty Outsole

2. Dirty Upper

3. Thread End

## Measurement Result

#### **MEASUREMENT FLUIDFLOW 2.0 M**

	PART. NAME	SIZE UK																	
NO		6T			7			8			8T			9			10		
		Std	ki	ka	Std	ki	ka	Std	ki	ka	Std	ki	ka	Std	ki	ka	Std	ki	ka
1	HEEL HEIGHT	97.0	95.1	95.8	98.0	97.7	97.6	100.0	98.0	98.0	101.0	99.8	99.7	102.0	102.0	101.0	104.0	102.6	102.6
2	LATERAL COLLAR HEIGHT	58.0	57.4	58.0	59.0	58.5	58.3	61.0	59.0	60.0	62.0	61.6	62.2	63.0	62.6	61.6	65.0	64.5	65.0
3	MEDIAL COLLAR HEIGHT	61.0	60.1	60.8	62.0	61.7	61.6	64.0	62.0	63.0	65.0	63.2	63.6	66.0	66.0	65.0	68.0	66.4	66.6
4	TOE SPRING	38.0	38.0	38.0	38.0	38.8	38.9	40.0	40.1	40.2	40.0	40.6	40.8	40.0	41.3	41.0	42.0	43.8	43.7

CEK	48					
ок	48					
NOT OK	0					
%	100%					




# ISSUE FINDINGS

### **TOP ISSUE**








DIRTY OUTSOLE DIRTY UPPER THREAD END

#### **ASSEMBLY ISSUE**










TOE OFF CENTER

BONDING

LINE UP HEEL WEBBING

**OVERCEMENT** 


## **OTHER ISSUE**



TWISTED SHOE LACE



POOR SHAPE HEEL WEBBING



BONDING OUTSOLE TO MIDSOLE

