

Document No A0373

Version 11

Page: 1/13
Approval Date: 20 Feb 2020
Effective:

3rd Party Inspection Procedure (FTW)

20 Feb 2020 Effective until: 14 Feb 2022

Document Owner:

Hoang Do, Senior Manager Quality Assurance Programs and Systems. Footwear Sourcing.

Author:

Eric Jeandin,

Senior Manager FW Quality adidas Herzo

Updates since Jan 2020:

Hoang Do,

Senior Manager Quality Assurance Programs

and Systems. Footwear Sourcing.

Approval:

Robert Fessele,

Senior Director Quality FW

Departments Affected:

All Sourcing LOs, FTW Quality teams

All FTW T1 Supply Partners

3rd Party Inspection Institutes

/ersion	Date	Modifications	Page
01	09/05/2007	All new	all
02	03/09/2007	2.1 3 rd party inspection criteria	2
		2.7 Inspection preparation	4
		2.8 Selecting the Random Sampling	4
		2.9 Packing integrity	5
		2.10 Inspection quantity	5 5
		2.11 Inspection cannot be stopped	
		2.14 Intertek identification and sealing procedure	6
		3. Finished shoe inspection process	9
		3. IV Final Random Inspection Report - revised	9
03	20/03/2008	claim influence in 3 rd Party Inspection percentage	2
		PO selection process	4
04	20/11/2008	Adding CPSC certificate to required documents for US orders	3
05	03/12/2008	Changing PO selection responsibilities for ITS inspection	4
06	01/10/2009	2.1. 3 rd party inspection criteria	2
07	25/10/2012	New document owner, Renamed Head of Quality to Senior Quality Manager	
08	15/04/2013	Updated Intertek contact	1
		2.g Required Documents	4
		Inspection Certificate	4,6,9
		3. Finished Shoe Inspection Process	9
		4. Policies and Procedures	9
09	15/04/2014	Updated to SOM and SMM	
		Added 2.a., exceptional 3 rd party inspection criteria	2
10	25/07/2017	Clarified and reorganized point 2.) Procedure	2-7
		Updated job titles	Variou



Document No A0373

Version 11

Page: 2/13 Approval Date: 20 Feb 2020 Effective:

20 Feb 2020 Effective until: 14 Feb 2022

3rd Party Inspection Procedure (FTW)

15/01/2020 11 Update Defect List 7,8,11-13 Update Approved 3rd Party Inspection Company List 10

Table of Content

8

Factory Accountability

	Table of Content	
1	Purpose	9
2	Reasons for 3 rd party inspection	Annex 1
2a	General reasons for 3 rd party inspection	Annex 2
2b	Claim-based reason for 3 rd party inspection	Annex 3
2c	Exceptional reason for 3 rd party inspection	Annex 4
3	3 rd Party Inspectors	Annex 5
3a	3 rd party inspectors training and certification	10
3b	Rotation of 3 rd party inspectors	
3c	Performance feedback for 3 rd party inspectors	
4	Factory Responsibilities	
4a	Booking of 3rd party inspectors	
4b	Manufacturing confirmation samples and other documents	
4c	Inspection certificates, AQL level and sampling sizes	
4d	POs for inspections	
5	Inspection Process	
5a	Random Selection of POs	
5b	Random Selection of Outer Cartons	
5c	Completion of inspection certificates	
5d	Shoe handling during inspections	
5e	Defect review	
5f	3rd party identification and sealing procedure	
6	Defect Disagreement Handling	
6a	Defect disagreement	
6b	PO decision making	
6c	Re-inspection after repairing or repacking	
7	Report Distribution and Storage	

9 Annex	
---------	--

- 3rd Party Inspector Training Tracking 1
- 3rd Party Inspection Process
- Inspection Certificate, IC
- Defect List
- Approved 3rd Party Testing Institutes
 - **Abbreviations**



Document No A0373

Version 11

Page: 3/13
Approval Date: 20 Feb 2020
Effective: 20 Feb 2020

3rd Party Inspection Procedure (FTW)

Effective: 20 Feb 2020 Effective until: 14 Feb 2022

1) Purpose

The adidas Footwear Quality Department requires under certain circumstances the execution of AQL Inspections of purchase orders prior shipment by a 3rd party Inspection ("3rd party inspection"). Random samples according to Acceptable Quality Level (AQL) Plans will be selected and inspected for various characteristics.

The entire lot will either be accepted or rejected. The decision will be based on specified criteria and the number of defects or defective units found in the sample.

2) Reasons for 3rd party inspection

a) General reasons for 3rd party inspection

In case an existing T1 supplier did not participate yet in 3rd party inspection or a new T1 supplier is requested to participate in 3rd party inspection, 10% of the total number of completed POs per month will initially be inspected by 3rd party inspection institute:

- If there is <u>no</u> rejection by 3rd party inspection during one entire month; the inspection percentage will go down by 2,5%. In the ideal case a factory will be out of 3rd party Inspection until further notice after 4 months continuous 3rd party inspections without a PO rejection
- If there is one rejection during one month the inspection percentage will stay the same
- More than one rejection during one month the inspection percentage will go up by 2,5%

b) Claim-based reason for 3rd party inspection

When claims arise, they are used to set the PO inspection percentage for 3rd party inspection in the following manner:

- In case a factory is receiving one claim in one respective month the inspection level is going up by 2,5% for the following month
- In case a factory is receiving multiple claims in one month
 - o different claim reasons will be treated individually, and each claim leads to a 2,5% increase for each claim.
 - Same claim reason in different claims will only lead in a general increase of 2,5%.

Once 3rd party inspection is implemented, the same rules as under section 2.a.) are applied, i.e.:

- If there is <u>no</u> rejection by 3rd party inspection during one entire month; the inspection percentage will go down by 2,5%
- If there is one rejection during one month the inspection percentage will stay the same
- More than one rejection during one month the inspection percentage will go up by 2,5%

Note:		



Document No A0373

Version 11

Page: 4/13 Approval Date: 20 Feb 2020 Effective: 20 Feb 2020 Effective until:

3rd Party Inspection Procedure (FTW)

14 Feb 2022

A claim must have "settled" status in the claim tracking lists from the claim desks in order to trigger 3rd party inspection, However, VPS, SDOM, DM, SDQ or DQ can decide to implement 3rd party inspection prior to the official claim settlement, e.g. if there are delays receiving the complete information about affected pairs from markets, but it is confirmed that the affected PO has a quality issue.

c) Exceptional reason for 3rd party inspection

Under exceptional circumstances roles responsible for quality in production (i.e., VPS, SDOM, DM, SDQ or DQ) have the authority to increase or decrease the 3rd party inspection level by more than 2.5%:

Examples include (but are not limited to):

- A manufacturer has on-going and/or severe quality issues
- Rapid start up or ramp up of a new or existing factory/facility
- Starting up or ramping up of technically challenging, strategically important products in new factories/facilities

3) 3rd Party Inspectors

a.) 3rd party inspectors training and certification

All 3rd party inspectors who inspect adidas products must be trained and certified for adidas quality standards and inspection procedures:

- DQ of respective LO is overseeing and monitoring training status
- 3rd party institute has train new inspectors internally for shoe inspections
- Afterwards new inspectors are trained at a factory according to Annex 1, 3rd Party Inspector Training Tracking Form - DQ of respective LO arranges factory for training
- DQ of respective LO certifies 3rd party inspectors at end training

b.) Rotation of 3rd party inspectors

3rd party institute is responsible to rotate 3rd inspectors between factories. There must be at least 2 3rd inspectors rotating at any given factory. The 3rd party institute decides which inspector goes to which factory.

c.) Performance feedback for 3rd party inspectors

Any feedback regarding the performance or knowledge of 3rd party inspectors must be directed to the Director Quality of the respective LO.

4) Factory Responsibilities

a) Booking of 3rd party inspectors



A0373

Version 11

Page: 5/13

Approval Date: 20 Feb 2020

Effective: 20 Feb 2020

Effective until:

14 Feb 2022

3rd Party Inspection Procedure (FTW)

The respective factory is responsible to inform 3rd party inspectors 4 days (can be lowered to 2 days with a local agreement) prior to when an inspection should take place, including the total number of completed POs which are ready for inspection and how many POs must be inspected.

The PO inspection quantity per inspector is determined by following guideline:

- Inspection time: 30-40 seconds per pair
- Quantity per day: 500-650 pairs, including time for picking up the carton
- Number of PO's per day:

if POs quantity is 900 to 3,000 pairs:
if POs smaller than 900 pairs:
20-35 POs

b) Manufacturing confirmation samples and other documents

Factory must provide:

- Approved MCS in good condition for every article which is inspected
- Grading sheet to check e.g. size grouping of lace length and logo dimensions
- SHAS & Packing Manual to check packing integrity

c) Inspection certificates, AQL level and sampling sizes

Factory provides an inspection certificate including AQL level and sampling size for the respective POs, which means they prepare the frame work of the inspection according to Table I, II, III.

The framework should be identical to the procedure the factory has uses to conduct internal factory AQL inspections by the factory AQL Inspectors.

Therefore 3rd party inspectors start their inspections with their carton selection in the warehouse and are not double-checking or responsible for:

- AQL level selection
- To be inspected quantity
- Size calculation
- Maximum acceptable defects according to AQL Level selection

d) POs for inspections

To minimize the time needed for selecting products for 3rd party inspections and to ensure random sampling, it must be ensured that:

- Only POs inspected by factory AQL Inspectors can be inspected by 3rd inspectors
- The POs to be inspected must be complete and in one physical location. This should be verified by the inspector prior to selecting samples
- The POs need to be clearly laid out & identified in the warehouse, so that cartons can be easily selected



Document No A0373

Version 11

Page: 6/13 Approval Date: 20 Feb 2020 Effective: 20 Feb 2020

3rd Party Inspection Procedure (FTW)

Effective until: 14 Feb 2022

- No cleaning or repairing is allowed during or prior the inspection process
- There must be at least twice the number of POs which 3rd party has to inspect in the warehouse to guarantee a random selection

5) Inspection Process

Annex 2, 3rd Party Inspection Process describes the overall process of an inspection and surrounding conditions.

a) Random Selection of POs

To guarantee that there is a random selection, there is not (pre-)selection of POs by adidas or factory employees. 3rd party inspectors select randomly POs which they will inspect upon arrival at the factory.

b) Random Selection of Outer Cartons

- 3rd party inspector selects randomly in FG WH outer cartons for inspection. Outer carton numbers and shoe sizes on recorded on the inspection certificate
- The selected outer cartons must be marked with a 3rd party stamp or a personal 3rd party inspector sticker on the barcode end of each carton as it is pulled from the PO
- The outer cartons are taken into the AQL inspection room under the supervision of the 3rd party inspector
- If outer cartons are not identified properly in FG WH or outer cartons are missing, the inspection should not continue

c) Completion of inspection certificates

- Quality standards and defect types are based on the defect list (please refer to annex 3) as listed in Quality Claim Procedure FTW
- All defects found during 3rd party inspection is identified and notified on the inspection certificate
- If several defects are detected on one pair only the most serious one is recorded
- If the found defects are exceeding the acceptable number of defects for the respective PO after a relatively low number of inspected shoes, the inspection has to be fully (100%) completed and it is not allowed to stop the inspection earlier
- 3rd party inspectors are not authorized to B-Grade or C-Grade products. Results will only be reported

d) Shoe handling during inspections

- Defective shoes found during the 3rd party inspection is clearly marked with red, orange and yellow arrow stickers for Critical, Major and Minor defect
- Defective shoes are stored on a specific defective rack, separated by defects types
- All shoes without defects will be returned to original lot and repacked into the outer cartons by factory assistant.



Document No A0373

Version 11

Page: 7/13 Approval Date: 20 Feb 2020 Effective: 20 Feb 2020

3rd Party Inspection Procedure (FTW)

Effective until: 14 Feb 2022

e) Defect review

- Defective shoes found during the 3rd party inspection is clearly marked with red, orange and yellow arrow stickers for Critical, Major and Minor defect then stored in a separate, defective
- After the 3rd party inspection is finished the defective shoes will be reviewed with T1 and adidas production team. Adidas production team makes the decision if shoes can be repaired or must be replaced
- Replacement shoes must be checked by 3rd party inspector before they can be added to the outer carton
- All open outer cartons must stay in the inspection room until the cartons are filled with replacement shoes and can be closed and sealed by 3rd party inspector
- o If not all replacement shoes are available within the standard working hours, 3rd party inspector does not have to seal outer cartons with missing shoes. The factory is then responsible to complete the PO and to close the outer cartons with grey tape and QIP inspected stickers

3rd party identification and sealing procedure

- For each inspected and released pair of shoes the inner box must be marked with a small rectangular personalized 3rd party inspector sticker on the inside of the carton. The personalized 3rd party inspector sticker must
 - o have at least a unique personal identifier of the 3rd party inspectors
 - be temper proof, which means it cannot be take away and/or moved to a different inner box
- Each outer carton must be resealed with the grey tape by the factory assistant. Then it is marked with a rectangular 3rd party outer carton sticker which is placed half on the tape and half on the outer carton on the top side of the carton. The 3rd party outer cartons sticker must be temper proof, which means it cannot be take away and/or moved to a different outer carton box.
 - Additionally, a temper proof personalized 3rd party inspector sticker has to be place half on the 3rd party outer carton and half on the outer carton on the top side of the outer carton

6) Defect Disagreement Handling

a) Defect disagreement

In case of a disagreement with defects during the defect review, especially in case a PO is rejected:

- 3rd party inspector does not change their original evaluation and list all defects on their report. The 3rd party inspection result serves as basis for decision making for the adidas DQ
- 3rd party inspector does not have to wait for repaired or replacements shoes and does not seal the outer carton
- T1 or adidas production team has to contact DQ for further evaluation



A0373

Version 11

Page: 8/13
Approval Date: 20 Feb 2020
Effective: 20 Feb 2020

3rd Party Inspection Procedure (FTW)

Effective: 20 Feb 2020 Effective until: 14 Feb 2022

b) PO decision making

- DQ is authorized to decide after reviewing the defects and/or the 3rd party inspection result to release a PO.
- In case a PO remains rejected, the DQ is authorized to decide if the PO must be repaired, repacked or B-graded
- In case the DQ is not available, the respective SDOM or DM is authorized to make a final decision

c) Re-inspection after repairing or repacking

3rd party inspector is not required to conduct a re-inspection of any PO which they already inspected. The factory is responsible for re-inspecting POs after repairing or repacking.

7) Report Distribution and Storage

- All 3rd party ICs which are completed must be signed on the inspection day by 3rd party inspector and adidas personnel. Copies must be given immediately to the factory personnel and the adidas SMP
- An official typed report will be sent by 3rd party institute the following day only to the attention of the respective SDOM, DM, SPM and DQ
- Reports must be kept a minimum 12 month after completion

8) Factory Accountability

The factory is accountable and responsible for all delays in shipments due to manufacturing quality problems (if it disables adidas from meeting its commitments to its customer required delivery date within shipping policy, shipment by air freight is on factories expense).

If legitimate claims are made against any shipment by an adidas customer, the severity of the problems must be determined, and samples of the defective shoes should be sent to the liaison office.

TABLE I: sample - size code letters



Document No A0373

Version 11

Page: 9/13
Approval Date:

20 Feb 2020 Effective: 20 Feb 2020

Effective until: 14 Feb 2022

3rd Party Inspection Procedure (FTW)

		特殊	验货级别	ıj		一般验货	级别
	Spe	cial insp	ection le	evels		al inspec	
Lot or batch size	S-1	S-2	S-3	S-4		ll l	III
验货批次大小							
2-8	Α	Α	Α	Α	Α	Α	В
9-15	Α	Α	Α	Α	Α	В	С
16-25	Α	Α	В	В	В	С	D
26-50	Α	В	В	С	С	D	Е
51-90	В	В	С	С	С	E	F
91-150	В	В	С	D	D	F	G
151-280	В	С	D	E	E	G	н
281-500	В	С	D	E	F	Н	J
501-1200	С	С	E	F	G	J	K
1201-3200	С	D	E	G	Н	ĸ	L
3201-10,000	С	D	F	G	J	L	M
10,001-35,000	С	D	F	Н	K	М	Ν
35,001-150,000	D	E	G	J	L	N	Р
150,001-500,000	D	E	G	J	M	Р	Q
500,001 and over	D	E	Н	K	N	Q	R

TABLE II: master table for normal inspection




Table III: method ANSI/AQL calculation



Document No A0373

Version 11

Page: 10/13
Approval Date: 20 Feb 2020

Effective: 20 Feb 2020 Effective until: 14 Feb 2022

3rd Party Inspection Procedure (FTW)

	Method ANSI / AQL Calculation Table III																						
P/O N	CUST.NAM E	CUST.ORD	MODEL NAME	ART	ETD	6	6-	7	7-	8	8-	9	9-	10	10-	11	11-	12	12-	13	13-	QTY	Inspection Level / Multiplication %
						60	90	90	90	110	140	170	170	130	90	90	70	80	20			1400	Level2 / K
	To-be inspected sample qty per size					5,4	8,0	8,0	8,0	9,8	12,5	15,2	15,2	11,6	8,0	8,0	6,3	7,1	1,8			125	8,9%
Selected Qty						5	8	8	8	10	13	15	15	12	8	8	6	7	2			125	

9) Annex

Annex 1: 3rd Party Inspector Training Tracking Form

Annex 2: 3rd Party Inspection Process

Annex 3: Inspection Certificate, IC

Annex 4: Defect List

Annex 5: Approved 3rd Party Inspection Companies

- Intertek (ITS) and IMPACTIVA are the world-wide approved 3rd party Inspection Companies for adidas T1 suppliers
- Adidas FTW Quality (DQs) will have right to recommend/direct in selection of approved 3rd party inspection company to support T1s.
- FTW Quality also reserves the right to appoint under special circumstances to appoint a different external supplier to perform 3rd party inspection

Intertek

Contact Europe	Contact LO China
Daniel Kafitz <u>Daniel.Kafiz@intertek.com</u>	Anny Li anna.yy.li@intertek.com
Gregory Baxter Gregory.Baxter@intertek.com	
Contact LO Indonesia	Contact LO Vietnam
Nuriana AprianiNurina.apriani@intertek.com	Huyen NguyenHuyen.nguyen@intertek.com
	, , , , , , , , , , , , , , , , , , , ,

IMPACTIVA

Contact Global	Contact LO China
Mathieu Vassal <u>mvassal@impactiva.com</u>	Name: Anna
Cécilia Rie crie@impactiva.com	Email: ayang@impactiva.com
Contact LO Indonesia	Contact LO Vietnam
Name: Manmohan	Name: Karthik



Email: makumar@impactiva.com

Procedure

Document No A0373

Version 11

Approval Date: 20 Feb 2020

Page: 11/13

Effective: 20 Feb 2020 Effective until:

14 Feb 2022

3rd Party Inspection Procedure (FTW)

Email: gkarthik@impactiva.com

Code	Defect Classification (Page 1/3)	Descripton ==>	MINOR DEFECT	MAJOR DEFECT	CRITICA DEFEC
00	PACKING AND LABELING		2.5	1.5	0.0
00.01	OUTER CARTON DAMAGED / DIRTY (INCLUDE LABELING AND LABELING OFF CENTER)	1	Х		
0.02	INNER BOX DAMAGED / DIRTY (INCLUDE LABELING, LABELING OFF CENTER AND PACKING MATERIALS)	<2 dots, <2mm	х		
0.03	INNER BOX DAMAGED / DIRTY (INCLUDE LABELING, LABELING OFF CENTER AND PACKING MATERIALS)	>2 dots, >=2mm		Х	
00.04	ACCESSORIES/ATTACHMENTS MISSING OR IN BAD QUALITY		X		
00.05	ODD PAIR (BOTH LEFT/RIGHT SHOES IN PAIR, DIFFERENT SIZE IN ONE PAIR, SHOE SIZE NOT AS LABEL/STICKER)				X
00.06	SIZE LABEL AND HANGTAG IN BAD QUALITY (PEEL OFF, UNCLEAR, ETC.) OR MISSING			X	
00.07	WRONG MATERIAL CONTENT LABEL OR HANGTAG				X
10	INSIDE THE SHOE				
0.01	CONTAMINATION (STAINS, CEMENT, etc.)	<2 dots, <2mm	х		
0.02	CONTAMINATION (STAINS, CEMENT, etc.)	>2 dots, >=2mm	^	x	
0.03	METAL PIECE/SHARP PIECE OR Any foreign item that could cause harm/injury to the consumer	-2 dots, -=211111		_^	х
0.04	MINOR/SOFT FOLDS, WRINKLES IN LINING OR LOOSE LINING		х		
10.05	NOTICEABLE/MAJOR/HARD FOLDS, WRINKLES IN LINING OR LOOSE LINING		- 71	х	
0.06	LINING MATERIAL DAMAGED		х		
0.07	LINING NOT SECURED BY STROEBEL STITCHING OR LASTING		х		
80.00	SOCKLINER POOR QUALITY OF PRINT, EMBOSS, LOGO			Х	
0.09	SOCKLINER OFF-SPEC [THICKNESS, LENGTH]		х	8	
0.10	POOR CEMENTING SOCKLINER TO INSOLE BOARD		Х		
0.11	MINOR/SOFT WRINKLED SOCKLINER/INSOLE BOARD		Х		
0.12	NOTICEABLE/MAJOR/HARD WRINKLED SOCKLINER/INSOLE BOARD			Х	
0.13	MISSING SOCKLINER	7		X	
0.14	WRONG COLOR OF LINING, SOCKLINER, LOGO OR PRINT	4	X		
0.15	DELAMINATION SOCKLINER COVER	4		X	
0.16	WRONG SIZE OR POSITION OF HEEL COUNTER/DAMAGED OR POOR TOE BOX			Х	
0.17	OTHER DEFECTS		>		
0	UPPER			<u> </u>	
310	UPPER MATERIALS				
310.01 310.02	LEATHER DEFECTS (LOOSE GRAIN, PEELING, ORANGE PEEL, EDGES NOT DYED AS REQUESTED, ETC.)			X	_
310.02	MATERIAL BROKEN/POOR MATERIAL QUALITY (TEXTILE, SYNTHETIC, MESH, ETC. I/POOR LEATHER (HAIRY, FRAYED EDGE) COLOR DIFFERENCE/LEATHER GRAIN DIFFERENCE BETWEEN LEFT AND RIGHT SHOE			x	
310.03	SHARP EDGE/POINT (for children's shoes) OR Any foreign objects that could cause ham/injury to consumer			_^	X
010.04	START EDGE FORT TO CHARLET 3 STOCKS ON ANY TO CIGHT OBJECTS MICK COURS COURSE HUMBINGS YOU CONSUME				
320	UPPER STITCHING				
320.01	WRONG STITCH LENGTH	not 9-10 stitches/inch	х		
320.02	WRONG ZIG-ZAG STITCH LENGTH	not 8 stitches/inch	х	8	
320.03	POOR STITCHING MARGIN, POOR STITCH EDGE DISTANCE (1mm < adidas edge distance's standard < 2.5mm)		X		
320.04					
320.04	BROKEN STITCHING/LOOSE STITCHING/SKIPPED STITCHING/OPEN SEAM		^	X	
320.05	INSECURE BACK/LOCK-STITCH		х	x	
320.05 320.06	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING				
320.05 320.06 320.07	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS		X X	X	
320.05 320.06 320.07 320.08	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS	>2mm	х	х	
320.05 320.06 320.07	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS	>2mm	X X		
320.05 320.06 320.07 320.08 320.09	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR	>2mm	X X	х	
320.05 320.06 320.07 320.08 320.09	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.)	>2mm	X X	х	
320.05 320.06 320.07 320.08 320.09 330 330.01	INSECURE BACK/LOCK-STITCH WAV/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE	>2mm	x x x	х	
320.05 320.06 320.07 320.08 320.09 330 330.01 330.02	INSECURE BACK/LOCK-STITCH WAY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING	>2mm	X X X	х	
320.05 320.06 320.07 320.08 320.09 330 330.01 330.02 330.03	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE	>2mm	x x x	X	
320.05 320.06 320.07 320.08 320.09 330 330.01 330.02	INSECURE BACK/LOCK-STITCH WAY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING	>2mm	X X X	х	
320.05 320.06 320.07 320.08 320.09 330 330.01 330.02 330.03 330.03	INSECURE BACK/LOCK-STITCH WAV/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION	>2mm	X X X	X	
320.05 320.06 320.07 320.08 320.09 330.01 330.02 330.03 330.04	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE		X X X	X	
320.05 320.06 320.07 320.08 320.09 330.01 330.01 330.02 330.03 330.04	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark)	<2 dots, <2mm	X X X	X X	
320.05 320.06 320.07 320.08 320.09 330.01 330.02 330.03 330.04 340.01 340.01	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark) CONTAMINATION (Stains, printing mark)	<2 dots, <2mm >2 dots, >=2mm	X X X X X	X	
320.05 320.06 320.07 320.08 320.09 330.01 330.01 330.02 330.03 330.04	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark)	<2 dots, <2mm	X X X	X X	
320.05 320.06 320.07 320.08 320.09 330.01 330.02 330.03 330.04 340.01 340.01	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark) CONTAMINATION (Stains, printing mark)	<2 dots, <2mm >2 dots, >=2mm <4mm length,	X X X X X	X X	
320.05 320.06 320.07 320.08 320.09 330.01 330.02 330.03 330.04 340.01 340.02	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark) CONTAMINATION (Stains, printing mark) OVER CEMENTING OR PRIMING	<2 dots, <2mm >2 dots, >=2mm <4mm length, <2mm width >=4mm length,	X X X X X	x x	
320.05 320.06 320.07 320.07 320.08 320.09 330.01 330.02 330.03 340.03 340.01 340.02 340.03 340.03	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark) CONTAMINATION (Stains, printing mark) OVER CEMENTING OR PRIMING	<2 dots, <2mm >2 dots, >=2mm <4mm length, <2mm width >=4mm length,	X X X X X X X X X X X X X X X X X X X	x x	
320.05 320.06 320.07 320.08 320.09 330.01 330.02 330.03 330.04 340.01 340.02 340.03 340.04 340.04 340.04	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark) CONTAMINATION (Stains, printing mark) OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING POOR TOUCH UP/PAINTING, MARKING LINE COLOR CHANGE/MIGRATION/BLEEDING OFF CENTER TOE TO HEEL / CROOKED	<2 dots, <2mm >2 dots, >=2mm <4mm length, <2mm width >=4mm length, >=2mm width <=3mm width	X X X X X X X X X X X X X X X X X X X	x x x	
320.05 320.06 320.07 320.08 320.09 330.03 330.02 330.03 330.04 340.01 340.02 340.03 340.04 340.05 340.05 340.07 340.07	IINSECURE BACK/LOCK-STITCH WAY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark) CONTAMINATION (Stains, printing mark) OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING POOR TOUCH UP/PAINTING, MARKING LINE COLOR CHANGE/MIGRATION/BLEEDING	<2 dots, <2mm >2 dots, >=2mm <4mm length, <2mm width >=4mm length, >=2mm width	X X X X X X X X X X X X X X X X X X X	x x	
320.05 320.06 320.07 320.07 320.08 320.07 330.01 330.02 330.03 340.04 340.01 340.02 340.03 340.04 340.04 340.05 340.05	IINSECURE BACK/LOCK-STITCH WAY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark) CONTAMINATION (Stains, printing mark) OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OFF CENTER TOE TO HEEL / CROOKED OFF CENTER TOE TO HEEL / CROOKED POOR SHAPE (WRINKLES/COLLAPSING/TOE SPRING)	<2 dots, <2mm >2 dots, >=2mm <4mm length, <2mm width >=4mm length, >=2mm width <=3mm width	X X X X X X X X X X X X X X X X X X X	x x x	
320.05 320.06 320.07 320.08 320.07 330.01 330.02 330.03 330.04 340.01 340.02 340.04 340.04 340.05 340.04 340.05 340.06 340.07 340.09	INSECURE BACK/LOCK-STITCH WAY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark) CONTAMINATION (Stains, printing mark) OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OFF CENTER TOE TO HEEL / CROOKED OFF CENTER TOE TO HEEL / CROOKED OFF CENTER TOE TO HEEL / CROOKED POOR SHAPE (WRINKLES/COLLAPSING/TOE SPRING PATTERN VARIATION different between LEFT and RIGHT shoes (when not intended by MCS)	<2 dots, <2mm >2 dots, >=2mm <4mm length, <2mm width >=4mm length, >=2mm width <=3mm width	X X X X X X X X X X X X X X X X X X X	x x x x x x x	X
320.05 320.06 320.07 320.08 320.07 330.03 330.02 330.03 330.04 340.01 340.02 340.03 340.04 340.05 340.06 340.07 340.08 340.08 340.09	INSECURE BACK/LOCK-STITCH WAVY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark) CONTAMINATION (Stains, printing mark) OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING POOR TOUCH UP/PAINTING, MARKING LINE COLOR CHANGE/MIGRATION/BLEEDING OFF CENTER TOE TO HEEL / CROOKED OFF CENTER TOE TO HEEL / CROOKED POOR SHAPE (WRINKLES/COLLAPSING/TOE SPRING PATTERN VARIATION different between LEFT and RIGHT shoes (when not intended by MCS) POOR SKIVING/X RAV/PRESSING MARKS	<2 dots, <2mm >2 dots, >=2mm <4mm length, <2mm width >=4mm length, >=2mm width <=3mm width	X X X X X X X X X X X X X X X X X X X	x x x x x x x	x
320.05 320.06 320.07 320.07 320.08 320.07 330.01 330.02 330.03 340.03 340.01 340.03 340.04 340.05 340.05 340.05 340.06 340.07 340.08	IINSECURE BACK/LOCK-STITCH WAY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark) CONTAMINATION (Stains, printing mark) OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OFF CENTER TOE TO HEEL / CROOKED POOR SHAPE (WRINKLES/COLLAPS)ING/TOE SPRING PATTERN VARIATION different between LEFT and RIGHT shoes (when not intended by MCS) POOR SKIVING/X RAY/PRESSING MARKS TONGUE MISSPLACED, LOOSE/EYESTAY NOT ALIGNED, HOLES NOT PUNCHED PROPERLY	<2 dots, <2mm >2 dots, >=2mm <4mm length, <2mm width >=4mm length, >=2mm width <=3mm >3mm >3mm	X X X X X X X X X X X X X X X X X X X	x x x x x x x	x
320.05 320.06 320.07 320.08 320.07 330.01 330.02 330.03 330.04 340.01 340.02 340.03 340.04 340.04 340.05 340.05 340.06 340.07 340.09 340.09 340.10	INSECURE BACK/LOCK-STITCH WAY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark) CONTAMINATION (Stains, printing mark) OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OFF CENTER TOE TO HEEL / CROOKED POOR SHAPPE (WRINKLES/COLLAPSING/TOE SPRING PATTERN VARIATION different between LEFT and RIGHT shoes (when not intended by MCS) POOR SKIVING/X RAY/PRESSING MARKS TONGUE MISSPLACED, LOOSE/EYESTAY NOT ALIGNED, HOLES NOT PUNCHED PROPERLY MIS-MATCHING/INCORRECT MEDIAL, LATERAL QUARTER AND BACK HEIGHT	<2 dots, <2mm >2 dots, >=2mm <4mm length, <2mm width >=4mm length, >=2mm width <=3mm >3mm <=3mm	X X X X X X X X X X X X X X X X X X X	X X X X X	X
320.05 320.06 320.07 320.08 320.07 330.01 330.02 330.03 330.04 340.01 340.02 340.03 340.04 340.05 340.05 340.05 340.07 340.08	IINSECURE BACK/LOCK-STITCH WAY/INCONSISTENT STITCHING NEEDLE HOLES / CUTS THREAD ENDS WRONG THREAD OR WRONG COLOR UPPER TREATMENTS (LOGO, EMBROIDERY, HF WELDING, DE- AND EMBOSS, PRINT, COMPONENTS, etc.) WRONG COLOR/ COLOR DIFFERENCE MISSING POOR SYMMETRY/OFF POSITION/WRONG SIZE POOR DEFINITION, NOT CLEAN, NOT CLEAR, DELAMINATION UPPER APPERANCE CONTAMINATION (Stains, printing mark) CONTAMINATION (Stains, printing mark) OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OVER CEMENTING OR PRIMING OFF CENTER TOE TO HEEL / CROOKED POOR SHAPE (WRINKLES/COLLAPS)ING/TOE SPRING PATTERN VARIATION different between LEFT and RIGHT shoes (when not intended by MCS) POOR SKIVING/X RAY/PRESSING MARKS TONGUE MISSPLACED, LOOSE/EYESTAY NOT ALIGNED, HOLES NOT PUNCHED PROPERLY	<2 dots, <2mm >2 dots, >=2mm <4mm length, <2mm width >=4mm length, >=2mm width <=3mm >3mm >3mm	X X X X X X X X X X X X X X X X X X X	x x x x x x	x



Document No A0373

Version 11

Page: 12/13
Approval Date: 20 Feb 2020

Effective: 20 Feb 2020

Effective until: 14 Feb 2022

3rd Party Inspection Procedure (FTW)

	B50 LACES / VELCROS/ SPEED LACE				
	350.01 LACE LACE LENGTH OUT OF SPEC [TOO SHORT OR LONG]	<= 3cm	Х		
	350.02 LACE LACE LENGTH OUT OF SPEC (TOO SHORT OR LONG)	> 3cm		X	
	350.03 VELCRO / SPEED LACE LENGTH OUT OF SPEC (TOO SHORT OR LONG)	<= 2cm	Х	v	
	950.04 VELCRO / SPEED LACE LENGTH OUT OF SPEC (TOO SHORT OR LONG)	> 2cm		X	
	B50.05 LACE / VELCRO / SPEED LACE WRONG COLOR, WRONG MATERIAL, DAMAGED, BROKEN OR	RNOT FUNCTIONING	- v	X	
	350.06 CONTAMINATION		X		
35	350.07 FRAYING		X		
2/	OTHER DEFECTS (THAT NEED REPORT AND CONSULT WITH ADIDAS PRODUCTION/QUALITY	AV)			
30	OTHER DEFECTS (THAT NEED REPORT AND CONSOLT WITH ADIDAS PRODUCTION/QUALITY	1)			
Cod	de Defect Classification (Page 2/3)	Defect Type ==>	MINOR	MAJOR	CRITICAL
400	BOTTOM AND STOCKFITTING (attaching midsole and components to outsole)		DEFECT	DEFECT	DEFECT
400.01	CONTAMINATION (Stains)	<2 dots, <2mm	X		
400.02	CONTAMINATION (Stains)	>2 dots, >=2mm	_ ^	X	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<4mm length,			
400.03	OVER CEMENTING OR PRIMING	<2mm width	Х		
400.04	OVER CEMENTING OR PRIMING	>=4mm length,		х	
5777777	100-00 (ART - WATER COURT AND ACT ACT COURT -	>=2mm width	200	^	
400.05	POOR TOUCH UP/PAINTING, MARKING LINE		X		
400.06	WRONG OR POOR OUTSOLE STITCHING	not 8-10mm/stitch	Х		
400.07	COLOR RELATED (WRONG COLOR, BLEEDING, MIGRATION, YELLOWING, ETC.)				Х
400.08	VISIBLE FILM / BLOOMING ON RUBBER				Х
400.09	POOR MID-/OUTSOLE QUALITY (UNEVEN TOP LINE, TRIMMING, AIR BUBBLES, SCRATCHES	S, WRINKLES, ETC)		Х	
400.10	POOR TREATMENT (PAINTING, LOGO)			х	
400.11	COMPONENTS DELAMINATION	>4mm length and depth			Х
400.12	COMPONENTS DELAMINATION	<=4mm length and depth	1	X	
400.13	MISMATCHING, INCORRECT POSITIONING, WRONG SIZES		-	X	
400.14	DIMENSION/HARDNESS OUT OF SPEC		-	X	
500	ACCEPANG THE CONTRACT OF THE PARTY OF THE PA				
500.01	ASSEMBLING (attaching BOTTOM TO UPPER) OFF CENTER / INCORRECT POSITIONING (SOLE LAYING)/LONG OR SHORT OUTSOLE				
500.01		2	X		x
500.02	BONDING GAP BONDING GAP	>2mm length and depth <=2mm length and depth	+		
500.04	WRONG BOTTOM/UPPER SIZE	<=2mm tength and deptr	+	х	-
600	CLEATS AND SPIKES				
600.01	WRONG TYPE / WRONG COLOR / WRONG SIZE			X	
600.02	MISSING OR DAMAGED			X	
600.03	LOOSE OR NOT TIGHTENED		Х		
600.04	NOT PROPERLY INSERTED [NOT 90 DEGREE ANGLE TO OUTSOLE PLATE OR WRONG DIREC	CTION	X		
600.05	RECEPTACLE NOT PROPER COUNTERSUNK			х	
600.06	RUSTY PARTS				Х
700	BOOST				
700.01	UNBLOWN BEAD		X		
700.02	SEMI UNBLOWN BEAD	MAX 1 PER PIECE	X		
700.03	YELLOWING BEAD BUT NO SIGNIFICANT COLOR DIFFENRENCE	MAX 1 PER PIECE	Х		
700.04	UNFILLED BEAD FOR NON-COLOR BOOST	8MM X 6MM X 4MM, MAX		X	
700.05	UNFILLED BEAD FOR COLOR BOOST	:4MM X 3MM X 2MM, MAX		Х	
700.06	CONTAMINATION BUT WITHOUT SIGNNIFICANT COLOR DIFFERENCE TO STANDARD BOOS	T COLOR MAX 1	Х		
800	VULCANIZED / vulcanized "look"				
800.01	YELLOWISH ON FOXING EDGE		X		
800.02	OVER CEMENT ON QUARTER/COLLAR LINING (AFTER VULCANIZING)		X		
800.03	SCRATCHED FOXING	>3MM LENGTH		X	
800.04	UNSMOOTH FOXING (AIR BUBBLES INSIDE)	- UNIVERSITY III	X	- "	
800.05	OVERLAPPED FOXING CONNECTION		X		
800.06	GAP AT FOXING CONNECTION			x	
800.07	FOXING LABEL ATTACHING OFF CENTER	>3MM	X		
800.08	POOR FOXING TRIMMING		-	Х	
	CARBON 4D				
900	PRINTED DEFECT AT VISIBLE AREA		Х		
900 900.01		2 OR MORE		х	
900.01	BROKEN LATTICE				
	BROKEN LATTICE SHIFT LINES		X		
900.01 900.02		OUTSIDE FOREFOOT	X	x	
900.01 900.02 900.03 900.04	SHIFT LINES	OUTSIDE FOREFOOT	X	Х	
900.01 900.02 900.03	SHIFT LINES EXCESS RESIN SURFACE FINISH CLUMBS AT VISIBLE AREA CONTAMINATION	OUTSIDE FOREFOOT		Х	
900.01 900.02 900.03 900.04 900.05 900.06 900.07	SHIFT LINES EXCESS RESIN SURFACE FINISH CLUMBS AT VISIBLE AREA CONTAMINATION COLOR DIFFERENCE, MISMATCH		X	X	
900.01 900.02 900.03 900.04 900.05 900.06	SHIFT LINES EXCESS RESIN SURFACE FINISH CLUMBS AT VISIBLE AREA CONTAMINATION		х		



A0373

Version 11

Approval Date: 20 Feb 2020

> Effective: 20 Feb 2020 Effective until:

14 Feb 2022

Page: 13/13

3rd Party Inspection Procedure (FTW)

1000	DIRECT SOLING				
1000.01	DOUBLE SKIN		Х		
1000.02	DOUBLE PRESSING LINE ON OUTSOLE		X		
1000.03	PU OVER-FLOW TO OUTSOLE		X		
1000.04	AIR BUBBLE	>1MM		Х	
1000.05	UN-FILLED TPU	>8 DOTS/INCH ²		X	
1000.06	PU OVER-FLOW TO INSOLE BOARD (NOT COVERED BY SOCKLINER)	A 11 - C 1 -	Х		
1000.07	POOR PARTING LINE TRIMMING	>1MM	Х		
1000.08	UPPER PINCHING/DAMAGE	BROKEN		Х	
1000.09	RELEASE AGENT MARKING AT VISIBLE AREA [CONTAMINATION]		X		
1000.10	PU OVER-FLOW TO UPPER	>1MM		X	
1000.11	MERGED UPPER TO PU MIDSOLE	>1MM	X		
1000.12	FLOW MARKING	CLEARY VISIBLE	X		
1000.13	HIGH/LOW BACK		Х		
1000.14	BONDING GAP PU & TPU			Х	
1000.15	DAMANGED PU/TPU			X	
1000.17	TORN MATERIAL			X	
2					
1100	SLIDES/SANDALS				
1100.01	DIFFERENT FOOTBED LENGTH	<= 3MM	Х		
1100.02	DIFFERENT TOE/HEEL SPRING	>=3MM	Х		
1100.03	OFF HEIGHT/WIDTH BETWEEN LEFT AND RIGH THONG/FLIP-FLOP	>=3MM	Х		
1100.04	OUTSOLE SUNKEN/COLLAPSING			X	

Code	Defect Classification (Page 3/3)	Defect Type ==>	MINOR DEFECT	MAJOR DEFECT	DEFECT
1200	KNITTING UPPER		DEFECT	DEFECT	DEFECT
1200.01	FRAYING OUT		х		
1200.02	BROKEN / COLOR VARIATION			х	
1200.03	HOT MELT YARN ACCUMULATES INTO GRANULES		х		
1200.04	UPPER PATTERN NOT SYMMETRY BETWEEN LEFT & RIGHT SHOE		Х		
1300	NO SEW				
1300.01	DELAMINATION/PEEL OFF/CRACKING ON PRINTING			х	
1300.02	OVERFLOWING CEMENT	>0.5MM	х		
1300.03	NOT SYMMETRY BETWEEN LEFT & RIGHT SHOE		х		
1300.04	YELLOWING/WHITENNING			х	
1300.05	COLOR DIFFERENT			X	
1300.06	BURN NO SEW			X	
1300.07	WRONG PRESSING POSITION / PRESSING MARKED		Х		
1400	OTHER DEFECTS (THAT NEED REPORT AND CONSULT WITH ADIDAS PRODUCTION/QUALITY)				

10) Abbreviations

Sample Quantity of product selected randomly from each lot

FGT Finished Goods Testing AQL Acceptable Quality Level

MCS Manufacturing Confirmation Sample

SHAS Special Handling at Source QIP Quality Integration Project

PO Production Order
IC Inspection Certificate
VPS Vice President Sourcing

SDOM Senior Director Operations Management

DM Director Manufacturing
SMP Senior Manager Production
SDQ Senior Director Quality

DQ Director Quality

SQM Senior Manager Quality