

Chapuis, Bruno UTCFS

De: Chapuis, Bruno UTCFS
Envoyé: mercredi 19 août 2009 17:37
À: Benis, Stephane UTCFS; Besson, Boris UTCFS; Ehrhardt, Philippe UTCFS; Guerin, Loic UTCFS; Lepevedic, Stephane UTCFS; Maire, Thierry UTCFS; Rebours, Alain UTCFS; Rothier, Patrick UTCFS; Da Cruz, Gilbert UTCFS; De Sousa, Acurcio Chubb Securite; Khensous, Nordine UTCFS; Bares, Laurent Chubb Securite; Beaubreuil, Jean-Louis Chubb Securite; Casales, Bernard UTCFS; Gaillard, Michel Chubb Securite; Garino, Gilles UTCFS; Kientz, Brigitte Chubb Securite; Lafforgue, Benoit UTCFS; Lotode, Stephane UTCFS; Martin, Gerard UTCFS; Perre, Michel Chubb Securite; Romo, Bernard UTCFS; Barth, Christophe UTCFS; Hebert, Serge UTCFS; Hideux, Sebastien UTCFS; Pautremat, Patrick UTCFS; Richard, Patrick UTCFS; Schoepf, Pascal UTCFS; Senot, Laurent UTCFS; Sztajnowski, Florent UTCFS; Vachon, Alain UTCFS; da silva, Mario UTCFS; Hochard, Sebastien UTCFS; Oliveira, Auguste UTCFS; Bienvenu, jerome UTCFS; Carillo, Patrick UTCFS; Crapanzano, David UTCFS; Durand, Michel Chubb Securite; Ferreira, Jean-Michel UTCFS; Gaillard, Herve UTCFS; Guillot, Michel UTCFS; Szymczak, Gerard UTCFS
Cc: Dufeutrelle, Gerard UTCFS; Detriche, Philippe UTCFS; Lambert, Jean-Marc UTCFS; Locteau, Patrice UTCFS; Bourson, Lionel UTCFS; Gratadeix, Christophe Chubb Securite; Hesry, Olivier Chubb Securite; Morel, Philippe UTCFS; Rhie, Olivier UTCFS; Allais, Daniel UTCFS; Anxionnat, Bertrand UTCFS; Basecq, Frederic UTCFS; Castellant, Jean UTCFS; Elui, Eric UTCFS; Lajarrige, Jerome UTCFS; Lapuyade, Franck UTCFS; Legrand, Ludovic UTCFS; Marcouyeux, Alain UTCFS; Normand, Yves UTCFS; Cartel, Maryvonne UTCFS; Grard, Guy UTCFS; Legoff, Jean-Luc UTCFS; Muller, Jean-Louis UTCFS; Perez, Jose UTCFS; Rabusseau, Loic UTCFS; Becker, Cyrille UTCFS; Bonnard, Sylvain UTCFS; Quelin, Francis UTCFS; Balligand, Frank UTCFS; Berne, Pierre-Jean Chubb Securite; Falomir, Stefan Chubb Securite; Giquel, Christian UTCFS; Mouzet, Pierre-Yves Chubb Securite
Objet: Flash info DCS : Evolution carte UAI I-Scan et UTI 1 et 2 Bus
Importance: Haute



Flash Info D.C.S



Bonjour,

La carte UAI 2B IScan (CE10397) ainsi que les cartes mère UTI 1 et 2 Bus (CE10413 et CE10415) ont été modifiées :

- ▶ Modification de la valeur de résistances évitant un dysfonctionnement potentiel lors de court-circuit sur le bus,
- ▶ évolution du logiciel U21 qui passe en V4.24 permettant :
 - la reconnaissance des détecteurs linéaires 6500F et 6500FS,
 - la reconnaissance des détecteurs laser Scan,
 - la correction sur l'inversion des sensibilités des détecteurs laser Scan

Les cartes modifiées sont maintenant à l'édition 0002 pour les CE10397 et 0003 pour les CE0010413 – CE10415

Les stocks de cartes neuves et SAV ont été remis à niveau

Merci de diffuser largement cette information auprès de tous vos collaborateurs

A votre disposition pour tout complément d'information,

La Direction Chantiers & Services

Pour mémoire, tous les Flash Infos D.C.S sont accessibles sur <\\10.65.0.067\data\Direction Chantiers & Services\07 - Documents Métiers Partagés\11-Flash Infos DCS>

Historique des versions logiciels : \\10.65.0.67\data\Direction Chantiers & Services\07 - Documents Métiers Partagés\01-Incendie\05-Gamme_RESONANCE\suivi-versions.xls