

De: Chapuis, Bruno CCS
Envoyé: jeudi 2 août 2012 17:17
À: Adrien, Bruno Chubb Securite; Casales, Bernard CCS; Guermache, Abdes
Chubb Securite; Hochard, Sebastien CCS; Locteau, Patrice CCS; Cressant,
Sebastien CCS; Da Cruz, Gilbert CCS; Ehrhardt, Philippe CCS; Guerin, Loic
CCS; Maire, Thierry CCS; Senot, Laurent CCS; Lepevedic, Stephane CCS;
Lusic, Bruce Chubb Securite; Rojo, Raphael CCS; Rotthier, Patrick CCS;
Bouhours, Samuel CCS; Boulet, Eric CCS; Crapanzano, David CCS;
Lafforgue, Benoit CCS; Bares, Laurent Chubb Securite; Lotode, Stephane
CCS; Richard, Patrick CCS; Colombo, Eric CCS; da silva, Mario CCS;
Sarpon, Raynald UTCFS; Nageotte, Patrick CCS; Schoepf, Pascal CCS;
Tottet, Janick CCS; Vachon, Alain CCS; Bertrand, Renald CCS; Boiche,
Marc CCS; Demaret, Damien CCS; Hebert, Serge CCS; Lemerre,
Charlotte CCS; Pautremat, Patrick CCS; Guillot, Michel CCS; Perre, Michel
Chubb Securite; Schweizer, William CCS; Viard, Christophe CCS; Beaubreuil, Jean-
Louis Chubb Securite; Borsova, Daniel CCS; Ferreira, Jean-Michel CCS; Gaillard,
Herve CCS; Kientz, Brigitte Chubb Securite; Patry, Laurent CCS
Dujardin, Eric CCS; Marcouyeux, Alain CCS; Mellier, Johnny CCS; Caron,
Pierre-Nicolas CCS; Couprie, Gilles Chubb Securite; Detriche, Philippe CCS;
Khensous, Nordine CCS; Langevin, Emmanuel CCS; Laparade, Pascale CCS;
Lochon, Sylvain CCS; Silva-Branco, Laurent CCS; Simon, Alexandre CCS;
Soboleff, Marc CCS; Angoso, Vincent CCS; De Brito, Jose CCS;
Chauveau, Simon CCS; Deiss, Marc CCS; Dridi, Makrem CCS; Garino,
Gilles CCS; MARTIN, Regis RM CCS; Pamies, Laurent CCS; Anxionnat,
Bertrand CCS; Basecq, Frederic CCS; Lajarrige, Jerome CCS; Normand, Yves
CCS; Talabot, Julien CCS; Balouzet, Rodolphe CCS; Besson, Boris CCS;
Devos, Sylvain Chubb Securite; Dosne, Patrick CCS; Dujardin, Herve
CCS; FAVIER, Eric CCS; Giotta, Paolo CCS; Leroux, Yves CCS;
Louis, Patrick CCS; Sarraiha, Yohann Chubb Securite; savonnet, x CCS
Objet: Flash info Technique : Rappel sur les codes SAV UTI V3 présent dans le PDA

Importance:

Haute



Bonjour,

Suite à quelques confusions en agence, je vous rappelle les codes SAV des modules UTI V2 et V3 présent dans le PDA :

- 7 651 617 : Module UTI V2
- 7 653 617 : Module UTI V3

Merci d'en tenir compte lors de vos commandes SAV et de ne pas remplacer les modules V3 par des modules V2 (Resonance V3 étant maintenant fiable depuis de nombreux mois)

De même, la carte bornier CE01003 n'apparaît dans le PDA : les codes associés sont :

- 630 000 024 : Bornier Chantier CMSI V3 COFFRET
- 630 000 124 : Bornier Chantier CMSI V3 RACK

Merci de diffuser largement cette information auprès de tous vos collaborateurs

A votre disposition pour tout complément d'information,

Bruno CHAPUIS

Pour mémoire, tous les Flashes Infos Technique, les versions logiciels et l'historique des versions sont accessibles l'intranet Chubb, Direction Chantiers & Services : [lien](#)

Rappel : copier facilement les dernières versions logiciels Resonance à jour en cliquant ici : [lien](#)