

Test Report

Date: Jun.09, 2021





Page 1 of 3

Report No.: SFT21060721613-03-02E

Applicant: ALLWINNER TECHNOLOGY CO.,LTD

Address: NO.9 TECHNOLOGY ROAD 2,HIGH-TECH ZONE,ZHUHAI GUANGDONG CHINA

The following merchandise was (were) submitted and identified by client as:

Sample Name: T113-S3 Model No.: T113-S3

Test Period: From Jun.07, 2021 to Jun.09, 2021

SUMMARY OF TEST RESULTS

TEST REQUESTED	2	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	1	CONCLUSION
Halogen free requirement in Standard IEC 61249-2-21:2003 – Halogen			PASS	

Test Result(s): Please refer to next page(s).

mcocc,

"OCOCCI

"OCOCCI

"OCOCCI

illococci

JIIOCOCC.

SOCCY,

Signed for and on Behalf of SFT

Jack Zhong / Technical Manager Guangdong Safety Testing Co., Ltd.

Unless otherwise stated the results shown in this report refer only to the sample(s) tested. This test report cannot be reproduced, except in full. Without prior written permission of the company,

Guangdong Safety Testing Co., Ltd.

No.1, the 1st North Industry Road, Songshan Lake Sci.&Tech. Park, Dongguan, Guangdong, China

l:86-769-23105888 Fax: 86-769-22899858 http://www.sft-cert.com/



Test Report

Date: Jun.09, 202





Page 2 of 3

Report No.: SFT21060721613-03-02E

Test Result(s):

Halogens Content

Test Method: EN 14582:2016, analysis was performed by Ion Chromatograph(IC).

	GY :	Limit (mg/kg)		
Analyte				
	1	-	7.	
Fluorine(F)	ND	/5/	1 -	,5-
Chlorine(Cl)	ND	- / -	Z -	900
Bromine(Br)	ND	- \ - \	/ · · · · ·	900
Iodine(I)	ND	2 - 6	A	
Chlorine(Cl) + Bromine(Br)	ND	- CC - C	.00	1500
Conclusion	PASS	O C I IIIO	- Jillo	-11100

Note / Key: ND = Not detected

mg/kg = milligrams per kilogram (ppm=parts per million)

Report Limit (mg/kg): 50

Remark : The presence of insoluble halide sulfates in the initial sample or in the combustion step can not be fully

analyzed by this method.

Test Component	Sample Description/ Location	5	Style
1	Black solid (T113-S3)		0-1

"OCOCCI

"oco^c

"ococci

occi moc

"OCOCY

Unless otherwise stated the results shown in this report refer only to the sample(s) tested. This test report cannot be reproduced, except in full. Without prior written permission of the company,

Guangdong Safety Testing Co., Ltd.

No.1, the 1st North Industry Road, Songshan Lake Sci.&Tech. Park, Dongguan, Guangdong, China

el:86-769-23105888 Fax: 86-769-22899858

http://www.sft-cert.com/

Moco

a Jillo COC



Report No.: SFT21060721613-03-02E

Test Report






Page 3 of 3

Date: Jun.09, 2021

Photo of Sample



End of Report

cocci

"OCOCC.

"Ococo,

"OCOCC,

"OCOCC,

COCCI

Unless otherwise stated the results shown in this report refer only to the sample(s) tested. This test report cannot be reproduced, except in full. Without prior written permission of the company,

Guangdong Safety Testing Co., Ltd.

No.1, the 1st North Industry Road, Songshan Lake Sci.&Tech. Park, Dongguan, Guangdong, China

000 C 1 dx. 50 7 65 22

http://www.sft-cert.com/

rullOCO

S WIN

MINOCO