Stewardship for Bethel Branch

Lead Steward: Andrea

2022-09-09

Boundary Issues



Channel Issues

Year	Subtype	Issue	Description
2022	Channel Stability/Erosion		
2022	Failed Structure		
2022	Failed Structure		Blown out bank
2022	Failed Structure		Eroding brush tie
2021	Channel Stability/Erosion		bank weakening, sloughing, cracking
2021	Channel Stability/Erosion	Erosion_Scour	Erosion. Needs plugs and stakes if they work in bedrock

Vegetation Issues

Year Issue	Description	Treatment	TreatDate
2022 Low Stem Density	fescue competition	supplemental planting of 50 1-gal container trees	03/2022
2022 Low Stem	stems planted late and suppressed by		
Vigor/Height & Density	undesired vegetation		
2022 Low Stem			
Vigor/Height			
2022 Low Stem	Plant 30 5-gallon trees		
${\it Vigor/Height~\&}$	Ü		
Density			
2021 Low Stem	dense weeds suppressing trees	ring sprays around trees and foliar spray to	
Vigor/Height &			
Density			
2021 Bare Areas & Low	Size is smaller in growing season.	seeding temp & perm mix and added soil amendments: lime,	04/2021
Stem Vigor/Height	Walked bigger winter perimeter.	Carbon ProG, 17-17-17, Humic+, Azomite, molasses, peat moss	
2021 Bare Areas & Low	Size is smaller in growing season.	temporary seed	08/2021
Stem Vigor/Height	Walked bigger winter perimeter.		

Weed Issues

Year	Species1	Issue
2022	Chinese Privet	
2022	Chinese Privet	
2022	Chinese Privet	
2022	Chinese Privet	Small Privet
2022	Japanese Honeysuckle	
2022	Japanese Honeysuckle	Loja canopy
2022	Multiflora Rose	
2022	OTHER	Murdannia
2022	Tree Of Heaven	

Miscellaneous Issues

Year	Subtype	Issue_Desc
2022	Misc	Needs Plugs
2022	Soil Sample	BUT33
2022	Soil Sample	UT1-SS2 BA
2022	Soil Sample	UT1-SS1
2022	Misc	Corners on Moon Lindley- No signs