Stewardship for Double H

Lead Steward: Sam

2022-09-07

Boundary Issues

Channel Issues

Year	Subtype	Issue	Issue_Desc	Treated
	Failed Structure Failed Structure	Piping	Right bank, in front of Boulder toe, has collapsed	No No

Vegetation Issues

Year	Issue	Treated
2022	Bare Areas	No

Weed Issues

Year	Species1	Species2	Issue
2022	Multiflora Rose	OTHER	Thistle
2022	Multiflora Rose	Oriental Bittersweet	
2022	Multiflora Rose	Oriental Bittersweet	
2022	Multiflora Rose	Japanese Barberry	
2022	Multiflora Rose	Oriental Bittersweet	Bittersweet resprouts
2022	Multiflora Rose		
2022	Multiflora Rose	Oriental Bittersweet	
2022	Multiflora Rose	Oriental Bittersweet	Numerous bittersweet resprouts
2022	Multiflora Rose	Oriental Bittersweet	
2022	Multiflora Rose	Chinese Privet	
2022	Multiflora Rose	Oriental Bittersweet	
2022	Multiflora Rose		
2022	Multiflora Rose	Chinese Privet	

Year	Species1	Species2	Issue
2022 2022	Oriental Bittersweet Oriental Bittersweet		

Miscellaneous Issues

Year	Subtype	Issue_Desc	Treated
2022	Misc	Downed tree. Is not affecting flow currently	No