Stewardship for Cross Creek

Lead Steward: Sam


2023-12-18

Boundary Issues

Channel Issues

OBJECTID	Year	Subtype	Issue	Description	Resolved
1152	2023	Failed Structure	Piping		No
622	2022	Failed Structure		Monitor step pool system for headcutting issues	No
755	2022	Failed Structure	Piping		No

Channel Issues (points)




Vegetation Issues


Weed Issues

OBJECTID	Year	Species1	Species2	Resolved
1110	2023	Blackberry		No
1393	2023	Chinese Privet		No
1394	2023	Chinese Privet		No
1153	2023	Princess Tree		No
688	2022	Chinese Privet		No
689	2022	Chinese Privet	Multiflora Rose	No
690	2022	Chinese Privet	Multiflora Rose	No
691	2022	Chinese Privet	Multiflora Rose	No
692	2022	Chinese Privet		No
693	2022	Chinese Privet		No
694	2022	Chinese Privet		No
911	2022	Chinese Privet		No
995	2022	Chinese Privet		No
996	2022	Chinese Privet	Multiflora Rose	No
397	2022	Chinese Privet	Multiflora Rose	No
398	2022	Chinese Privet		No
759	2022	Tree Of Heaven		No


Weed Issues – Blackberry




Weed Issues - Chinese Privet



Weed Issues - Princess Tree




Weed Issues – Tree Of Heaven



Miscellaneous Issues

OBJECTID	Year	Subtype	Description	Resolved
1045	2023	Misc	Log debris	No
760	2022	Misc	Mid channel bar	Yes
756	2022	Misc	Downed tree	No
757	2022	Misc		No
758	2022	Beaver Dam		No
868	2022	Misc		No
869	2022	Misc	Tree on fence	No

Miscellaneous - Beaver Dam



Miscellaneous Issues

