Stewardship for Holman Mill

Lead Steward: Andrea

2022-09-09

Boundary Issues



Channel Issues

Year	Subtype	Issue Issue_Desc
2021	Channel Stability/Erosion	Erosion_Scour headcut and widening pool possibly caused by fallen branches in channel. Branches removed at time of inspection

Vegetation Issues

Year	Issue	Issue_Desc	Treatment
2021	Low Stem Vigor/Height & Density	low tree density, some low height	17-17-17 fertilizer tree booster
2021	Low Stem Vigor/Height & Density	low stem density and tree height	tree boosters with fertilizer, humic+, biochar, lime, molasses
2021	Low Stem Vigor/Height & Density	low tree density, some low height	tree boosters: lime, biochar, humic+, Carbon Pro G, molasses

Weed Issues

Year	Species1	Species2	Issue	Treatment	Method	TreatDate
2021	Chinese	Japanese	scattered stems throughout. Fenceline cannot be			
	Lantern	Honeysuckle	treated with chemical			
2021	Japanese	Chinese Privet	Honeysuckle throughout, scattered stems of woody	Japanese honeysuckle	Backpack	07/2021
	Honeysuckle		invasives, dense fescue	treatment	Spray	,
2021	Japanese	Callery Pear	Low density scattered stems. Honeysuckle requires	cut stump and foliar	Backpack	07/2021
	Honeysuckle	v	most attention.	•	Spray	,
2021	Japanese	Multiflora	Dense on fencelines (organic farm)	cut along fencelines. No	Other	04/2021
	Honeysuckle	Rose		herbicide		,
2021	Tree Of		scattered saplings	ring sprays & honeysuckle	Backpack	03/2021
	Heaven		1 0	treatment	Spray	,
2021	Tree Of		scattered small stems		- 0	
	Heaven					

Miscellaneous Issues

Year	Subtype	Issue_Desc
2022	Misc	Debris jam
2022	Misc	Potential debris jam