Stewardship for Double H

Lead Steward: Sam

2022-09-09

Boundary Issues



Channel Issues

Year	Subtype	Issue	Issue_Desc
_	Failed Structure Failed Structure	Piping	Right bank, in front of Boulder toe, has collapsed

Vegetation Issues

Year	Issue
2022	Bare Areas

Weed Issues

Year	Species1	Species2	Issue
2022	Multiflora Rose	Oriental Bittersweet	Small bittersweet sprouts throughout the wooded area
2022	Multiflora Rose		
2022	Multiflora Rose		
2022	Multiflora Rose	Japanese Barberry	
2022	Multiflora Rose		
2022	Multiflora Rose		
2022	Multiflora Rose	Oriental Bittersweet	
2022	Multiflora Rose	Oriental Bittersweet	
2022	Multiflora Rose	Oriental Bittersweet	
2022	Multiflora Rose	Chinese Privet	
2022	Multiflora Rose	Oriental Bittersweet	
2022	Multiflora Rose		
2022	Multiflora Rose	Chinese Privet	
2022	Oriental Bittersweet		
2022	Oriental Bittersweet		

Miscellaneous Issues

Year	Subtype	Issue_Desc
2022	Misc	Downed tree. Is not affecting flow currently