Stewardship for Cross Creek Ranch

Lead Steward: Sam

2022-09-27

Boundary Issues

 $||\ ||\ ||\ ||$

Channel Issues

| Year | Subtype | Issue | Resolved |
|------|------------------|--------|----------|
| 2022 | Failed Structure | Piping | No |

Vegetation Issues

Weed Issues

| Year | Species1 | Species2 | Resolved |
|------|----------------|-----------------|----------|
| 2022 | Chinese Privet | | No |
| 2022 | Chinese Privet | Multiflora Rose | No |
| 2022 | Chinese Privet | Multiflora Rose | No |
| 2022 | Chinese Privet | Multiflora Rose | No |
| 2022 | Chinese Privet | | No |
| 2022 | Chinese Privet | | No |
| 2022 | Chinese Privet | | No |
| 2022 | Chinese Privet | | No |
| 2022 | Chinese Privet | Multiflora Rose | No |
| 2022 | Chinese Privet | | No |
| 2022 | Tree Of Heaven | | No |
| 2021 | Chinese Privet | | No |

Miscellaneous Issues

| Year | Subtype | Issue_Desc | Resolved |
|------|------------|---|----------|
| 2022 | Misc | Mid channel bar | Yes |
| 2022 | Misc | | No |
| 2022 | Misc | Monitor step pool system for headcutting issues | No |
| 2022 | Misc | Downed tree | No |
| 2022 | Misc | | No |
| 2022 | Beaver Dam | | No |