# Stewardship for Firestone


Lead Steward: Sam

2023-12-18

## Boundary Issues

OBJECTID	Year	Issue	Description	Resolved
1156	2023			No
1185	2023	Other	Riprap encroachment	No
1186	2023	Other	Riprap encroachment	No
1187	2023	Cattle	Fencing allows cattle access	No
1304	2023	Mowing	Mowing and equipment	No


## Boundary Issues (polygons)




## Channel Issues

OBJECTID	Year	Subtype	Issue	Description	Resolved
1076	2023	Channel Stability/Erosion	ErosionScour	Rb erosion 3ft	No
1077	2023	Channel Stability/Erosion	ErosionScour	Lb 5ft	No
1359	2023	Failed Structure	Failed/Not Functional		No

## Channel Issues (points)



## Channel Issues (lines)




### Vegetation Issues


#### Weed Issues

OBJECTID	Year	Species1	Species2	Issue	Treatment	Method	${\bf TreatDate}$	Resolved
1144	2023	Bamboo		Young bamboo	Bamboo sprouts removed and treated beyond bamboo barrier		07/2023	No
1147	2023	Chinese Privet	Tree Of Heaven	Privet, toh		Cut Stump	11/2023	Yes
1253	2023	Chinese Privet		Privet		Cut Stump	11/2023	Yes
1146	2023	Chinese Privet	Multiflora Rose	Privet, mfr, honey suckle				No
1148	2023	Japanese Honeysuckle	Chinese Privet	Hs, privet		Cut Stump	11/2023	Yes
1149	2023	Japanese Honeysuckle	Chinese Privet	Hs, privet		Cut Stump	11/2023	Yes
476	2023	Multiflora Rose	Japanese Honeysuckle					No
1252	2023	Multiflora Rose		Mfr				No
1145	2023	Tree Of Heaven		Mature Tree of Heaven, sprouts TOH	6 mature tree of heavens treated with hack and squirt		07/2023	No
474	2021	Tree Of Heaven	Chinese Privet		Larger TOH treated with cut stump. Partial foliar treatment of smaller. Will need second treatment.		07/2023	No
213	2021	Tree Of Heaven						No


## Weed Issues - Bamboo




## Weed Issues - Chinese Privet




Weed Issues – Japanese Honeysuckle



Weed Issues - Multiflora Rose




Weed Issues - Tree Of Heaven



### Miscellaneous Issues

OBJECTID	Year	Subtype	Description	Resolved
1251	2023	Misc	Major slump	No
1494	2023	Misc	Remove metal debris	No
1574	2023	Misc	UP2S pp1	No
1575	2023	Misc	UP2S pp2	No
1576	2023	Misc	UP2S pp3	No
1577	2023	Misc	UP2S pp4	No
1578	2023	Misc	UP2S pp5	No
1579	2023	Misc	UP2S pp6	No
1580	2023	Misc	UP2S pp7	No
1581	2023	Misc	UP2S pp8	No
1582	2023	Misc	UP2S pp9	No
1583	2023	Misc	UP2S pp10	No
1584	2023	Misc	UP2S PP11	No
1586	2023	Misc	UP2S pp12	No
1587	2023	Misc	UP2S pp13,14	No
1589	2023	Misc	UP2S pp15	No
1700	2023	Misc	Wet area begin	No
			wet area begin	
1701	2023 $2023$	Misc Misc		No No
1702 1703	2023	Misc		No
1704	2023	Misc		No
1705	2023	Misc		No
1706	2023	Misc		No
1707	2023	Misc	Wet area 2 start	No
1708	2023	Misc		No
1709	2023	Misc		No
1710	2023	Misc		No
1711	2023	Misc		No
1712	2023	Misc		No
1713	2023	Misc		No
1714	2023	Misc		No
1715	2023	Misc		No
1716	2023	Misc		No
1717	2023	Misc		No
1718	2023	Misc		No
1719	2023	Misc		No
1720	2023	Misc		No
1721	2023	Misc		No
1722	2023	Misc		No
1723	2023	Misc		No
1724	2023	Misc		No
1724	2023	Misc		No
1726	2023	Misc		No
463	2023 $2022$	Misc	Arundinaria. Make a zone. Expand	No
400	2022	111100	into buffer	110
705	2022	Soil Sample	Soil Sample 1	
706	2022	Soil Sample	Soil sample 4	
707	2022	Soil Sample	Sample 2	
708	2022	Soil Sample	Sample 5	
709	2022	Soil Sample	Soil sample 6	
710	2022	Soil Sample	Soil sample 7	
711	2022	Soil Sample	Soil Sample	
111	2022	Son Sample	Son Sample	

## Miscellaneous - Soil Samples



## Miscellaneous Issues

•

463