Stewardship for Critcher

Lead Steward: Emily

2022-09-09

Boundary Issues

Year	Issue	Issue_Desc	Treatment
2022	Other	Fence incomplete	Patched bottom of fence
2022	Debris	Tree fell on fence	
2022	Debris	Tree fell on fence	
2022	Cattle	Cow jumped fence	
2022	Debris	Dead tree fell on fence. Need chainsaw to cut and repair.	
2022	Debris	Boundary tree knocked over	
2022	Debris	Debris popped fencing off posts.	
2021		Signage added to potential encroachment area	

Channel Issues

Year	Subtype	Issue	Description
2022	Failed Structure	Erosion/Scoured	Erosion behind log keyed in bank
2022	Failed Structure		Channel incision and piping under large boulder in riffle d/s PP49
2022	Failed Structure		Flow over log sill but piping under rock immediately d/s
2021	Needs Livestakes		Needs live stakes both sides
2021	Needs Livestakes		Needs live stakes (a quarter of original quantities)
2021	Channel Stability/Erosion	Aggradation_Deposition	
2021	Needs Livestakes		Needs live stakes at least along right floodplain

Year	Subtype	Issue	Description
2021	Failed Structure	Failed/Not Functional	Piping under log sill

Vegetation Issues

Year Issue	Description	Treatment	TreatDate
2022 Bare Areas			
2022 Bare Areas &			
Low Stem			
Density			
2022Bare Areas &			
Low Stem			
Density			
2022	Erosion and headcut from bank to floodplain		
2022	Erosion		
2021	Timber slash across CE by logging violation	Staff removed slash from timber operation but allowed pre-existing debris to remain. Slash was scattered within and outside the easement.	11/2021
2021 Bare Areas	Reseeding needed		
2021 Bare Areas	Reseeding needed		
2021	Gully forming and slumping. Need to rework		
	ground, reseed, and stabilize.		
2021 Bare Areas	Reseeding needed		
2021 Bare Areas	Reseeding needed		
2021 Bare Areas	Easement ran over by machinery, including t-post.		
	Need to at least reseed. (Area was originally not planted)		

Weed Issues

Year	Species1	Species2	Issue
2022	Chinese Privet	Chinese Yam	
2022	Chinese Privet	Japanese Honeysuckle	
2022	Japanese Honeysuckle	Chinese Privet	
2022	Kudzu		
2022	Marsh Dewflower		Murdannia in wetland
2022	Multiflora Rose	Chinese Privet	
2022	OTHER		
2022	OTHER		Harlequin glorybower
2022	Reed Canary Grass		
2022			
2022			
2022			
2022			
2022			
2022			
2022			
2021	Chinese Privet		Privet patch
2021	Reed Canary Grass		
2021			Murdannia
2020	Chinese Privet		Scattered
2020	Chinese Privet		

Miscellaneous Issues

Year	Subtype	Issue_Desc
2022	Misc	LO barbed wire and t-post fence is down in multiple spots due to dead trees. Cattle in CE as result.
2022	Beaver Dam	
2021	Misc	PP 24
2021	Misc	PP 2
2021	Misc	PP 5
2021	Misc	PP 8
2021	Misc	PP 11
2021	Misc	PP 14

Year	Subtype	Issue_Desc
2021	Misc	PP 17
2021	Misc	PP 20
2021	Misc	PP 26
2021	Misc	PP 34