Stewardship for Huntsman

Lead Steward: Dominic

2022-09-27

Boundary Issues

 $||\ ||\ ||\ ||$

Channel Issues

Year	Subtype	Issue	Description	Resolved
2022	Channel Stability/Erosion			No
2022	Channel Stability/Erosion	Erosion_Scour		No
2022	Channel Stability/Erosion			No
2022	Channel Stability/Erosion			No
2022	Channel Stability/Erosion			No
2022	Channel Stability/Erosion			No
2022	Failed Structure		Banks eroding on both sides of log sill.	No

Vegetation Issues

Year	Description	Resolved
2022	Rilling	No
2022	Low vegetation	No
2022	Now veg	No
2022	Low veg	No
2022	Eroded bank	No

Weed Issues

Year	Species1	Species2 I	Issue	Treatment	Method	TreatDa	t&Resolved
2022	Tree Of Heaven	Multiflora Rose		Invasives treatment	Hack and Squirt	09/2021	No
2022				In stream veg spray	-	08/2022	No
2021	Callery Pear					,	No
2021	Callery Pear						No
2021	Chinese	Multiflora		Mechanical removal by machines	Other	02/2022	No
	Privet	Rose		during construction		,	
2021	Chinese	Multiflora		Mechanical removal by machines	Other	02/2022	No
	Privet	Rose		during construction		,	
2021	Chinese			Mechanical removal by machines	Other	02/2022	No
	Privet			during construction		,	
2021	Chinese	Multiflora		Invasives treatment	Backpack	09/2021	No
	Privet	Rose			Spray	,	
2021	Chinese	Japanese		Mechanical removal by machines	Other	02/2022	No
	Privet	Honeysuckle		during construction		,	
2021	Chinese	Multiflora		Invasives treatment	Hack and	09/2021	No
	Privet	Rose			Squirt	,	
2021	Chinese	Multiflora		Invasives treatment	Hack and	09/2021	No
	Privet	Rose			Squirt	,	
2021	Chinese	Multiflora		Invasives treatment	Hack and	09/2021	No
	Privet	Rose			Squirt	,	
2021	Chinese	Multiflora		Mechanical removal by machines	Other	02/2022	No
	Privet	Rose		during construction		,	
2021	Chinese	Japanese		Mechanical removal by machines	Other	02/2022	No
	Privet	Honeysuckle		during construction		,	
2021	Chinese Yam	V		Mechanical removal by machines	Other	02/2022	No
				during construction		- / -	
2021	Japanese			Mechanical removal by machines	Other	02/2022	No
	Honeysuckle			during construction		,	
2021	Japanese			Mechanical removal by machines	Other	02/2022	No
	Honeysuckle			during construction		,	
2021	Japanese	Multiflora		Mechanical removal by machines	Other	03/2022	No
	Honeysuckle	Rose		during construction		/	-
2021	Mimosa			Mechanical removal by machines	Other	02/2022	No
	~ ~ ~ ~			during construction		>=, = > = =	

Year	Species1	Species2	Issue	Treatment	Method	${\bf TreatDat} \\ {\bf Resol}$
2021	Mimosa					No
2021	Multiflora					No
	Rose					
2021	Multiflora					No
	Rose					
2021	Oriental			Invasive treatment	Backpack	09/2021 No
	Bittersweet				Spray	
2021	Oriental			Invasive treatment	Backpack	09/2021 No
	Bittersweet				Spray	
2021	Tree Of		Naturally dead? Was defoliated upon	Invasive treatment	Hack and	09/2021 No
	Heaven		observation (Oct 2020)		Squirt	
2021	Tree Of			TOH treatment	Hack and	09/2021 No
	Heaven				Squirt	
2021	Tree Of	Multiflora		Mechanical removal by machines	Other	02/2022 No
	Heaven	Rose		during construction		
2021				TOH treatment	Hack and	09/2021 No
	Heaven				Squirt	
2021	Tree Of	Multiflora		Invasives treatment	Hack and	09/2021 No
	Heaven	Rose			Squirt	
2021			Alligator Weed	Instream Veg Spray		08/2022 No

Miscellaneous Issues

Year	Subtype	Issue_Desc	Resolved
2022	Soil Sample	Soil sample 01	na
2022	Soil Sample	Soil sample 01	na
2022	Soil Sample	Soil sample 02	na
2022	Soil Sample	Soil sample 03	na
2022	Soil Sample	Soil sample 04	na
2022	Soil Sample	Soil sample 05	na
2022	Soil Sample	Soil sample 06	na
2022	Soil Sample	Soil sample 07	na
2022	Soil Sample	Soil sample 08	na
2021	Soil Sample	HBH4-2	na
2021	Soil Sample	HBH3-2	na

Year	Subtype	Issue_Desc	Resolved
2021	Soil Sample	HBH1 -3'	na
2021	Soil Sample	HBH2-3'	na
2021	Soil Sample	HBH5-2	na
2021	Soil Sample	HBH6-2	na
2021	Soil Sample	HBH8-3	na
2021	Soil Sample	HBH7 -3	na
2021	Soil Sample	HBH10-3	na
2021	Soil Sample	HBH9-3	na