# Stewardship for Lyon Hills

Lead Steward: Emily

2022-10-17

### **Boundary Issues**

Year	Issue	Issue_Desc	Resolved
2022		Hay bales rolled through fence. Farmer patched fence. Hay bales still in stream	No
2022	Debris	Tree fell on fence	No
2021	Cattle	Cattle stepping into easement around creek crossing	No

### Channel Issues

Year	Subtype	Issue	Description	Resolved
2022	Needs Livestakes			Yes
2022	Needs Livestakes			Yes
2022	Needs Livestakes		Low wet area draining from field.	Yes
2022	Failed Structure			No
2022	Failed Structure		Slumping after Boulder toe	No
2022	Failed Structure			No
2022	Failed Structure		Piping. Put some small rocks in; made a slight improvement	No
2021	Needs Livestakes			Yes
2021	Needs Livestakes			Yes
2021	Needs Livestakes		Needs livestakes	No
2021	Needs Livestakes		Needs livestakes	No
2021	Needs Livestakes		Needs livestakes	No
2021	Needs Livestakes		Needs livestakes around structures	No

Year	Subtype	Issue	Description	Resolved
2021	Needs Livestakes		Needs livestakes on meander bend	No
2021	Needs Livestakes		Needs livestakes on right bank	No
2021	Needs Livestakes		Needs livestakes on left bank (maybe right bank, too)	No
2021	Channel	Erosion_Scour	Erosion and Aggradation	No
	Stability/Erosion			
2021	Channel	Erosion_Scour		No
	Stability/Erosion			
2021	Failed Structure		Failed log sill. Undercutting. Disconnected from grade? And no splash rock to reduce drop.	No
2021	Failed Structure	Failed/Not	Failed j-hook	No
		Functional		
2021	Failed Structure	Failed/Not	Too high	No
		Functional		

## Vegetation Issues

Year	Issue	Description	Treatment	TreatDate	Resolved
2022		Low stem density/bare area	Summer seed mix (millet, clover, humic plus)	05/2022	No
2022		Bare area	Summer seed mix (millet, clover, humic plus)	05/2022	No
2022	Bare Areas & Low Stem		Summer seed mix (millet, clover, humic plus)	05/2022	No
	Density				
2022		Bare area	Summer seed mix (millet, clover, humic plus)	05/2022	No
2021	Bare Areas & Low Stem	Bare areas and some rilling	Summer seed mix (millet, clover, humic plus)	05/2022	No
	Density				
2021	Bare Areas		Summer seed mix (millet, clover, humic plus)	05/2022	No
2021	Bare Areas		Summer seed mix (millet, clover, humic plus)	05/2022	No
2021	Bare Areas	Bare area	Summer seed mix (millet, clover, humic plus)	05/2022	No
2021	Bare Areas & Low Stem		Summer seed mix (millet, clover, humic plus)	05/2022	No
	Density				
2021	Bare Areas	Bare area	Summer seed mix (millet, clover, humic plus)	05/2022	No

### Weed Issues

Year	Species1	Species2	Issue	Treatment	Method	TreatDa	teResolve
	Kudzu						No
	OTHER		Cattails				No
	Princess Tree						No
-	Princess Tree			<b>Q</b>	<b>C</b> .	00 /0001	No
	Chinese Privet			Cut stump	$\operatorname{Cut}$ $\operatorname{Stump}$	09/2021	
2021	Chinese Privet	Oriental Bittersweet		Cut stump BS, privet, HS	Cut Stump	09/2021	No
2021	Chinese Privet	Oriental Bittersweet		,	•		No
2021	Chinese Privet	2100015 11 000					No
2021		Multiflora Rose	Isolated multiflora occurrence at top of right bank and mature privet on stream bank				No
2021	Chinese Privet	nose	mature privet on stream bank				No
	Japanese Japanese	Multiflora					No
2021	Honeysuckle	Rose					NO
2021	Japanese	Oriental					No
2021	Honeysuckle	Bittersweet					110
2021	Multiflora	Oriental		Cut stump	Cut	09/2021	Yes
2021	Rose	Bittersweet		c at stamp	Stump	00/2021	105
2021	Multiflora	Oriental	All invasives listed plus honeysuckle. Lots of dense	Cut stump	Cut	09/2021	No
	Rose	Bittersweet	climbing vines at top of reach.	о и и и и и и и и и и и и и и и и и и и	Stump	00/-0	
2021	Oriental		Huge BS vine	Cut stump	Cut	09/2021	Yes
	Bittersweet			1	Stump	,	
2021	Oriental	Multiflora	Climbing BS and isolated MF	Cut stump	Cut	09/2021	Yes
	Bittersweet	Rose		•	$\operatorname{Stump}$	,	
2021	Oriental		Large climbing BS	Cut stump vines	Cut	09/2021	Yes
	Bittersweet			-	Stump	,	
2021	Oriental	Chinese Privet		Cut stump	Cut	09/2021	Yes
	Bittersweet				Stump		
2021	Oriental	Chinese Privet		Cut stump	Cut	09/2021	No
	Bittersweet				$\operatorname{Stump}$		
2021	Oriental		Climbing BS in a couple locations on right floodplain				No
	Bittersweet						

Year	Species1	Species2	Issue	Treatment	Method	TreatDat	teResolved
2021	Oriental Bittersweet	Chinese Privet					No
2021	Oriental Bittersweet	Multiflora Rose	Climbing BS and isolated MF				No
2021	Oriental Bittersweet	Chinese Privet	Small invasive cluster along tree line				No
2021	Oriental Bittersweet		Climbing vine				No
2021	Oriental Bittersweet						No
2021	Oriental Bittersweet		6" diameter climbing vine				No
2021	Princess Tree	Tree Of Heaven	Young princess trees and mature TOH	Cut stump	Cut Stump	09/2021	Yes
2021	Princess Tree						No
2021	Tree Of Heaven	OTHER	Canopy TOH and monoculture of Harlequin Glorybower at top of reach	Cut stump	$\operatorname{Cut}$ $\operatorname{Stump}$	09/2021	No
2021			In-stream veg	Sprayed	•	09/2021	Yes
2021			In-stream veg with Aggradation	- v		,	No
2021			In-stream veg and Aggradation upstream of culvert				No
2021			1				No
2021							No
2021			In-stream veg				No
2021							No
2021							No
2021							No
2021							No
2021							No

#### Miscellaneous Issues

Year	Subtype	Issue_Desc	Treatment	TreatDate	Resolved
2022	Beaver Dam		Raked by staff	08/2022	No
2022	Misc	Two bales of straw in CE. In-stream			No
2021	Misc	Hunting tree stands			No

Year	Subtype	Issue_Desc	Treatment	TreatDate	Resolved
2021	Misc	Mature Hemlock. Approx 15-18" DBH. Needs treatment.			No
2021	Beaver Dam				No
2021	Misc	Mature Hemlocks need treatment. DBH 12-15"			No