Stewardship for Holman Mill

Lead Steward: Andrea

2022-09-07

Boundary Issues

Channel Issues

Year Subtype	Issue	Issue_Desc	Treated
2021 Channel Sta- bility/Erosion	Erosion_	Schemed and widening pool possibly caused by fallen branches in channel. Branches removed at time of inspection	Partial

Vegetation Issues

Year	Issue	Issue_Desc	Pct_C	oFreated	dTreatment
	Low Stem Vigor/Height & Density	low stem density and tree height	51- 75%	Yes	tree boosters with fertilizer, humic+, biochar, lime, molasses
	Low Stem Vigor/Height & Density	low tree density, some low height	51- 75%	Yes	tree boosters: lime, biochar, humic+, Carbon Pro G, molasses
	Low Stem Vigor/Height & Density	low tree density, some low height	51- 75%	Yes	17-17-17 fertilizer tree booster

Weed Issues

Year Species1	Species2	Issue	Treatment	Method TreatDate
2021 Chinese	Japanese	scattered stems throughout.		
Lantern	Honey- suckle	Fenceline cannot be treated with chemical		
2021 Japanese	Chinese	Honeysuckle throughout, scattered	Japanese	Backpack $07/2021$
Honey- suckle	Privet	stems of woody invasives, dense fescue	honeysuckle treatment	Spray
2021 Japanese	Callery	Low density scattered stems.	cut stump and	Backpack 07/2021
Honey- suckle	Pear	Honeysuckle requires most attention.	foliar	Spray

Year Species1	Species2	Issue	Treatment	Method	TreatDate
2021 Japanese Honey- suckle	Multiflora Rose	Dense on fencelines (organic farm)	cut along fencelines. No herbicide	Other	04/2021
2021 Tree Of Heaven		scattered saplings	ring sprays & honeysuckle treatment	Backpac Spray	k 03/2021
2021 Tree Of Heaven		scattered small stems			

Miscellaneous Issues

Year	Subtype	Issue_Desc	Treated
2022 2022	Misc Misc	Debris jam Potential debris jam	No No
4044	MIISC	i otentiai debris jain	110