Stewardship for Falling Creek

Lead Steward: Andrew

2022-09-07

Boundary Issues

Channel Issues

Year	Subtype	Issue	Issue_Desc	Treated
2022	Needs			No
	Livestakes			
2022	Failed Structure		Confluence reveals incision in main stem	No
2021	Channel Stabil-	Aggradation_De	ephositically in with sand, channel hard to define around	Yes
	ity/Erosion		multi-stem willow. Remove willow?	
2021	Channel Stabil-	Erosion_Scour	Incision and scour	No
	ity/Erosion			
2021	Needs			No
	Livestakes			
2021	Failed Structure	Piping	Piping left side, no fabric. Update: log vane. No action needed $3/14/22$	No
2021	Failed Structure	Other	Needs to pare down	No

Vegetation Issues

 $||\ ||\ ||\ ||$

Weed Issues

Year	Species1	Species2	Issue	Treatment	Method	TreatDate
2022	Blackberry	Chinaberr	ry			
2022	Chinaberry					
2022	Chinese					
	Privet					
2022	Chinese		Lopper size, scattered			
	Privet					
2022	Lespedeza		from contaminated seed mix	foliar	Backpack	06/2022
					Spray	
2022	Lespedeza					

Year	Species1	Species2	Issue	Treatment	Method	TreatDate
2022	OTHER		Remove Willow from channel			
2022	OTHER		cattails			
2021	Chinaberry		Scattered stems			
2021	Chinese		Size classes vary from seedlings to	cut stump	Cut Stump	07/2022
	Privet		saw size	privet		,
2021	Chinese		Some saw sized privet and			
	Privet		seedlings.			
2021	Chinese					
	Privet					
2021	Chinese					
	Privet					
2021	Mimosa		Saw size 1 stem			

Miscellaneous Issues

Year	Subtype	Issue_Desc	Treated
2022	Misc	Needs plugs	No