# Stewardship for Alexander Farm

Lead Steward: Dominic

2023-11-28

## Boundary Issues

OBJECTID	Year	Issue	Description	Resolved
1021	2023		Cow encroachment (tracks and poo)	No
1025	2023	Cattle	Cow encroachment (tracks and manure)	No
1026	2023	Cattle	Cow encroachment (tracks and manure)	No
1027	2023	Cattle	Fallen fencing - cow access point	No

## Channel Issues

OBJECTID	Year	Subtype	Issue	Description	Treatment	TreatDate	Resolved
949	2023	Channel Stability/Erosion	ErosionScour				No
931	2022	Needs Livestakes			live staked	01/2023	Yes
649	2022	Failed Structure		piping			Yes
650	2022	Failed Structure					Yes
777	2022	Channel Stability/Erosion	ErosionScour	Monitor			No
778	2022	Channel Stability/Erosion	SlumpingSettling				No
779	2022	Channel Stability/Erosion	SlumpingSettling				No
481	2022	Failed Structure	Headcut	Head cut forming	live staked	01/2023	No
473	2022	Failed Structure	Piping				No
475	2022	Failed Structure	Piping				No
476	2022	Failed Structure	Piping				No
477	2022	Failed Structure	Dislodged				No
478	2022	Failed Structure	Piping				No
479	2022	Failed Structure	Piping				No
480	2022	Failed Structure	Headcut	Head cut forming			No
651	2022	Failed Structure					No
652	2022	Failed Structure					No
653	2022	Failed Structure					No
153	2021	Failed Structure		Piping			Yes

## Vegetation Issues

## Weed Issues

OBJECTID	Year	Species1	Species2	Issue	Treatment	Method	TreatDate	Resolved
1196	2023	Chinese Privet	Multiflora Rose		cut stump	Cut Stump	07/2023	No
474	2022	Callery Pear	Chinese Privet		cut stump	Cut Stump	09/2022	No
784	2022	Cattail		Cattails				No
923	2022	Chinese Privet			cut stump and foliar spray	Cut Stump	11/2022	No
923	2022	Chinese Privet			cut stump and foliar spray	Cut Stump	04/2023	No
768	2022	Princess Tree			cut stump	Cut Stump	09/2022	No
770	2022	Princess Tree	Chinese Privet					No
914	2022							No
915	2022							No
546	2021	Chinese Privet			cut stump	Cut Stump	07/2023	No
292	2021	Chinese Privet			cut stump and foliar spray	Cut Stump	11/2022	No
259	2021	Chinese Privet	Multiflora Rose					No
260	2021	Chinese Privet						No
300	2021	Chinese Privet						No
151	2021	Multiflora Rose						No
150	2021	Princess Tree					06/2022	Yes
152	2021	Princess Tree			cut stump	Cut Stump	08/2022	Yes
152	2021	Princess Tree					06/2022	Yes
149	2021	Princess Tree					07/2022	Yes
154	2021	Princess Tree					07/2022	Yes
261	2021	Princess Tree						No
438	2021	Tree Of Heaven			Hack n Squirt/Cut Stump w/ triclopyr		09/2021	No
438	2021	Tree Of Heaven			hack and squirt, foliar spray, cut stump	Cut Stump	09/2022	No
262	2021	Tree Of Heaven	Princess Tree		Hack n Squirt/Cut Stump w/ triclopyr		09/2021	No
535	2021							No

## Miscellaneous Issues

OBJECTID	Year	Subtype	Description	Resolved
955	2023	Misc	Pond	No
1193	2023	Beaver Dam		No
1194	2023	Beaver Dam		No
1195	2023	Beaver Dam		No
1196	2023	Beaver Dam		No
1200	2023	Beaver Dam		No
1202	2023	Beaver Dam		No
1203	2023	Beaver Dam		No
1204	2023	Beaver Dam		No
1205	2023	Beaver Dam		No
1206	2023	Beaver Dam		No
1207	2023	Beaver Dam		No
1492	2023	Beaver Dam		No
900	2022	Misc	Downed tree on fence needs removal (chainsaw)	Yes
771	2022	Misc	Streambed dry	No