# Stewardship for Owls Den

Lead Steward: Emily

2023-11-28

## Boundary Issues

OBJECTID	Year	Issue	Description	Resolved
801	2022	Mowing	Scalloping	No

#### Channel Issues

## Vegetation Issues

OBJECTID	Year	Issue	Resolved
571	2022	Low Stem Density	No

#### Weed Issues

OBJECTID	Year	Species1	Species2	Issue	Treatment	Method	${\bf TreatDate}$	Resolved
840	2022	Cattail		Cattails				No
337	2022	Chinese Privet		Single mature privet	Cut stump by staff	Cut Stump	01/2022	Yes
697	2022	Chinese Privet	Japanese Honeysuckle		Staff cut stump privet, MF, Bradford pear, and some HS.	Cut Stump	03/2022	No
338	2022	Chinese Privet	Japanese Honeysuckle					No
696	2022	Japanese Honeysuckle			Staff brush cut privet and HS (left floodplain)	Other	04/2022	No
573	2022	Japanese Honeysuckle		Need to brush cut				No
698	2022	Japanese Honeysuckle						No
331	2022	Japanese Honeysuckle		Climbing HS				No
332	2022	Japanese Honeysuckle						No
333	2022	Japanese Honeysuckle		Climbing HS				No
334	2022	Japanese Honeysuckle		Climbing HS				No
335	2022	Japanese Honeysuckle		Climbing and groundcover HS				No
399	2022	Japanese Honeysuckle						No
400	2022	Japanese Honeysuckle		Climbing vines				No
401	2022	Japanese Honeysuckle		Climbing vines				No
402	2022	Japanese Honeysuckle		Climbing vines and groundcover				No
403	2022	Japanese Honeysuckle		Climbing vines and groundcover				No
178	2021	Chinese Privet	Multiflora Rose					No
175	2021	Climbing Hempvine		Mikania scandens (Climbing Hempvine)	Hempvine Removal		07/2022	No
177	2021	Climbing Hempvine		Mikania scandens (Climbing Hempvine)	Hempvine Removal		07/2022	No
174	2021	Climbing Hempvine		Mikania scandens (Climbing Hempvine)	Hempvine Removal		07/2022	No
176	2021	Japanese Honeysuckle	Chinese Privet					No
543	2021	Japanese Honeysuckle						No
119	2021	Marsh Dewflower		Murdannia and rushes in-stream				No
120	2021	Marsh Dewflower		Murdannia in-stream				No
113	2021	Multiflora Rose		Between two veg plot markers	Staff cut stump multiflora	Cut Stump	03/2022	Yes
114	2019	Chinese Privet		~ -	-	•	•	No
115	2019	Chinese Privet						No

#### Miscellaneous Issues

OBJECTID	Year	Subtype	Description	LocationOrFeature	Treatment	${\bf TreatDate}$	Resolved
763	2022	Beaver Dam	Notched 9/7				Yes
764	2022	Beaver Dam					Yes
542	2022	Beaver Dam			Dam hand removed	05/2022	No
245	2021	Beaver Dam			Raked by staff	12/2021	Yes
246	2021	Beaver Dam			Raked by staff	12/2021	Yes
111	2021	Beaver Dam			Dam check after removal	09/2021	Yes
112	2021	Beaver Dam			Staff removed dam	08/2021	Yes
179	2021	Misc	Aggradation	In-Stream			No
243	2021	Beaver Dam			Raked by staff	12/2021	No
248	2021	Beaver Dam			Raked by staff	12/2021	No
248	2021	Beaver Dam			Raked by staff	05/2022	No
249	2021	Beaver Dam			Raked by staff	12/2021	No
249	2021	Beaver Dam			Raked by staff	01/2022	No
249	2021	Beaver Dam			Raked by staff	02/2022	No
247	2021	Beaver Dam			Raked by staff	12/2021	No
244	2021	Beaver Dam					No
336	2021	Misc	Where initial staff treatment stopped				No
116	2020	Misc	Channel clearing in 2020	In-Stream			No
118	2020	Misc	Channel clearing in 2020				No