# Stewardship for Cool Springs

Lead Steward: Hanna

2023-02-14

## Boundary Issues

#### Channel Issues

Year	Subtype	Issue	Description	Resolved
2022	Channel Stability/Erosion	ErosionScour	ditch eroding into grass swail	No

## Vegetation Issues

#### Weed Issues

### Miscellaneous Issues

Year	Subtype	Description	Resolved
2022	Misc	Pile of rocks	Yes
2022	Misc	Gate	Yes
2022	Misc	Gate	Yes
2022	Misc	Gate	Yes
2022	Misc	Gate	Yes
2022	Misc	Gate	Yes
2022	Misc	Gate	Yes
2022	Misc	Gate	Yes
2022	Misc	Gate	Yes
2022	Misc	Gate	Yes
2022	Misc	Gate	Yes
2022	Misc	Potential repair needed, add riffle material	No
2022	Misc	Keep an eye on high riffle	No
2022	Misc	Keep an eye on log structure	No
2022	Misc	Keep an eye on this, rock shifting	No
2022	Misc	Live stake eroding bank w whatever is most successful	No
2022	Misc	Structure is a candidate for repair	No
2022	Misc	Two structures are candidates for repair	No
2022	Misc	Sill missing filter fabric	No
2022	Soil Sample	SS1	
2022	Soil Sample	SS3	
2022	Soil Sample	SS2	
2022	Soil Sample	CS7	
2022	Soil Sample	CS2	
2022	Soil Sample	CS3	
2022	Soil Sample	CS6	
2022	Soil Sample	CS8; very rocky so samples shallow	



2