Stewardship for Double H

Lead Steward: Sam

2023-02-14

Boundary Issues

Channel Issues

Year	Subtype	Issue	Description	Treatment	${\bf TreatDate}$	Resolved
2022	Failed Structure	Piping		Repair	09/2022	Yes
2022	Failed Structure		Left bank behind Boulder toe has collapsed. Appears to have started piping			No
2022	Failed Structure		Right bank, in front of Boulder toe, has collapsed			No
2022	Failed Structure	Piping				No
2022	Failed Structure	Piping				No
2022	Failed Structure					No
2022	Failed Structure					No
2022	Failed Structure	Piping				No

Vegetation Issues

Year	Issue	Treatment	TreatDate	Resolved
2022	Bare Areas	Seeding/Amendments added	07/2022	No
2022	Bare Areas	Seeding/ Amendments added	07/2022	No
2022	Bare Areas	Stabilization	09/2022	No
2022	Bare Areas			No
2022	Bare Areas			No
2022	Bare Areas			No

Weed Issues

Year	Species1	Species2	Issue	Treatment	Method	TreatDate	Resolved
2022	Japanese Barberry	Oriental Bittersweet		Herbicide	Backpack Spray	09/2022	No
2022	Multiflora Rose	Oriental Bittersweet		Herbicide	Backpack Spray	09/2022	No
2022	Multiflora Rose	Oriental Bittersweet	Small bittersweet sprouts throughout the wooded area	Herbicide	Backpack Spray	09/2022	No
2022	Multiflora Rose	Oriental Bittersweet		Herbicide	Backpack Spray	09/2022	No
2022	Multiflora Rose	OTHER	Thistle	Herbicide Backpack Spray		09/2022	No
2022	Multiflora Rose			Herbicide	Backpack Spray	09/2022	No
2022	Multiflora Rose	Oriental Bittersweet		Pre-construction invasive treatment	Backpack Spray	06/2021	No
2022	Multiflora Rose	Oriental Bittersweet		Bittersweet	Cut Stump	09/2022	No
2022	Multiflora Rose	Oriental Bittersweet		Herbicide	Backpack Spray	09/2022	No
2022	Multiflora Rose						No
2022	Multiflora Rose	Oriental Bittersweet					No
2022	Multiflora Rose	Japanese Barberry					No
2022	Multiflora Rose	Japanese Barberry					No
2022	Multiflora Rose						No
2022	Multiflora Rose	Oriental Bittersweet	Bittersweet resprouts				No
2022	Multiflora Rose						No
2022	Multiflora Rose						No
2022	Multiflora Rose	Oriental Bittersweet					No
2022	Multiflora Rose	Oriental Bittersweet	Numerous bittersweet resprouts				No
2022	Multiflora Rose	Chinese Privet					No
2022	Multiflora Rose	Oriental Bittersweet					No
2022	Multiflora Rose						No
2022	Multiflora Rose						No
2022	Multiflora Rose	Chinese Privet					No
2022	Multiflora Rose						No
2022	Oriental Bittersweet			Herbicide	Backpack Spray	09/2022	No
2022	Oriental Bittersweet						No
2022	Oriental Bittersweet		Resprouts				No

Miscellaneous Issues

Year	Subtype	Description	Resolved
2022	Misc	Culvert eroding away	No
2022	Misc	Downed tree. Is not affecting flow currently	No