Stewardship for Huntsman

Lead Steward: Dominic

2022-10-17

Boundary Issues



Channel Issues

Year	Subtype	Issue	Description	Resolved
2022	Channel Stability/Erosion			No
2022	Channel Stability/Erosion	Erosion_Scour		No
2022	Channel Stability/Erosion			No
2022	Channel Stability/Erosion			No
2022	Channel Stability/Erosion			No
2022	Channel Stability/Erosion	Other	Stream goes under riffle	No
2022	Channel Stability/Erosion	Aggradation_Deposition	Stream channel not obvious	No
2022	Needs Livestakes			No
2022	Failed Structure		Banks eroding on both sides of log sill.	No
	Channel Stability/Erosion		-	No

Vegetation Issues

Year	Issue	Description	Resolved
2022		Rilling	No
2022		Low vegetation	No
2022		Now veg	No
2022		Low veg	No
2022		Eroded bank	No
2022	Bare Areas & Low Stem Density		No

Weed Issues

Year	Species1	Species2	Issue	Treatment	Method	TreatDa	t&Resolved
2022	Tree Of	Multiflora		Invasives treatment	Hack and	09/2021	No
	Heaven	Rose			Squirt	•	
2022	Tree Of	Multiflora		Invasives treatment	Hack and	09/2021	No
	Heaven	Rose			Squirt	,	
2022				In stream veg spray	-	08/2022	No
2021	Callery Pear			Ŭ 1		,	No
2021	Callery Pear						No
2021	Chinese	Multiflora		Mechanical removal by machines	Other	02/2022	No
	Privet	Rose		during construction		,	
2021	Chinese	Multiflora		Mechanical removal by machines	Other	02/2022	No
	Privet	Rose		during construction		,	
2021	Chinese			Mechanical removal by machines	Other	02/2022	No
	Privet			during construction		,	
2021	Chinese	Multiflora		Invasives treatment	Backpack	09/2021	No
	Privet	Rose			Spray	,	
2021	Chinese	Japanese		Mechanical removal by machines	Other	02/2022	No
	Privet	Honeysuckle		during construction		,	
2021	Chinese	Multiflora		Invasives treatment	Hack and	09/2021	No
	Privet	Rose			Squirt	,	
2021	Chinese	Multiflora		Invasives treatment	Hack and	09/2021	No
	Privet	Rose			Squirt		
2021	Chinese	Multiflora		Mechanical removal by machines	Other	02/2022	No
	Privet	Rose		during construction			
2021	Chinese	Japanese		Mechanical removal by machines	Other	02/2022	No
	Privet	Honeysuckle		during construction			
2021	Chinese Yam			Mechanical removal by machines	Other	02/2022	No
				during construction			
2021	Japanese			Mechanical removal by machines	Other	02/2022	No
	Honeysuckle			during construction			
2021	Japanese			Mechanical removal by machines	Other	02/2022	No
	Honeysuckle			during construction			
2021	Japanese	Multiflora		Mechanical removal by machines	Other	03/2022	No
	Honeysuckle	Rose		during construction		•	
2021	Mimosa			Mechanical removal by machines	Other	02/2022	No
				during construction		•	

Year	Species1	Species2	Issue	Treatment	Method	TreatDa	t&Resolved
2021	Mimosa						No
2021	Multiflora						No
	Rose						
2021	Multiflora						No
	Rose						
2021	Oriental			Invasive treatment	Backpack	09/2021	No
	Bittersweet				Spray		
2021	Oriental			Invasive treatment	Backpack	09/2021	No
	Bittersweet				Spray		
2021	Tree Of		Naturally dead? Was defoliated upon	Invasive treatment	Hack and	09/2021	No
	Heaven		observation (Oct 2020)		Squirt		
2021	Tree Of	Multiflora		Mechanical removal by machines	Other	02/2022	No
	Heaven	Rose		during construction		,	
2021			Alligator Weed	Instream Veg Spray		08/2022	No

Miscellaneous Issues

Year	Subtype	Issue_Desc
2022	Soil Sample	Soil sample 01
2022	Soil Sample	Soil sample 01
2022	Soil Sample	Soil sample 02
2022	Soil Sample	Soil sample 03
2022	Soil Sample	Soil sample 04
2022	Soil Sample	Soil sample 05
2022	Soil Sample	Soil sample 06
2022	Soil Sample	Soil sample 07
2022	Soil Sample	Soil sample 08
2021	Soil Sample	HBH4 - 2
2021	Soil Sample	HBH3-2
2021	Soil Sample	HBH1-3
2021	Soil Sample	HBH2-3
2021	Soil Sample	HBH5-2
2021	Soil Sample	$\mathrm{HBH6}$ -2 '
2021	Soil Sample	HBH8-3
2021	Soil Sample	HBH7 −3'

Year	Subtype	Issue_Desc
2021	Soil Sample	HBH10 -3'
2021	Soil Sample	HBH9 −3'