Stewardship for Bethel Branch

Lead Steward: Andrea

2022-09-07

Boundary Issues

Channel Issues

Year	Subtype	Issue	Issue_Desc	Treated
2022	Channel			Yes
	Stability/Erosion			
2022	Failed Structure			No
2022	Failed Structure		Blown out bank	No
2022	Failed Structure		Eroding brush tie	No
2021	Channel		bank weakening, sloughing, cracking	Yes
	Stability/Erosion			
2021	Channel	Erosion_Se	cour Erosion. Needs plugs and stakes if they work in	No
	Stability/Erosion		bedrock	

Vegetation Issues

YearIssue	Issue_Desc	Pct_CoreateBreatment	
2022Low Stem Density	fescue competition	51- Yes supplemental planting of 50 1-gal contain 75% trees	ner
2022Low Stem Vigor/Height & Density	stems planted late and suppressed by undesired vegetation	51- Yes 75%	
2022Low Stem Vigor/Height		Yes	
2022Low Stem Vigor/Height & Density	Plant 30 5-gallon trees	No	
2021Bare Areas & Low Stem Vigor/Height	Size is smaller in growing season. Walked bigger winter perimeter.	26- Yes temporary seed $50%$	
2021Bare Areas & Low Stem Vigor/Height	Size is smaller in growing season. Walked bigger winter perimeter.	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	

YearIssue	Issue_Desc	Pct_Cloveatellreatment
2021Low Stem Vigor/Height & Density	dense weeds suppressing trees	76- Yes $$ ring sprays around trees and foliar spray to 100%

Weed Issues

Year	Species1	Issue
2022	Chinese Privet	
2022	Chinese Privet	
2022	Chinese Privet	
2022	Chinese Privet	Small Privet
2022	Japanese Honeysuckle	
2022	Japanese Honeysuckle	Loja canopy
2022	Multiflora Rose	
2022	OTHER	Murdannia
2022	Tree Of Heaven	

Miscellaneous Issues

Year	Subtype	Issue_Desc	Treated
2022	Misc	Needs Plugs	No
2022	Misc	Corners on Moon Lindley- No signs	No
2022	Soil Sample	BUT33	na
2022	Soil Sample	UT1-SS2 BA	na
2022	Soil Sample	UT1-SS1	na