# Stewardship for Lyon Hills

Lead Steward: Emily

2023-02-14

## Boundary Issues

| Year | Issue  | Description   | Resolved |
|------|--------|---|----------|
| 2022 |        | Hay bales rolled through fence. Farmer patched fence. Hay bales still in stream | No       |
| 2022 | Debris | Tree fell on fence  | No       |
| 2021 | Cattle | Cattle stepping into easement around creek crossing                             | No       |

## Channel Issues

| Year | Subtype                   | Issue                 | Description  | Resolved |
|------|---------------------------|-----------------------|--|----------|
| 2022 | Needs Livestakes          |                       |  | Yes      |
| 2022 | Needs Livestakes          |                       |  | Yes      |
| 2022 | Needs Livestakes          |                       | Low wet area draining from field.  | Yes      |
| 2022 | Channel Stability/Erosion | AggradationDeposition |  | No       |
| 2022 | Failed Structure          |                       |  | No       |
| 2022 | Failed Structure          |                       | Slumping after Boulder toe   | No       |
| 2022 | Failed Structure          |                       |  | No       |
| 2022 | Failed Structure          |                       | Piping. Put some small rocks in; made a slight improvement                                 | No       |
| 2021 | Needs Livestakes          |                       |  | Yes      |
| 2021 | Needs Livestakes          |                       |  | Yes      |
| 2021 | Needs Livestakes          |                       | Needs livestakes   | No       |
| 2021 | Needs Livestakes          |                       | Needs livestakes   | No       |
| 2021 | Needs Livestakes          |                       | Needs livestakes   | No       |
| 2021 | Needs Livestakes          |                       | Needs livestakes around structures   | No       |
| 2021 | Needs Livestakes          |                       | Needs livestakes on meander bend   | No       |
| 2021 | Needs Livestakes          |                       | Needs livestakes on right bank   | No       |
| 2021 | Needs Livestakes          |                       | Needs livestakes on left bank (maybe right bank, too)                                      | No       |
| 2021 | Channel Stability/Erosion | ErosionScour          | Erosion and Aggradation  | No       |
| 2021 | Channel Stability/Erosion | ErosionScour          |  | No       |
| 2021 | Failed Structure          |                       | Failed log sill. Undercutting. Disconnected from grade? And no splash rock to reduce drop. | No       |
| 2021 | Failed Structure          | Failed/Not Functional | Failed j-hook  | No       |
| 2021 | Failed Structure          | Failed/Not Functional | Too high   | No       |

## Vegetation Issues

| Year | Issue                           | Description                 | Treatment                                    | TreatDate | Resolved |
|------|---------------------------------|-----------------------------|--|-----------|----------|
| 2022 |                                 | Bare area                   | Summer seed mix (millet, clover, humic plus) | 05/2022   | No       |
| 2022 | Bare Areas and Low Stem Density |                             | Summer seed mix (millet, clover, humic plus) | 05/2022   | No       |
| 2022 |                                 | Bare area                   | Summer seed mix (millet, clover, humic plus) | 05/2022   | No       |
| 2022 |                                 | Low stem density/bare area  | Summer seed mix (millet, clover, humic plus) | 05/2022   | No       |
| 2021 | Bare Areas and Low Stem Density |                             | Summer seed mix (millet, clover, humic plus) | 05/2022   | No       |
| 2021 | Bare Areas                      |                             | Summer seed mix (millet, clover, humic plus) | 05/2022   | No       |
| 2021 | Bare Areas                      | Bare area                   | Summer seed mix (millet, clover, humic plus) | 05/2022   | No       |
| 2021 | Bare Areas                      | Bare area                   | cool season seeding, cord matting            | 10/2022   | No       |
| 2021 | Bare Areas                      |                             | Summer seed mix (millet, clover, humic plus) | 05/2022   | No       |
| 2021 | Bare Areas and Low Stem Density | Bare areas and some rilling | Summer seed mix (millet, clover, humic plus) | 05/2022   | No       |
| 2021 | Bare Areas                      | Bare area                   | Summer seed mix (millet, clover, humic plus) | 05/2022   | No       |

#### Weed Issues

| Year         | Species1                                  | Species2                                | Issue  | Treatment                 | Method                 | ${\bf TreatDate}$  | Resolved   |
|--------------|---|---|--|---------------------------|------------------------|--------------------|------------|
| 2022         | Kudzu                                     |   |  |                           |                        |                    | No         |
| 2022         | Princess Tree                             |   |  |                           |                        |                    | No         |
| 2022         | Princess Tree                             |   |  | ~                         | ~ . ~                  | /                  | No         |
| 2021         | Chinese Privet                            | 0.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1 |  | Cut stump                 | Cut Stump              | 09/2021            | Yes        |
| 2021         | Chinese Privet                            | Oriental Bittersweet                    |  | Cut stump BS, privet, HS  | Cut Stump              | 09/2021            | No         |
| 2021         | Chinese Privet                            | Oriental Bittersweet                    |  |                           |                        |                    | No         |
| 2021         | Chinese Privet                            |   |  |                           |                        |                    | No         |
| 2021         | Chinese Privet                            | Multiflora Rose                         | Isolated multiflora occurrence at top<br>of right bank and mature privet on<br>stream bank |                           |                        |                    | No         |
| 2021         | Chinese Privet                            |   |  |                           |                        |                    | No         |
| 2021         | Japanese Honeysuckle                      | Multiflora Rose                         |  |                           |                        |                    | No         |
| 2021         | Japanese Honeysuckle                      | Oriental Bittersweet                    |  |                           |                        |                    | No         |
| 2021         | Multiflora Rose                           | Oriental Bittersweet                    |  | Cut stump                 | Cut Stump              | 09/2021            | Yes        |
| 2021         | Multiflora Rose                           | Oriental Bittersweet                    | All invasives listed plus honeysuckle.  Lots of dense climbing vines at top of reach.      | Cut stump                 | Cut Stump              | 09/2021            | No         |
| 2021         | Oriental Bittersweet                      |   | Huge BS vine   | Cut stump                 | Cut Stump              | 09/2021            | Yes        |
| 2021         | Oriental Bittersweet                      | Multiflora Rose                         | Climbing BS and isolated MF  | Cut stump                 | Cut Stump              | 09/2021            | Yes        |
| 0001         | Oniontal Dittanson                        |   |  | -                         |                        |                    | V          |
| 2021<br>2021 | Oriental Bittersweet Oriental Bittersweet | Chinese Privet                          | Large climbing BS  | Cut stump vines Cut stump | Cut Stump<br>Cut Stump | 09/2021<br>09/2021 | Yes<br>Yes |
| 2021         | Oriental Bittersweet                      | Chinese Privet                          |  | Cut stump                 | Cut Stump              | 09/2021            | No         |
| 2021         | Oriental Bittersweet                      | Omnese 1 11vet                          | Climbing BS in a couple locations on right floodplain                                      | Cut brump                 | Cut Stump              | 00/2021            | No         |
| 2021         | Oriental Bittersweet                      | Chinese Privet                          | 2  |                           |                        |                    | No         |
| 2021         | Oriental Bittersweet                      | Multiflora Rose                         | Climbing BS and isolated MF  |                           |                        |                    | No         |
| 2021         | Oriental Bittersweet                      | Chinese Privet                          | Small invasive cluster along tree line   |                           |                        |                    | No         |
| 2021         | Oriental Bittersweet                      |   | Climbing vine  |                           |                        |                    | No         |
| 2021         | Oriental Bittersweet                      |   | -  |                           |                        |                    | No         |
| 2021         | Oriental Bittersweet                      |   | 6" diameter climbing vine  |                           |                        |                    | No         |
| 2021         | Princess Tree                             | Tree Of Heaven                          | Young princess trees and mature TOH  | Cut stump                 | Cut Stump              | 09/2021            | Yes        |
| 2021         | Princess Tree                             |   | 01   | 1                         | 7                      | ,                  | No         |
| 2021         | Tree Of Heaven                            | OTHER                                   | Canopy TOH and monoculture of<br>Harlequin Glorybower at top of reach                      | Cut stump                 | Cut Stump              | 09/2021            | No         |
| 2021         |   |   | In-stream veg  | Sprayed                   |                        | 09/2021            | Yes        |
| 2021         |   |   | In-stream veg with Aggradation   |                           |                        |                    | No         |
| 2021         |   |   | In-stream veg and Aggradation<br>upstream of culvert                                       |                           |                        |                    | No         |
| 2021         |   |   | 1  |                           |                        |                    | No         |
| 2021         |   |   |  |                           |                        |                    | No         |
| 2021         |   |   | In-stream veg  |                           |                        |                    | No         |
| 2021         |   |   |  |                           |                        |                    | No         |
| 2021         |   |   |  |                           |                        |                    | No         |
| 2021         |   |   |  |                           |                        |                    | No         |
| 2021         |   |   |  |                           |                        |                    | No         |
| 2021         |   |   |  |                           |                        |                    | No         |

#### Miscellaneous Issues

| Year | Subtype    | Description   | Resolved |
|------|------------|---|----------|
| 2022 | Misc       | Two bales of straw in CE. In-stream                 | No       |
| 2021 | Misc       | Hunting tree stands                                 | No       |
| 2021 | Misc       | Mature Hemlock. Approx 15-18" DBH. Needs treatment. | No       |
| 2021 | Beaver Dam |   | No       |
| 2021 | Misc       | Mature Hemlocks need treatment. DBH 12-15"          | No       |