Stewardship for Huntsman

Lead Steward: Dominic

2023-02-14

Boundary Issues

Channel Issues

Year	Subtype	Issue	Description	Resolved
2022	Channel Stability/Erosion			No
2022	Channel Stability/Erosion	ErosionScour		No
2022	Channel Stability/Erosion			No
2022	Channel Stability/Erosion			No
2022	Channel Stability/Erosion			No
2022	Channel Stability/Erosion			No
2022	Channel Stability/Erosion	Other	Stream goes under riffle	No
2022	Channel Stability/Erosion	AggradationDeposition	Stream channel not obvious	No
2022	Needs Livestakes			No
2022	Needs Livestakes			No
2022	Needs Livestakes			No
2022	Needs Livestakes			No
2022	Needs Livestakes			No
2022	Needs Livestakes			No
2022	Needs Livestakes			No
2022	Failed Structure		Banks eroding on both sides of log sill.	No

Vegetation Issues

Year	Issue	Description	Resolved
2022		Rilling	No
2022		Low vegetation	No
2022		Now veg	No
2022		Low veg	No
2022		Eroded bank	No
2022	Bare Areas and Low Stem Density		No

Weed Issues

Year	Species1	Species2	Issue	Treatment	Method	${\bf TreatDate}$	Resolved
2022	Tree Of Heaven	Multiflora Rose		Invasives treatment	Hack and Squirt	09/2021	No
2022	Tree Of Heaven	Multiflora Rose		Invasives treatment	Hack and Squirt	09/2021	No
2022				In stream veg spray		08/2022	No
2021	Callery Pear						No
2021	Callery Pear						No
2021	Chinese Privet	Multiflora Rose		Invasives treatment	Hack and Squirt	09/2021	No
2021	Chinese Privet	Multiflora Rose		Invasives treatment	Hack and Squirt	09/2021	No
2021	Chinese Privet	Multiflora Rose		Mechanical removal by machines during construction	Other	02/2022	No
2021	Chinese Privet	Multiflora Rose		Mechanical removal by machines during construction	Other	02/2022	No
2021	Chinese Privet	Multiflora Rose		Mechanical removal by machines during construction	Other	02/2022	No
2021	Chinese Privet	Multiflora Rose		Invasives treatment	Backpack Spray	09/2021	No
2021	Chinese Privet	Japanese Honeysuckle		Mechanical removal by machines during construction	Other	02/2022	No
2021	Chinese Privet			Mechanical removal by machines during construction	Other	02/2022	No
2021	Chinese Privet	Japanese Honeysuckle		Mechanical removal by machines during construction	Other	02/2022	No
2021	Chinese Yam			Mechanical removal by machines during construction	Other	02/2022	No
2021	Japanese Honeysuckle	Multiflora Rose		Mechanical removal by machines during construction	Other	03/2022	No
2021	Japanese Honeysuckle			Mechanical removal by machines during construction	Other	02/2022	No
2021	Japanese Honeysuckle			Mechanical removal by machines during construction	Other	02/2022	No
2021	Mimosa			Mechanical removal by machines during construction	Other	02/2022	No
2021	Mimosa						No
2021	Multiflora Rose						No
2021	Multiflora Rose						No
2021	Oriental Bittersweet			Invasive treatment	Backpack Spray	09/2021	No
2021	Oriental Bittersweet			Invasive treatment	Backpack Spray	09/2021	No
2021	Tree Of Heaven	Multiflora Rose		Mechanical removal by machines during construction	Other	02/2022	No
2021	Tree Of Heaven		Naturally dead? Was defoliated upon observation (Oct 2020)	Invasive treatment	Hack and Squirt	09/2021	No
2021			Alligator Weed	Instream Veg Spray		08/2022	No

Miscellaneous Issues

Year	Subtype	Description
2022	Soil Sample	Soil sample 01
2022	Soil Sample	Soil sample 01
2022	Soil Sample	Soil sample 02
2022	Soil Sample	Soil sample 03
2022	Soil Sample	Soil sample 04
2022	Soil Sample	Soil sample 05
2022	Soil Sample	Soil sample 06
2022	Soil Sample	Soil sample 07
2022	Soil Sample	Soil sample 08
2021	Soil Sample	HBH4 – 2'
2021	Soil Sample	HBH3 -2'
2021	Soil Sample	HBH1 -3'
2021	Soil Sample	HBH2 -3'
2021	Soil Sample	HBH5 -2'
2021	Soil Sample	HBH6 -2'
2021	Soil Sample	HBH8 -3'
2021	Soil Sample	HBH7 -3'
2021	Soil Sample	HBH10 −3'
2021	Soil Sample	НВН9 -3'