



## Turning and Boring Volume 1 A Specialized Treatise for Machinists, Students in Industrial and Engineering Schools, and Apprentices, on Turning and Bo

By Franklin Day Jones

RareBooksClub. Paperback. Book Condition: New. This item is printed on demand. Paperback. 70 pages. Dimensions: 9.7in. x 7.4in. x 0.1in. This historic book may have numerous typos and missing text. Purchasers can download a free scanned copy of the original book (without typos) from the publisher. Not indexed. Not illustrated. 1915 Excerpt: . . . of threads to the inch is ordinarily determined by referring to a table or index plate which shows what the size of gears a and c should be, or the number of teeth each should have, for cutting any given number of threads per inch. Selecting the Change Gears for Thread Cutting. -- Suppose a V-thread is to be cut on the end of the bolt B, Fig. 2, having a diameter of 1 inch and seven threads per inch of length, as shown at A in Fig. 1, which is the standard number of threads per inch for that diameter. First the change gears to use are found on plate which is shown enlarged in Fig. 3. This plate has three columns: The first contains different numbers of threads to the inch, the second the size gear to place on the spindle or stud at a...



## Reviews

It in a of the best publication. It really is rally intriguing through reading through period of time. You will not feel monotony at anytime of your own time (that's what catalogs are for relating to in the event you request me).

-- Dr. Pat Hegmann

It in one of my favorite publication. It is among the most awesome publication i have go through. I am just quickly will get a delight of reading through a published publication.

-- Prof. Martin Zboncak DVM