



Maine Municipal Association

60 Community Drive
PO Box 9109
Augusta, ME 04332-9109

Attachment N2

Action Plan

Member: Portland School Department

Loss Control Consultant: Ann Schneider

Key Contact: Craig Worth, Deputy Chief of Operations

Survey Date:
2/12/2016

The following items requiring attention were noted during my recent visit. These recommendations and proposed completion dates were discussed in detail on 2/12/2016. We agreed the time frames were reasonable. Please indicate your estimated completion dates and return a copy of this form within the next thirty days.

Item Number	Description / Recommendation	Proposed Completion Date	Estimated Completion Date
Location	<u>Reiche School</u>		
02-16-01-B	Housekeeping- Clutter Recommendation: There is a lot of clutter and housekeeping issues throughout the school. This increases the fire load, and presents potential trip/fall hazards. Work with staff to clean up and organize their areas to reduce the clutter.	4/29/2016	
Location	<u>Reiche School</u>		
02-16-02-B	Hazard Communication Recommendation: The Safety Data Sheets for this building should be reviewed and updated to ensure they are current with the new Global Harmonization System.	4/29/2016	
Location	<u>Reiche School</u>		
02-16-03-B	Electrical Hazards Recommendation: There is an over-use of extension cords due to a lack of receptacles. According to the National Electrical Code, extension cords are not to be in permanent use. Have a licensed electrician evaluate and determine if additional receptacles can be added in identified locations to reduce the use of extension cords. Conduit covers should be placed over cords that cannot be removed to prevent a trip/fall hazard.	4/12/2016	
Location			
02-16-04-B	Hazard Communication Recommendation: Staff are bringing in their own cleaning chemicals and air fresheners. The school policy on bringing in chemicals should be reviewed with all staff, and they should be instructed to stop this practice.	4/29/2016	

Our survey of your operation is to assist you in your loss control efforts. We do not assume responsibility for the discovery or elimination of all hazards that could possibly cause accidents or losses. Recommendations are developed from the conditions observed at the time of the survey and may not include every possible cause of loss. Compliance with these recommendations does not guarantee the fulfillment of your obligation under local, state, or federal law.

Location

02-16-05-A	Fire Door Hazard	3/29/2016
------------	------------------	-----------

Recommendation:

Room 101 - remove all paper from the double emergency doors and remove the flag that can present an entanglement hazard in an emergency due to low height. There should not be any paper taped to a designated egress door.

Location

02-16-06-B	Egress Door Signage	4/29/2016
------------	---------------------	-----------

Recommendation:

Replace the paper EXIT sign with a real EXIT sign in the 2nd floor Art room. EXIT signage should have letters that are six inches in height, 3/4 inch in width, and be reflective or illuminated.

Location

02-16-07-B	Clutter and Securing of Tools	4/29/2016
------------	-------------------------------	-----------

Recommendation:

2nd Floor Art - clean up the clutter which presents a trip/fall hazard and increases the fire load. Secure the tools (saw, etc.) in a locked cabinet.

Location

02-16-08-B	Sprinkler Inspections	4/12/2016
------------	-----------------------	-----------

Recommendation:

Ensure that the building sprinkler system is being maintained and inspected per NFPA 25. Contact the Portland Fire Department for the exact language for this standard.

Location

02-16-09-B	Ladder Hazard	4/29/2016
------------	---------------	-----------

Recommendation:

Dispose of the stepladder located in the boiler room. It is faded in color, indicating it has exceeded its age and safe use.

Location

02-16-10-B	Tube Light Cover	4/29/2016
------------	------------------	-----------

Recommendation:

Receiving - place enclosed covers on the tube lights above the door - they are located within 8 feet of the floor.

CC: Superintendent Jeanne Crocker

Our survey of your operation is to assist you in your loss control efforts. We do not assume responsibility for the discovery or elimination of all hazards that could possibly cause accidents or losses. Recommendations are developed from the conditions observed at the time of the survey and may not include every possible cause of loss. Compliance with these recommendations does not guarantee the fulfillment of your obligation under local, state, or federal law.