CLAIM EVIDENCE BUNDLE

Hydraulic filter head — customer line-down claim | compiled 30 September 2025

Control note. This internal compilation preserves the source labels used below. It includes the prior marked-up draft and review comments, not a finding of fact. Records relate to PO IV-44718 unless stated otherwise.

Component	Hydraulic filter head | Part HFX-6200-17 | Serial HFH-25-0917
Shipment	PMT-UK-240925-08 | Forwarder consignment FWD-7749031
Customer notice	CN-047, dated 29 Sep 2025 — £310,000 line-down cost claimed
Bundle index	DRAFT-01; REV-01; ASN-01/02; RCV-01/02; LOG-01; TERMS-01; TECH-01; PT-01; CN-047

Evidence map

The items are placed in date/source order where practical. Image references RCV-01 and RCV-02 are receiving photographs reconstructed from the receiving record, with original captions and timestamps retained.

DRAFT-01 — marked-up failure-origin memorandum (superseded)

Draft conclusion: “The temperature excursion during carriage caused the hydraulic filter-head failure. Allocate the customer’s £310,000 claim to the forwarder.”

Margin mark: Delete / unsupported. The log has a gap; it does not record an excursion. Do not equate delivery risk with cause or recovery.

REV-01 — review comments (M. Havlicek / Quality / Legal)

REV-01.1	Replace the assertion of a recorded temperature excursion; identify the missing-data interval and the logger diagnostic.
REV-01.2	Address revised ASN and Peatmoor’s repacking notation. Explain what that record does and does not prove.
REV-01.3	Separate likely physical origin, delivery/risk provision, contractual liability, insurer coverage and validation of the customer amount.
REV-01.4	Give insurer-locatable citations and make non-connections visible; name owners and a route if evidence cannot be obtained.
REV-01.5	End on the proposed allocation-meeting position.

ASN-01 — Advance Shipping Notice (original)

Peatmoor Trust | issued 24 Sep 2025, 09:14

Document number	ASN-PT-240925-118
Purchase order	IV-44718
Shipment / carrier	PMT-UK-240925-08 / FWD-7749031
Line	1 — Hydraulic filter head, HFX-6200-17; serial HFH-25-0917
Package	1 carton — OEM-sealed carton; 47 × 33 × 28 cm; gross weight 18.4 kg
Status	Ready for collection

ASN-02 — Advance Shipping Notice (revised)

Peatmoor Trust | issued 24 Sep 2025, 12:36

Document number	ASN-PT-240925-118-R1
Purchase order	IV-44718
Shipment / carrier	PMT-UK-240925-08 / FWD-7749031
Line	1 — Hydraulic filter head, HFX-6200-17; serial HFH-25-0917
Package	1 carton — **repacked by Peatmoor after outer label damage**; replacement transit carton; 49 × 35 × 30 cm; gross weight 19.1 kg
Status	Ready for collection

CARR-01 — forwarder collection scan: FWD-7749031; Peatmoor Trust despatch point; 24 Sep 2025, 15:10. No event narrative is recorded in this scan.

RCV-01 / RCV-02 — receiving photographs and captions

Ironvale receiving record, shipment PMT-UK-240925-08 / serial HFH-25-0917

RCV-01 — 25 Sep 2025, 10:42 Exterior carton at receipt. Carton faces shown intact; no obvious crushing, puncture or wetting visible.	**RCV-02 — 25 Sep 2025, 10:44** Internal packing / port. Port protector detached; port exposed with visible debris. No conclusion in the record on when this condition arose.

Receiving note RN-928: “Carton externally clean / no visible transit damage. Internal port cap loose.” The note identifies the shipment and serial above; it does not record an opening, impact, or custody event before receipt.

LOG-01 — forwarder temperature record extract

Consignment FWD-7749031 | logger TL-44-218 | storage requirement: 5°C to 35°C (SPEC-01)

24 Sep 2025, 15:20	18.2°C — recorded; within storage requirement
24 Sep 2025, 15:20 to 25 Sep 2025, 00:18	No readings — 8 h 58 min missing interval
25 Sep 2025, 00:16	Diagnostic: LOW POWER / RESTART FLAG
25 Sep 2025, 00:18	17.9°C — recorded; within storage requirement
Log note	The diagnostic makes sensor/power interruption plausible. It does not identify the reason for the missing readings. No record in LOG-01 records an excursion, opening, drop, impact or other handling event.

SPEC-01 — product handling extract: “Store and transport at 5°C to 35°C.” No temperature is stated for the missing interval.

TERMS-01 — purchasing terms extract (PO IV-44718, rev. 6)

Clause 1.3	Governing law: England and Wales.
Clause 7.2	Delivery: DAP Ironvale Distribution Centre, Coventry (Incoterms® 2020). Risk passes on physical delivery at the named place.
Clause 12.1	Supplier liability is subject to the agreement’s exclusions, limitations and applicable cap.
Clause 12.3	Neither party is liable for indirect or consequential loss, subject to the agreement and applicable law.

The extract is supplied for commercial review. It contains no determination of cause, enforceability, coverage or amount.

TECH-01 — preliminary Quality technical note

QTN-25-144 | 28 Sep 2025 | preliminary

Observed failure is compatible with contamination or ingress at the exposed port. This preliminary note cannot determine when or where material entered, whether the protector detached before or after handoff, or identify a responsible actor. Further technical examination is required for defect confirmation.

PT-01 — Peatmoor Trust written position

28 Sep 2025

“Peatmoor Trust maintains that the unit left our facility conforming. Incoming inspection/conformity record IR-910 supports this position.” IR-910 is dated 23 Sep 2025, 08:45. PT-01 provides no post-repack test, seal record or condition photograph; ASN-02 records repacking on 24 Sep 2025.

CN-047 — customer claim notice

29 Sep 2025

Customer presents a £310,000 line-down cost claim following reported failure. The notice supplies no completed validation, agreed breakdown, admission, mitigation review or recoverability determination.