



DEALER BEST PRACTICE SERIES

Service Card System

Maintenance and Repair Application Component Life Management Component Renewal (CRC) MARC Management

1.0 Introduction 1

2.0 Best Practice Description..... 2

3.0 Implementation Steps 3

4.0 Benefits..... 4

5.0 Resources Required 4

6.0 Supporting Attachments / References 4

7.0 Related Best Practices 4

8.0 Acknowledgements..... 4

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices”. Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

1.0 Introduction

This Best Practice assists in the visually tracking of activities (repairs) that are performed when working with equipment due to:

- a. Equipment planned repairs
- b. Equipment unplanned repairs
- c. Inspections

Visual controls allow:

- a. The Supervisor to have a real time monitoring of the work's progress
- b. Work quality verifications in an organized manner
- c. Visual machine transfer of the in processes and pending work

Generally, the staff is focused on their tasks and they do not update logs or Gantt charts until their shift is ending in order to deliver it to the supervisor for the shift change.

Machine transfers are usually performed orally and come with an achieved progress log and pending repairs (usually performed among Supervisors). This log is then reviewed after the shift ends, losing the machine's progress real control.

Following one of the CPS's principles of "Make it Visual", the card system allows everyone to quickly see the jobs that have been performed on a machine and those that have not.

It is important for the dealer processes because it:


- a. Give the supervisor a real time monitoring of the repairs progress.
- b. Allows work quality verification in an organized manner: when finishing each repair, the technician will handle the card to the Supervisor and this is a warning to verify the performed work quality.
- c. Allows a visual machine transfer of the in progress and pending work. The progress is visual for supervisors, but also for the machine's technicians.
- d. Allows technical staff to continue performing other activities without waiting for the supervisors' indication.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Service Card System	DATE 1/13/2015	CHG NO 00	NUMBER 1104-1.04-1223
---------------------	-------------------	-----------------	--------------------------

2.0 Best Practice Description

Below the card process and their relation to M&R processes is shown:



This Best Practice is intended to achieve:

- Improved work transfer system (quality)
- Formalized job completion quality control process (quality)
- Real time progress on machine visual inspection (management control)
- Visual control of the job's progress to all staff including the assigned technicians to the machine (management control)

This Best Practice can be applied by any dealer because it is a method which complements the M&R repair process.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Service Card System

DATE
1/13/2015

CHG
NO
00

NUMBER
1104-1.04-1223

4.0 Benefits

The greatest benefits are improving the transfer process quality and the performed tasks quality by formalizing the jobs' inspection supervisor function for each received card.

5.0 Resources Required

Investment: Manufacture cards and buy plastic bags, pull-tight seals and magnets. Quantity depends on the orders history per working day.

Time: Time to train and follow-up with the involved staff.

6.0 Supporting Attachments / References

- View Card Process
- Card Model

7.0 Related Best Practices

Repair Management 1007-2.0-1107

8.0 Acknowledgements

This Best Practice was written by:
Alexander Campos Vásquez
Operations Coordinator
acamposv@ferreyros.com.pe

Prepared by:
Luciana Cardoza Getar
Ferreiros CI & BP
lcardoza@ferreyros.com.pe

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Service Card System	DATE 1/13/2015	CHG NO 00	NUMBER 1104-1.04-1223
---------------------	-------------------	-----------------	--------------------------