



DEALER BEST PRACTICE SERIES

Parts Mezzanine Gate

Application Maintenance Site Management Component Rebuild Component Life Management Safety MARC Management

Parts Mezzanine Gate 0

1.0 Introduction 1

2.0 Best Practice Description..... 1

3.0 Implementation Steps 2

4.0 Benefits..... 2

5.0 Resources Required 2

6.0 Supporting Attachments / References 2

7.0 Related Best Practices 2

8.0 Acknowledgements..... 3

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices”. Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

1.0 Introduction

Where space for parts inventory is limited, onsite parts stores often have to make use of a mezzanine level. Typically, parts pallets are elevated up onto the edge of the mezzanine floor by forklift, where parts personnel can unpack it from. This requires there to be an area where there is no safety guard railing, creating a significant falling risk for the people unpacking the parts.

This Best Practice describes the use of a pivoting gate to allow parts to be stored on a mezzanine level while avoiding the risk of working at heights without constant protection.

2.0 Best Practice Description

A two-way pivoting safety gate was implemented on the parts warehouse mezzanine level, in order to take away the risk of falling for anyone standing in the vicinity.



The gate is normally in the position shown on the left above. When parts need to be lifted up onto the edge of the mezzanine level, the guard is pivoted to the position on the right above. Anybody standing on the mezzanine level is then never exposed to a falling risk. When the forklift moves away, the guard is pivoted back to the position on the left above. The parts person is now able to unpack the parts safely.

The safety gate pivots on two side stands, which are bolted to the mezzanine floor, as seen in the pictures above.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Parts Mezzanine Gate	DATE 2/13/2015	CHG NO 01	NUMBER 0108-2.14-1113
----------------------	-------------------	-----------------	--------------------------

3.0 Implementation Steps

Note: Although Caterpillar does not endorse this particular supplier, Westrac has experience with the following products or companies. We welcome additional supplier recommendations from our dealer network.

The safety gate used at this particular site was commercially procured through a company called Dexion. They only have offices worldwide, but this type of safety gate is custom made only in Perth, Australia.

Dexion Canning Vale
 57 Catalano Circuit
 Canning Vale WA 6155
 Australia
 T: +61 8 9455 7480
 F: +61 8 9455 7411
 dexioncanningvale.com.au
 dexion.com.au

There is no patent on this safety gate, as many companies offer similar products. Outside Australia, it is possible that another supplier may be able to produce a similar gate. It may also be possible to fabricate a similar gate onsite.

4.0 Benefits

- Falling hazard has been reduced thanks to the constant protection offered by the gate.

5.0 Resources Required

- Cost of materials (for fabrication) – approx. AUD \$500 (steel, consumables, etc.)
- Labour to fabricate (if necessary) – approx. 24hrs
- Labour to install – approx. 2hrs
- Training

6.0 Supporting Attachments / References

None.

7.0 Related Best Practices

None at this time.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Parts Mezzanine Gate	DATE 2/13/2015	CHG NO 01	NUMBER 0108-2.14-1113

8.0 Acknowledgements

Paul Darrah
Ravensthorpe Project Manager
Paul.Darrah@westrac.com.au
+61 418 909 332

Stuart Wheeler
Equipment Management Consultant – CGM APD
wheeler_stuart_g@cat.com
+61 418 320 142

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Parts Mezzanine Gate	DATE 2/13/2015	CHG NO 01	NUMBER 0108-2.14-1113
----------------------	-------------------	-----------------	--------------------------