



MINING DEALER BEST PRACTICE

R1300G Stand Chock Set

**Maintenance and
Repair**

Application

Component Life
Management

Component
Renewal (CRC)

MARC
Management

R1300G Stand Chock Set.....	0
1.0 Introduction.....	1
2.0 Best Practice Description.....	1
3.0 Implementation Steps.....	2
4.0 Benefits.....	2
5.0 Resources Required.....	2
6.0 Supporting Attachments / References.....	3
7.0 Related Best Practices.....	3
8.0 Acknowledgements.....	3

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices.” Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

December 2015
1511-1.11-1403

1.0 Introduction


There is the safety requirement in mine sites that all rubber-tired equipment must be equipped with stand chocks. Borusan Makina Kazakhstan has decided to take this opportunity and develop its own stand chocks at a place on the equipment where they will be kept if they are not used.

There is the Equipment Rebuild Shop (ERS) in the CRC where old machines are renewed to the status of the new ones. During a R1300G UG Loader rebuild, we designed and fabricated the first stand chock set for this machine. In the future stand chocks will be developed for other wheel machines (R1600G, R1700, R2900, AD30, AD45, AD55, AD60, 980H, 988H, 992G, 16H, 160H, 140H, etc.).

2.0 Best Practice Description

The R1300G stand chock set consists of 2 x Stand Chocks and 1 x Chock Holder. The stand chocks and their holder were designed to meet the following criteria: ergonomics, weight, installation place in the equipment, and tire dimensions of the equipment.

The **Chock Holder (1)** is installed on the splashguard of the wheel and fastened to the walking platform of the loader with its bolts. The holder is removable to provide access to the filter behind it during PMs. Each **Stand Chock (2)** has a **convenient handle (3)** to carry and the **locking sleeve (4)** that keeps the stand chock in place by connecting it to the **bolt (5)**, which is welded to the splashguard beforehand. Each locking sleeve has the chain so that the customer would not lose them in the mine site during the operation.



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
R1300G Stand Chock Set	DATE 6/23/2016	CHG NO 01	NUMBER 1511-1.11-1403

3.0 Implementation Steps

The stand chock set is in use.



4.0 Benefits

- Helps mining customers to follow the safety requirement about stand chocks.
- It can be additional business for the dealer.

5.0 Resources Required

- Machine Shop.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

R1300G Stand Chock Set	DATE 6/23/2016	CHG NO 01	NUMBER 1511-1.11-1403
------------------------	-------------------	-----------------	--------------------------

6.0 Supporting Attachments / References

The necessary drawings of the R1300G Stand Chock Set are attached.

7.0 Related Best Practices

- 1603-1.11-1421 - AD30 Chock Stand Set

8.0 Acknowledgements

The idea of creating & implementing this Best Practice belongs to:

Azamat IBRAYEV
Equipment Rebuild Shop Supervisor
Borusan Makina Kazakhstan LLP
akenzhetayev@borusan.com

Igor LISSIN
CRC Quality Engineer
Borusan Makina Kazakhstan LLP
ilissin@borusan.com

Dmitriy SILINSKIY
Welding Engineer
Borusan Makina Kazakhstan LLP
dsilinskiy@borusan.com

Andrey ASUMS
Electrical & Gas Welder
Borusan Makina Kazakhstan LLP
AAsmus@borusan.com

Alexandr KARPACHYOV
Electrical & Gas Welder
Borusan Makina Kazakhstan LLP
akarpachyov@borusan.com

Azamat ORAZALINOV
Electrical & Gas Welder
Borusan Makina Kazakhstan LLP
aorazalinov@borusan.com

Yernar NARGELOV
Service Engineer
Mining Product Support Department
Borusan Makina Kazakhstan LLP
ynargelov@borusan.com

Syrlan MYRZABEKOV
Repairman
Equipment Rebuild Shop
Borusan Makina Kazakhstan LLP
smyrzabekov@borusan.com

This Best Practice was written by:
Gulnaz MANSUROVA
CRC Process Engineer
Borusan Makina Kazakhstan LLP
gmansurova@borusan.com
+7 (701) 951 98 14

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
R1300G Stand Chock Set	DATE 6/23/2016	CHG NO 01	NUMBER 1511-1.11-1403