



DEALER BEST PRACTICE SERIES

Replace Fluid Hoses
During Component R & I

Application Maintenance Site Management **Component Rebuild** Safety MARC Management

Replace Fluid Hoses During Component R & I.....1

1.0 Introduction2

2.0 Best Practice Description.....2

3.0 Implementation Steps2

4.0 Benefits.....3

5.0 Resources Required3

6.0 Supporting Attachments & References.....4

7.0 Related Best Practices4

8.0 Acknowledgements.....4

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices”. Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

1.0 Introduction

When a major component is removed for a PCR rebuild, this is an ideal time to change all fluid line hoses in the major component compartment area. This is especially true for engine Removal and Installation (R&I) where hoses are very difficult to access with the engine in chassis.

This practice prevents:

- Hose failures,
- Contamination, and
- Loss of fluid and machine downtime to replace failed hoses.


2.0 Best Practice Description

This Best Practice is to replace all fluid hoses in a major component compartment area while the component is out of chassis for a PCR rebuild. Access to the compartment is greatly improved, and thus labor required is a fraction of the labor necessary to change a hose with the component in chassis. In addition, this practice provides a planned before-failure replacement schedule for the machine hoses and fluid lines.

3.0 Implementation Steps

Required process changes include:

1. Add "Replace Fluid Hoses" to the R&I checklist
2. Add hoses and clamps to the R&I parts kit and checklist,
3. Add OHT hose routing diagrams to the R&I forms kit. Hose routing diagrams are contained in the machine parts manual.



Example: Parts Book Hose Part Numbers and Routing Example

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Replace Fluid Hoses During Component R & I	DATE 9/13/2006	CHG NO 02	NUMBER 0906-2.3-1015

- Add OHT hose routing diagrams to the R&I forms kit.

793B


SN: 1HL

8X-5969

Lines Group – Steering

9005197.49

ALSO SEE ARRANGEMENTS	Assembly Part No.	Coupling 1	Coupling 2	Hose Type
8X-5971	8X-5977	3S-8503-R	3S-8503-R	X1-3ES
8X-5972	8X-5978	3S-8498-R	6D-9961-R	X1-3ES
8X-5973	8X-5979	3S-8501-R	2P-1801-R	X1-3ES
8X-6063	8X-6061	6V-9959-R	6V-9957-R	X1-3ES
8X-6063	8X-6062	6V-1404-R	6V-9959-R	X1-3ES
8X-6213	8X-6063	3S-8503-R	2P-1801-R	X1-3ES
8X-9627	8X-7787	3S-8498-R	3S-8503-R	X1-3ES
8X-8273	8X-8273	6V-9946-R	6V-9946-R	X1-3ES
8X-9629	105-3002	6V-9946-R	6V-9946-R	X1-3ES
8X-9630				



4.0 Benefits

- Prevent unplanned hose failures
- Better machine availability
- Increased production

5.0 Resources Required

Time to identify parts and information required to perform the hose replacements.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Replace Fluid Hoses During Component R & I	DATE 9/13/2006	CHG NO 02	NUMBER 0906-2.3-1015

6.0 Supporting Attachments & References

None Applicable

7.0 Related Best Practices

None applicable.

8.0 Acknowledgements

This Best Practice was authored by:

Dale Brehm
Caterpillar Global Mining
6 Sigma Black Belt
Brehm.Dale.E@cat.com
+1 309 675 6325

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Replace Fluid Hoses During Component R & I

DATE
9/13/2006

CHG
NO
02

NUMBER
0906-2.3-1015