



MINING DEALER BEST PRACTICE

785/ 789 Transmission Disassembly/ Assembly Stand

Maintenance and
Repair

Application

Component Life
Management

Component
Renewal (CRC)

MARC
Management

1.0	Introduction	1
2.0	Best Practice Description	1
3.0	Implementation Steps.....	1
4.0	Benefits	2
5.0	Resources Required.....	2
6.0	Supporting Attachments / References.....	2
7.0	Related Best Practices	3
8.0	Acknowledgements	3

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices.” Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

4.03-170504-02

Mining.cat.com

1.0 Introduction


Borusan Makina Kazakhstan has developed a stand for safe and convenient disassembling/ assembling of 785/ 789 transmissions.

This stand was fabricated before a 789C transmission came to the CRC for overhaul, because the it would not fit existing stands.

The height of the stand for disassembling/ assembling 785 / 789 transmissions and its stable design enable the CRC technicians to work safely and conveniently.

2.0 Best Practice Description

The design of the stand is quite simple. It has the reliable supports and convenient mounting base with necessary cutouts for a good component fit and bolt holes to fasten the component to the stand for safety. See Picture 1.



Picture 1. 785/ 789 Transmission Disassembly/ Assembly Stand

3.0 Implementation Steps

The transmission disassembly/ assembly stand is in use:

As an example, see below the disassembly of 785C Transmission. See the pictures below.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
785/ 789 Transmission Disassembly/ Assembly Stand	DATE 8/20/2018	CHG NO 00	NUMBER 4.03-170504-02



785C Transmission Disassembly on the stand

4.0 Benefits

- More stable, safe and convenient to use, because the height of the transmission is lower than it is on other stands;
- Improved disassembly/ assembly time of 785/ 789 transmissions.

5.0 Resources Required

- Materials needed to fabricate the stand;
- Welding.

6.0 Supporting Attachments / References

The necessary drawings of the stand are attached.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
785/ 789 Transmission Disassembly/ Assembly Stand	DATE 8/20/2018	CHG NO 00	NUMBER 4.03-170504-02

7.0 Related Best Practices

N/a.

8.0 Acknowledgements

The idea of creating & implementing this Best Practice belongs to:

Valentin AFANASYEV
Mechanic (foreman)
Component Rebuild Shop
Borusan Makina Kazakhstan LLP

Azamat ORAZALINOV
Electrical & Gas Welder
Equipment Rebuild Shop
Borusan Makina Kazakhstan LLP

Yernar NARGELOV
Service Engineer
Mining Division CSA and Service Standards
Borusan Makina Kazakhstan LLP

Yerbol AITPAYEV
CRC Planning Engineer
Planning-and-Technical Department
Borusan Makina Kazakhstan LLP

Daniil PONAMAREV
Painter
Equipment Rebuild Shop
Borusan Makina Kazakhstan LLP

This Best Practice was written by:
Gulnaz MANSUROVA
CRC Quality Engineer
Borusan Makina Kazakhstan LLP
gmansurova@borusan.com
+7 (701) 951 98 14

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

785/ 789 Transmission Disassembly/ Assembly Stand

DATE
8/20/2018

CHG
NO
00

NUMBER
4.03-170504-02