



Front Housing & Fan GP Rotating Stand for 3500 Series Engines

Maintenance and
Repair

Application

Component Life
Management

Component
Renewal (CRC)

MARC
Management

Front Housing & Fan GP Rotating Stand for 3500 Series Engines.....	0
1.0 Introduction.....	1
2.0 Best Practice Description.....	1
3.0 Implementation Steps.....	1
4.0 Benefits.....	4
5.0 Resources Required.....	4
6.0 Supporting Attachments / References.....	4
7.0 Related Best Practices.....	4
8.0 Acknowledgements.....	4

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices.” Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

1.0 Introduction

Borusan Makina Kazakhstan designed the adapter to the original CAT revolver for assembling C series and smaller engines that has improved the disassembly/assembly process of 3500 series engine front housings. Also the plate has been developed to this adapter that allows disassembling/assembling 3500 series and C32 engines fan group as well.


Without using the revolver with the adapter, the front housing was disassembled/ assembled on the table involving two technicians. It was inconvenient and required more efforts and man-hours.

Thus, the new tool is easier and safer to assemble front housings and fan group with one technician.


EDITOR'S NOTE: Given the cantilever load, proper safety precautions should be taken to prevent accidental falling of the loads.

2.0 Best Practice Description

It is a mobile tool with a 360° revolving forklift puller and 4 x fastening screws, and an additional plate for fan group.



The revolver with the forklift puller for front housings



The revolver with the plate for fan group

3.0 Implementation Steps

The Front Housing Revolver in use.


The **Front Housing** Assembly Process as an example.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Front Housing & Fan GP Rotating Stand for 3500 Series Engines	DATE 2/19/2015	CHG NO 00	NUMBER 1401-4.03-1334

1. The forklift puller is bolted to the revolver.



2. Use 4 x fastening screws to install the front housing onto the revolver.



3. The assembly has been started. This tool allows revolving the front housing to any position you need to do the job conveniently.



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Front Housing & Fan GP Rotating Stand for 3500
Series Engines

DATE
2/19/2015


CHG
NO
00

NUMBER
1401-4.03-1334

The Front Housing Revolver with the plate in use.

The **Fan GP** Assembly Process as an example.

1. The plate is bolted to the forklift puller.



2. Use 4 x fastening screws to install the fan group onto the revolver.



3. The assembly has been started. This tool allows revolving the front housing to any position you need to do the job conveniently.



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Front Housing & Fan GP Rotating Stand for 3500
Series Engines

DATE
2/19/2015

CHG
NO
00

NUMBER
1401-4.03-1334

4.0 Benefits

- Makes the work on disassembling/assembling front housings and fan group easier, more convenient & safer.
- Reduces significantly man-hours (now only one technician can handle this job).

5.0 Resources Required

- The CAT revolver consisting of Stand (Part No 1U5750) & 2 x Adapters (Part Nos: 1U-5749, 1U-7508);
- All required parts (name, size, number & material) to fabricate the adapter and the plate are indicated in the drawings attached.

6.0 Supporting Attachments / References

The adapter and the plate fabrication drawings are attached to this Best Practice.

7.0 Related Best Practices

N/A

8.0 Acknowledgements

The idea of creating & implementing this Best Practice belongs to:

Ali CEKIC
Engine Team Leader
Borusan Makina Kazakhstan LLP
acekic@borusan.com
+7 (701) 951 97 97

Almaz KENZHETAYEV
Machine Shop Supervisor
Borusan Makina Kazakhstan LLP
akenzhetayev@borusan.com
+7 (701) 803 04 87

Vassiliy FISSINETS
Machine Shop Welder
Borusan Makina Kazakhstan LLP
+7 (705) 831 37 38

Andrey ASMUS
Machine Shop Welder
Borusan Makina Kazakhstan LLP
+7 (700) 929 35 93

Bauyrzhan AKHANOV
Designer
Borusan Makina Kazakhstan LLP
bakhanov@borusan.com
+7 (700) 383 08 58

This Best Practice was written by:
Gulnaz MANSUROVA
CRC Process Engineer
Borusan Makina Kazakhstan LLP
gmansurova@borusan.com
+7 (701) 951 98 14

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Front Housing & Fan GP Rotating Stand for 3500 Series Engines	DATE 2/19/2015	CHG NO 00	NUMBER 1401-4.03-1334
--	-------------------	-----------------	--------------------------