



Aftercooler Adapter Remover – 793C, 793D

Maintenance and
Repair

Application

Component Life
Management

Component
Renewal (CRC)

MARC
Management

Removal Adapter Aftercooler – 793C, 793D	0
1.0 Introduction	1
2.0 Best Practice Description	1
3.0 Implementation Steps	3
4.0 Resources Required	3
5.0 Supporting Attachments / References	4
6.0 Related Best Practices	4
7.0 Acknowledgements	4

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices.” Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

October 18
4.03-171229-01

1.0 Introduction

A tool was developed to eliminate the damage to the aftercooler housing (P/N 210-2603 & 210-2581) when removing adapters (P/N 371-5945 & 371-5944.) Due to the small size of the adapters, it is often difficult to remove them without the risk of causing damage to other components.

2.0 Best Practice Description

Install the developed tool inside the space between the aftercooler core and the adapter. Make sure to adjust the nails and pull the adapter.

BEFORE



AFTER




THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Aftercooler Adapter Remover

DATE
10/25/2018

CHG
NO
00

NUMBER
4.03-171229-01



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Aftercooler Adapter Remover

DATE
10/25/2018

CHG
NO
00

NUMBER
4.03-171229-01

3.0 Implementation Steps

Design for the tool is shown below. Further dimensions are shown in the attachments section



Through the implementation of this tool, the following benefits have been observed:

- Extraction time reduction:
 - Before: 1 hour
 - Now: 8 minutes
- Significant safety increase by reducing the risk of hand injuries to technicians
- Significant reduction to adapter and aftercooler housing damage


4.0 Resources Required

There are minimal expenses associated with developing and fabricating this tool. The total cost for the tool was \$420

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Aftercooler Adapter Remover	DATE 10/25/2018	CHG NO 00	NUMBER 4.03-171229-01

5.0 Supporting Attachments / References

Below are the required manufacturing drawings and the stress analysis conducted on the lifting tool.



6.0 Related Best Practices

None

7.0 Acknowledgements

This Best Practice was written by:
Pablo Alcántara Michuy
Ferreyros S.A.

The idea for this Best Practice belongs to:
Gengis Gamonal Condori
Ferreyros S.A.

This Best Practice was revised by:
Aninu Mitacc Vizcardo
Ferreyros S.A.
aninu.mitacc@ferreyros.com.pe

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Aftercooler Adapter Remover	DATE 10/25/2018	CHG NO 00	NUMBER 4.03-171229-01