



BEST PRACTICE SERIES

Oil Pan Support Assembly – 797F

Maintenance and
Repair

Application

Component Life
Management

Component
Renewal (CRC)

MARC
Management

Removal of bearing differential	Error! Bookmark not defined.
1.0 Introduction	Error! Bookmark not defined.
2.0 Best Practice Description	2
3.0 Implementation Steps	3
4.0 Benefits	4
5.0 Resources Required	5
6.0 Supporting Attachments / References	6
7.0 Related Best Practices.....	7
8.0 Acknowledgements.....	8

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices”. Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

October 18
4.03-171229-03

1.0 Introduction

A support tool has been designed for the assembly process of the oil pan on the C175 models. This tool helps keep all parts of the oil pan level and evenly distributed during the time of installation which makes it an easier and more effective process.

2.0 Best Practice Description

Place the oil pan in the dedicated slots of the support tool. Use the adjustable supports to help assemble all parts of the oil pan until you get it completely level.



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Pan Oil Support Assembly - 797F	DATE 10/25/2018	CHG NO 00	NUMBER 4.03-171229-03

3.0 Implementation Steps

Manufacture support according to the dimensions of oil pan



Through the implementation of this tool, the following benefits have been observed:


- Reduced installation time:
 - Before: 40 minutes
 - Now: 15 minutes
- Significant safety increase by reducing the risk of hand injuries to technicians

4.0 Resources Required

The total cost to develop and fabricate this tool was \$2,348

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Pan Oil Support Assembly - 797F	DATE 10/25/2018	CHG NO 00	NUMBER 4.03-171229-03

5.0 Supporting Attachments / References.



6.0 Related Best Practices

None

7.0 Acknowledgements

This Best Practice was written by:
Pablo Alcántara Michuy
Ferreyros S.A.

The idea for this Best Practice belongs to:
Franklin Llanos
Ferreyros S.A.

This Best Practice was revised by:
Aninu Mitacc Vizcardo
Ferreyros S.A.
aninu.mitacc@ferreyros.com.pe

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Pan Oil Support Assembly - 797F

DATE
10/25/2018

CHG
NO
00

NUMBER
4.03-171229-03