



DEALER BEST PRACTICE SERIES

Assembly Tool for C175
Engine Connecting Rods,
Pistons, and Liners

Maintenance and Repair Application Component Life Management Component Renewal (CRC) MARC Management

Assembly Tool for C175 Engine Connecting
Rods, Pistons, and Liners0

1.0 Introduction1

2.0 Best Practice Description.....1

3.0 Implementation Steps.....3

4.0 Benefits3

5.0 Resources Required3

6.0 Supporting Attachments / References.....3

7.0 Related Best Practices3

8.0 Acknowledgements.....4

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices”. Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

1.0 Introduction

In order to assemble C175 engine connecting rod, piston, and liner, Ferreyros has developed a tool to make the process easier and faster. Reference assembly procedure KENR6052.

2.0 Best Practice Description

Since tool prints are not currently available, the following photos show the fixture and process.



Lifting bolts to handle the connecting rod.



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Assembly Tool for C175 Engine Connecting Rods,
Pistons and Liners

DATE
2/18/2015

CHG
NO
00

NUMBER
1206-4.03-1278

Use lifting bolts to lift connecting rod and piston into position over the liner.



The spacer shown below is fitted inside the liner to limit the movement of the piston inside the liner during assembly.



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Assembly Tool for C175 Engine Connecting Rods,
Pistons and Liners

DATE
2/18/2015

CHG
NO
00

NUMBER
1206-4.03-1278

Handle is in the space is for easy removal. Once removed, the 322-3564 puller group is attached and the liner pack is ready to install in the cylinder block.



3.0 Implementation Steps

Design a tool.

4.0 Benefits

- More efficient
- Improved technician comfort

5.0 Resources Required

Minimal expense to fabricate the tool

6.0 Supporting Attachments / References

- Assembly procedure KENR6052

7.0 Related Best Practices

None

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Assembly Tool for C175 Engine Connecting Rods,
Pistons and Liners

DATE
2/18/2015

CHG
NO
00

NUMBER
1206-4.03-1278

8.0 Acknowledgements

The idea for this Best Practice belongs to:
Franklin Llanos Hinostroza
Ferreyros SAA

This Best practice was written by
Pablo Alcántara Michuy
Ferreyros S.A.A.
pablo.alcantara@ferreyros.com.pe

This Best practice was revised by:
Aninu Mitacc Vizcardo
Ferreyros S.A.A.
aninu.mitacc@ferreyros.com.pe

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Assembly Tool for C175 Engine Connecting Rods,
Pistons and Liners

DATE
2/18/2015

CHG
NO
00

NUMBER
1206-4.03-1278