



DEALER BEST PRACTICE SERIES

Floor Mounted Cooler
Assembly Fixtures

Application Maintenance Site Management **Component Rebuild** Safety MARC Management

Floor Mounted Cooler Assembly Fixtures0

1.0 Introduction1

2.0 Best Practice Description.....1

3.0 Implementation Steps2

4.0 Benefits.....2

5.0 Resources Required2

6.0 Supporting Attachments / References2

7.0 Related Best Practices3

8.0 Acknowledgements.....3

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices”. Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

1.0 Introduction

Most dealers perform fluid cooler disassembly and assembly on the floor or on a standard workbench. The common practice makes the work cumbersome and inefficient. This Best Practice is a very simple design Disassembly and Assembly stand. This adds efficiency, quality, and improved material handling to the fluid cooler rebuild process.

2.0 Best Practice Description



Fixtures set up in a CRC environment

This specialized CRC tooling was designed and fabricated by a dealer to improve safety, quality, and labor efficiencies in the assembly processes of the engine oil and aftercooler core assemblies. This fabricated tooling, consists of a floor mounted spindle base, a bearing support, a 30-degree interlock rotation table top and an assortment of adapters for the various coolers that are processed by the dealer. For cooler core assembly, the housing is placed and secured in the appropriate adapter and the technician can then start with the assemble process. The technicians have the ability to rotate the table and keep the assembly adjacent to the workbench and hand tools at all times.



Using fixtures for oil cooler and engine D&A


THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Floor Mounted Cooler Assembly Fixtures	DATE	CHG NO	NUMBER
	2/19/2015	01	1006-4.4-1023

3.0 Implementation Steps

1. Fabricate floor mounted stand with a rotating platform.



2. Fabricate saddles and tie downs to hold coolers.



4.0 Benefits

- Reduced potential for damage due to easier handling.
- D & A stands save 2 hours on a typical cooler or aftercooler rebuild.
- Improved accessibility for assembly and disassembly.

5.0 Resources Required

Fabrication materials for stands, tie downs, and saddles.

6.0 Supporting Attachments / References

None.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Floor Mounted Cooler Assembly Fixtures

DATE
2/19/2015

CHG
NO
01

NUMBER
1006-4.4-1023

7.0 Related Best Practices

None.

8.0 Acknowledgements

This *Component Rebuild Best Practice* was authored by:

Kiwi Haig

Component Rebuild Consultant

LACD

+56 55 200 947

Haig_Kevin@cat.com

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Floor Mounted Cooler Assembly Fixtures

DATE
2/19/2015

CHG
NO
01

NUMBER
1006-4.4-1023