



MINING DEALER BEST PRACTICE

Hydraulic Test Bench Reflector

Maintenance and
Repair

Application

Component Life
Management

Component
Renewal (CRC)

MARC
Management

Hydraulic Test Bench Reflector	1
1.0 Introduction	2
2.0 Best Practice Description.....	3
3.0 Implementation Steps	4
4.0 Benefits	4
5.0 Resources Required	4
6.0 Supporting Attachments / References	4
7.0 Related Best Practices.....	4
8.0 Acknowledgements	4

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices.” Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

April 2021
4.03-210413-1

1.0 Introduction

Whilst carrying out a Hydraulic Test process, the recommended oil leak detection method is to use a dye that glows bright green under ultraviolet light. The dye will show the specific leak path of the oil when a black light is used. The dye is not visible in the oil under normal light. After normal testing is completed, an oil leakage inspection is carried out in the dark while the component is on the test unit but not working.


Since the oil leakage testing is carried out in darkness, work area around the component is not clear and can create a trip and collision hazard.



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Hydraulic Test Bench Reflector	DATE	CHG NO	NUMBER
	04/13/2021	00	4.03-210413-1

2.0 Best Practice Description

In order to clearly identify the work area during darkness, the test bench area is covered in phosphorus tape with increased caution symbols at our test area. By this way even in darkness the warning bands can be seen. The work area most likely to become oily is covered with non-slip floor paint.



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Hydraulic Test Bench Reflector	DATE 04/13/2021	CHG NO 00	NUMBER 4.03-210413-1

3.0 Implementation Steps

- Outline work area with phosphorus band.
- Cover work area with non-slip paint.

4.0 Benefits

1. Work area as walkway more visible
2. Removes slip hazard

5.0 Resources Required

- Non-slip Floor paint :150 Euro
- Phosphorous reflective tape
- Labor: 8 hours

6.0 Supporting Attachments / References

None

7.0 Related Best Practices

None

8.0 Acknowledgements

This Best Practice was written by:
Mustafa Tuzcu
CRC Engineer Intern
Borusan Makina ve Güç Sistemleri

This Best Practice designed by:
Aycan Ulu
CRS Workshop Engineer
Borusan Makina ve Güç Sistemleri

Project and Best practice supported by:
Ömer Emre Demirkale
CRC Manager
Borusan Makina ve Güç Sistemleri

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Hydraulic Test Bench Reflector	DATE 04/13/2021	CHG NO 00	NUMBER 4.03-210413-1