



BEST PRACTICE SERIES

Installation Valve Guides Assembly – C175

Maintenance and Repair Application Component Life Management Component Renewal (CRC) MARC Management

Installation Valve Guides Assembly – C175.....1

1. Introduction2

2. Best Practice Description2

3. Implementation Steps3

4. Benefits4

5. Resources Required4

6. Supporting Attachments / References4

7. Related Best Practices.....4

8. Acknowledgements.....5

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices”. Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

August 19
4.03-190214-01

1. Introduction

In the C175 models, the KENR6052 assembly manual indicates that the valve guides are installed one at a time in the cylinder head. This is done by using the valve guide driver 283-0052 and a suitable hammer. The proposed tool described in this best practice has been designed to install the 4 valve guides simultaneously, while still keeping installation efforts to a minimum.

2. Best Practice Description

This tool will be able to install all 4 valve guides all at once, thus decreasing the time to complete the task. It also makes the task more efficient and easier to complete. To install, the guides must be centered on the cylinder head, and an appropriate press must be used to install the valve guides themselves. Implementation steps and drawings are shown below.



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Installation Valve Guides Assembly – C175


DATE
8/1/2019

CHG
NO
00

NUMBER
4.03-190214-01

3. Implementation Steps

Manufacture tool according to the dimensions of cylinder head.




THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Installation Valve Guides Assembly – C175

DATE
8/1/2019

CHG
NO
00

NUMBER
4.03-190214-01



4. Benefits

- Increases safety by minimizing the risk of damage to hands
- Minimizes the efforts in the installation

5. Resources Required

- Expense to fabricate the tool \$ 415

6. Supporting Attachments / References

None

7. Related Best Practices

None

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Installation Valve Guides Assembly – C175

DATE
8/1/2019

CHG
NO
00

NUMBER
4.03-190214-01

8. Acknowledgements

This Best Practice was written by:

Pablo Alcántara Michuy
Ferreyros S.A.

The idea for this Best Practice belongs to:

Alexander Aranda Abanto
Ferreyros S.A.

This Best Practice was revised by:

Aninu Mitacc Vizcardo
Ferreyros S.A.

aninu.mitacc@ferreyros.com.pe

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Installation Valve Guides Assembly – C175

DATE
8/1/2019

CHG
NO
00

NUMBER
4.03-190214-01