



MINING DEALER BEST PRACTICE

Upgraded C175 Connecting Rod Measurement Method

Maintenance and
Repair

Application

Component Life
Management

Component
Renewal (CRC)

MARC
Management

Upgraded C175 Connecting Rod Measurement Method	1
1.0 Introduction	2
2.0 Best Practice Description	2
3.0 Implementation Steps	3
4.0 Benefits	4
5.0 Resources Required	4
6.0 Supporting Attachments / References	4
7.0 Related Best Practices	8
8.0 Acknowledgements	8

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices.” Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

December 2021
4.03-211216-1

1.0 Introduction

This upgrade improves safety and provides an ergonomically improved method for rod measurements using Mahr Connecting Rod Bend and Twist Measurement System -DFM050918-1.

2.0 Best Practice Description

This upgrading method uses a pneumatic system for positioning the rod on the Mahr Connecting Rod Bend and Twist Measurement System -DFM050918-1.


Procedure:

1. Check the vertical and horizontal movements of the pneumatic system.
2. Put the connecting rod on the base and move it vertically to locate the rod and then move it horizontally to the measuring equipment (Mahr Connecting Rod Bend and Twist Measurement System -DFM050918-1).
3. Evaluate and record the measurement.

Remove the connecting rod using the horizontal and vertical base.

3.0 Implementation Steps

- a) Design of the pneumatic system for handling connecting rod



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Upgraded C175 Connecting Rod Measurement Method	DATE 12/16/2021	CHG NO 00	NUMBER 4.03-211216-1
---	--------------------	-----------------	-------------------------

Important:

The pneumatic system must be set on a table near the Mahr Connecting Rod Bend and Twist Measurement System -DFM050918-1 as shown in the image below:



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Upgraded C175 Connecting Rod Measurement Method	DATE 12/16/2021	CHG NO 00	NUMBER 4.03-211216-1
---	--------------------	-----------------	-------------------------

4.0 Benefits


- Reduced fatigue and improved ergonomics during the measurement of the connecting rod
- Reduce the human physical effort for moving the 797F connecting rods during the measurement process in the Mahr Rod Bend and Twist Measurement System tool - DFM050918-1

5.0 Resources Required

- Pneumatic system components per drawings
- Table design per drawings
- Mahr Connecting Rod Bend and Twist Measurement System -DFM050918-1

6.0 Supporting Attachments / References

- Video attached





THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Upgraded C175 Connecting Rod Measurement Method

DATE
12/16/2021

CHG
NO
00

NUMBER
4.03-211216-1





THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Upgraded C175 Connecting Rod Measurement Method

DATE
12/16/2021

CHG
NO
00

NUMBER
4.03-211216-1





THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Upgraded C175 Connecting Rod Measurement Method

DATE
12/16/2021

CHG
NO
00

NUMBER
4.03-211216-1



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Upgraded C175 Connecting Rod Measurement Method

DATE
12/16/2021

CHG
NO
00

NUMBER
4.03-211216-1

7.0 Related Best Practices

None

8.0 Acknowledgements

This Best Practice was written by:

Olger Quezada Mendoza
Fernando Moreno Villaizan

This Best Practice was revised by:

Aninu Mitacc Vizcardo
aninu.mitacc@ferreyros.com.pe

This Best Practice procedure was developed by:

Olger Quezada Mendoza
Jack Solier Garcia
Carlos Vasquez Auqui
Oscar Rios Dillerva

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Upgraded C175 Connecting Rod Measurement Method	DATE 12/16/2021	CHG NO 00	NUMBER 4.03-211216-1