



DEALER BEST PRACTICE SERIES

Fabricated Track Stand for Weld Repairs of D10R Frames

Maintenance and Repair Application Component Life Management Component Renewal (CRC) MARC Management

Fabricated Track Stand for Weld Repairs of D10R Frames0

1.0	Introduction	1
2.0	Best Practice Description.....	1
3.0	Implementation Steps.....	2
4.0	Benefits	3
5.0	Resources Required	3
6.0	Supporting Attachments / References.....	3
7.0	Related Best Practices	4
8.0	Acknowledgements.....	4


DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices”. Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

1.0 Introduction

A fabricated stand has been designed for use in the Ferreyros S.A. weld shop in the repair of D10R rear frames. The stands makes it easier, safer, and much more efficient to align the frame tube and support for weld repairs. Stand drawing are not available, but photos are provided to show the design concept.

2.0 Best Practice Description

The fabricated fixture consists of two stands mounted on a level platform, one to mount the frame tube and the other for the support. The two stands are designed to center the tube to the support for welding the tube to the support. (See picture 1).



Picture 1. Frame Rear D10R

To repair cracks between the tube and the support (zone A in photo), the tube must be correctly aligned to the support.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Fabricated Track Stand for Weld Repairs of D10R
Frames

DATE
2/20/2015

CHG
NO
00

NUMBER
1210-4.04-1289

3.0 Implementation Steps

- Fixture is fabricated as shown below.
- Part 1 of the fixture is to hold the tube in the correct position for alignment. Mounting locations are as shown.



Picture 2. Centered tube on the part 1 of assembly device

- Part 2 of the fixture holds the support. Mount locations are as shown.



Picture 3. Centered tube on the part 1 of assembly device

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR


Fabricated Track Stand for Weld Repairs of D10R
Frames

DATE
2/20/2015

CHG
NO
00

NUMBER
1210-4.04-1289

- Weld the union “A” between the tube and the support.



Picture 4. Welding the union “A”

4.0 Benefits

- Time required to set up and align the tube to the support is reduced by 70%.
- Parts alignment is very precise.
- Time required to perform the welding is significantly reduced.
- Weld quality is easier to control.
- Material handling is easier to perform.

5.0 Resources Required

- Fabrication shop

6.0 Supporting Attachments / References

None

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Fabricated Track Stand for Weld Repairs of D10R
Frames

DATE
2/20/2015

CHG
NO
00

NUMBER
1210-4.04-1289

7.0 Related Best Practices

None

8.0 Acknowledgements

This Best Practice was written by:

Name Frank Córdova R.

E mail frank.cordova@ferreyros.com.pe

Recognition:

Team: Miguel Mauriola / Operations Support Chief
María Ávila / Welding Chief
Alex Alaya, Cesar Vidangos / Welding Supervisor
Sponsor: Rodolfo Gerstein / Manager Machine Shop

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Fabricated Track Stand for Weld Repairs of D10R Frames	DATE 2/20/2015	CHG NO 00	NUMBER 1210-4.04-1289
---	-------------------	-----------------	--------------------------