



MINING DEALER BEST PRACTICE

Basket to Storage Caps C175-16 and C175-20

Maintenance and
Repair

Application

Component Life
Management

Component
Renewal (CRC)

MARC
Management

Basket to Storage Caps C175-16 and C175-20.....	1
1.0 Introduction.....	2
2.0 Best Practice Description	2
3.0 Implementation Steps.....	4
4.0 Benefits	4
5.0 Resources Required.....	4
6.0 Supporting Attachments / References	5
7.0 Related Best Practices	5
8.0 Acknowledgements	6

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices.” Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

December 2022
4.03-221209-1

1.0 Introduction

This improvement contributes to a safer and more efficient washing and storage process for C175-16 and C175-20 engine mounts and accessories.

2.0 Best Practice Description

The improvement consists of implementing a basket with exclusive divisions and compartments for each of the parts that make up the C175 engine mount assembly: mounts, plates, studs, bolts and nuts. This allows that none of the parts placed in it suffer any kind of damage by bumping into each other during washing and/or storage.



Figure 1: How mounts and their accessories used to be stored BEFORE

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Basket to Storage Caps C175-16 and C175-20	DATE 12/9/2022	CHG NO 00	NUMBER 4.03-221209-1



Figure 2: New shape and arrangement of mounts and accessories NOW

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Basket to Storage Caps C175-16 and C175-20	DATE 12/9/2022	CHG NO 00	NUMBER 4.03-221209-1

3.0 Implementation Steps

Basket design for C175-16/20 engine beds.



4.0 Benefits

- Eliminate the danger or risk of stored parts bumping and damaging each other.
- Store in a safer, more orderly, and efficient manner the parts that constitute the C175 engine mount assembly: mounts, plates, studs, bolts and nuts.


5.0 Resources Required

- Expense to fabricate the basket US\$ 380.00

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Basket to Storage Caps C175-16 and C175-20	DATE 12/9/2022	CHG NO 00	NUMBER 4.03-221209-1

6.0 Supporting Attachments / References

- Drawing appendix



7.0 Related Best Practices

None

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Basket to Storage Caps C175-16 and C175-20	DATE 12/9/2022	CHG NO 00	NUMBER 4.03-221209-1

8.0 Acknowledgements

This Best Practice was written by:
Carlos Vasquez Auqui, Jose Vives Martinez and Fernando Moreno Villaizan.

This Best Practice was revised by:
Aninu Mitacc Vizcardo
aninu.mitacc@ferreyros.com.pe

This Best Practice procedure was developed by:
Carlos Vasquez Auqui

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Basket to Storage Caps C175-16 and C175-20	DATE 12/9/2022	CHG NO 00	NUMBER 4.03-221209-1